

Docket No. 272 – Development and Management Plan Inspection

The Connecticut Light and Power Company Certificate of Environmental Compatibility and Public Need for the construction of a new 345-kV electric transmission line and associated facilities between Scovill Rock Switching Station in Middletown and Norwalk Substation in Norwalk, Connecticut, including reconstruction of portions of existing 115-kV and 345-kV electric transmission line, the construction of Beseck Switching Station in Wallingford, East Devon Substation in Milford, (and Singer Substation in Bridgeport), modifications at Scovill Rock Switching Station and Norwalk Substation, and the reconfiguration of certain interconnections.

Segment 2b Inspection

Date: June 1, 2007

Inspector: Lee Curtis

Location: Segment 2b – Cheshire/Hamden Town Line to East Devon Substation

Rainfall: 0.21” of precipitation was recorded in the week since the last inspection (NOAA data at New Haven, CT).

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Access roads and adjacent roadways</p> <p>Orange, CT Ridge Rd, Rolling Ridge Rd, Sunset Dr, Hall Dr, Edward Ct, Racebrook Rd, Overland Dr, Hunting Hill Pl, Harbor View, Saddle Ridge, Route 152, Treat Lane, Pine Tree Dr, Lambert Rd, Russell Ave, and Hunting Hill Rd, Dogwood Road, Dogburn Rd, and Route 34</p> <p>All access roads (above)</p>	<p>Clearing/road construction appears to be complete in these sections at this time. 6/1/07</p>	<p>Continue to monitor. Install mats if necessary. 6/1/07</p>	<p>Not Applicable (NA)</p>
	<p>Mats remain at the wetland crossings in these sections. 6/1/07</p>	<p>Continue to monitor. 6/1/07</p>	<p>NA</p>
	<p>Efforts to restore portions of the ROW previously disturbed for access were noted off Ridge Road this week. 6/1/07.</p>	<p>NA</p>	<p>NA</p>
	<p>Stone pads remain in place at all entrances to access roads. Sediment tracking was not an issue this week. 6/1/07</p>	<p>Continue to monitor for sediment tracking. Sweep roadways as necessary. 6/1/07</p>	<p>NA</p>
	<p>“Silt saks” (or similar) remain intact within catch basins in the vicinity of the constructed access roads. Silt sak fabric was pulled over the curb drop inlet at those catch basins located immediately adjacent to the constructed access roads. 6/1/07</p>	<p>Continue to monitor and evaluate methods to protect the curb drop inlet and prevent sedimentation as needed. See Erosion Control Section for more detail. 6/1/07</p>	<p>Needs regular attention</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Milford, CT Fresh Meadow Road/West River Street, Eisenhower Park, East Rutland Ave, Naugatuck Ave, Caswell Street, Wheelers Farm Road, Plains Road to Oronoque Rd, Lexington Lane, Woodruff Road, and Route 121</p>	<p>Clearing and access road construction appears to be complete in these sections at this time. 6/1/07</p> <p>Two new culverts were installed at the entrance of the access road off West River Street last week. 6/1/07</p>	<p>Continue to monitor and add controls as necessary. See EC section. 6/1/07</p> <p>Continue to monitor and add controls as necessary. 6/1/07.</p>	<p>CB controls in place. Improve as necessary.</p> <p>Additional culverts were installed within the access road to control water flow.</p>
<p>Woodbridge, CT Pease Road, Salem Road, Rimmon Road (west), Woodbine Rd, Manville Rd, Clark Street, Brookwood and Cowpath Lane, and SCRRWA (Glen Dam), JCC and B'Nai Jacob, Oak Lane Country Club</p>	<p>Clearing and access road construction appear to be complete in these sections at this time. No active work was noted. Sediment tracking was not an issue this week. 6/1/07</p>	<p>Continue to monitor. Sweep roadway as needed. 6/1/07</p>	<p>NA</p>
<p>Center Road (east)</p>	<p>A stone access road was constructed here last week. 6/1/07</p>	<p>NA</p>	<p>NA</p>
<p>Bethany, CT Morris to Hatifeld and Downs Road (to West Todd, Hamden)</p>	<p>Access road construction continues in these sections. 6/1/07</p>	<p>Continue to monitor and add controls as necessary. See EC Section. 6/1/07</p>	<p>NA</p>
<p>Hamden, CT West Todd Street and Tom Swamp Rd/Arrow Rd</p>	<p>Access road construction appears to be complete in this section. Culverts, water bars, and drainage swales are in place. 6/1/07</p>	<p>Continue to monitor and add controls as necessary. See EC Section. 6/1/07</p>	<p>NA</p>
<p>115-kV underground transmission line</p>	<p>The access road adjacent to the catch basin is stabilized with stone. 6/1/07</p>	<p>Monitor during next large rain event. Curb inlet protection may be needed. 6/1/07.</p>	<p>Monitor during next large rain event</p>
<p>Foundation and site construction Orange, CT Sunset Dr, Overland Dr, Route 152, Ridge Rd, Edward Ct, Racebrook Rd, Hall Dr, and Russell Ave, Rolling Ridge Rd, Treat Lane, Pine Tree Dr, Dogwood Rd, Lambert</p>	<p>Foundation work appears to be complete in these sections at this time. Timber mat and stone crane pads remain in place. Structure installation continues. 6/1/07</p>	<p>See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Rd, Saddle Ridge Rd, Hunting Hill Rd and Place, and Dogburn Road</p> <p>Dogburn to Route 34 and Route 34 west</p>	<p>Foundation drilling/pouring continues in this section. Stone and timber mat crane pads remain in place. 6/1/07</p>	<p>Continue to monitor. 6/1/07</p>	<p>NA</p>
<p>Milford, CT</p> <p>West River Street</p>	<p>Foundation drilling/pouring continues at the first structure location of West River Street. 6/1/07.</p>	<p>None at this time. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>Plains Road, Caswell Street, and Shelland Street</p>	<p>Foundation drilling/pouring continues along Shelland Street toward Caswell. 6/1/07.</p>	<p>None at this time. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>Eisenhower park, Lexington Lane, East Rutland Rd, Wheelers Farm Rd, Woodruff Rd, Fresh Meadow Road (west), and Route 121</p>	<p>Foundation work appears to be complete in these sections at this time. Structure installation continues in some locations. 6/1/07</p>	<p>None at this time. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>Naugatuck Ave and Plains Road to Oronoque Rd.</p>	<p>Foundation drilling/pouring has not yet begun, but stone and timber mat crane pads are in place. 6/1/07</p>	<p>None at this time. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>Woodbridge, CT</p> <p>Pease Road</p>	<p>Foundation drilling/pouring is complete at the first structure location. 6/1/07.</p>	<p>Continue to monitor. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>SCCRWA (Glen Dam Reservoir) Dillon Rd to Morris Rd, Cowpath Lane</p>	<p>Foundation drilling/pouring continues in these sections. Stone crane pads remain. 6/1/07</p>	<p>Continue to monitor. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>
<p>Salem Rd, Brookwood Dr, JCC, Manville Rd and Rimmon Rd, Center Road</p>	<p>Foundation work has not yet begun, but stone pads have been constructed in these sections. Timber mat crane pads were installed in the wetland areas off Rimmon Rd, Salem Rd and Manville</p>	<p>Continue to monitor. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Bethany, CT Morris (Hamden) to Hatfield, Downs Road to West Todd (Hamden)</p> <p>Hamden, CT Tom Swamp/Arrow Road and West Todd Street</p>	<p>Salem Rd and Manville Rd. 6/1/07.</p> <p>Foundation work has not yet begun, but crane pads have been constructed in these sections. 6/1/07</p> <p>Foundation work has not yet begun, but crane pads have been constructed in these sections. 6/1/07</p>	<p>Continue to monitor. 6/1/07</p> <p>Continue to monitor. See Dewatering and EC Sections. 6/1/07</p>	<p>NA</p> <p>NA</p>
<p>Erosion and sediment controls</p> <p>All work areas</p> <p>Orange, CT Ridge Road</p> <p>Route 34/Dogburn Road</p> <p>Russell Ave</p> <p>Russell Drive, Sunset Dr, Overland Dr, and Treat Lane</p>	<p>Roots have been retained in most cleared areas to maintain some soil stability. Crews have made good efforts to temporarily stabilize most disturbed areas with hay mulch. When work occurs in or adjacent to wetlands, timber mat crane pads are in place with erosion controls along the edge. 6/1/07.</p> <p>Efforts to restore portions of the disturbed ROW were noted here this week. 6/1/07.</p> <p>Filter socks, silt fence and/or haybales are in place along the access road and crane pads. Hay mulch continues to be applied to disturbed slopes and soil. Spoil piles have been placed on liners and covered with plastic 6/1/07</p> <p>Some ruts remain within the ROW here. Soils are too soft to support equipment. 11/20-6/1/07.</p> <p>All spoil piles are on liners and remain partially covered with plastic in these sections. The plastic covering</p>	<p>None. Continue to temporarily stabilize disturbed soils as necessary. 5/17/07</p> <p>NA</p> <p>Continue to monitor and maintain controls as necessary. 6/1/07</p> <p>Stabilize soil (tracks) as it becomes necessary. 11/20-6/1/07</p> <p>Adjust plastic on spoil piles as needed. 6/1/07.</p>	<p>NA</p> <p>NA</p> <p>Mulch is being applied to disturbed soils for temporary stabilization. Spoil piles have been placed on a liner and covered with plastic.</p> <p>NA at this time</p> <p>Needs proactive attention when feasible.</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Rolling Ridge Road and Hall Dr	should be adjusted in some areas. 2/16-6/1/07 The spoil piles here remain uncovered but appear to be contained on site. 2/16-6/1/07	Inactive piles should be covered with plastic when feasible. 2/16-6/1/07	Needs proactive attention when feasible
Racebrook Rd.	Silt fence is need of repair along the edge of the crane pad at the wetland off Racebrook Rd. 3/23-6/1/07	Repair and maintain controls as necessary. 6/1/07	Needs some attention
Edward Court	Some of the mulch was washed downslope at the disturbed area, but the haybales and silt sak continue to protect the catch basin here. 2/22-6/1/07	Continue to monitor. Additional stabilization measures may be necessary here. Re-apply mulch in this area if needed. 2/22-6/1/07	Needs proactive attention when feasible
Hunting Hill Road	The majority of the silt fence remains intact at the matted wetland here. Snow was piled on the fence near the southeastern corner of the mat the week of 3/23. 6/1/07	Continue to monitor and maintain as necessary. 3/23- 6/1/07	Needs proactive attention when feasible
Milford, CT			
Eisenhower Park	Silt fence was repaired at structure #3840. 6/1/07.	Continue to monitor and maintain as necessary. 6/1/07.	Silt fence was repaired.
West River Street	Portions of the wetland have been disturbed outside of the crane pad work area in some locations. Filter socks are in place along the crane pad and along the outer edge of disturbance. 6/1/07	All equipment should remain within the limits of the crane pad/work area and wetland areas restored when feasible. Continue to monitor and maintain as necessary. 6/1/07	Controls are in place along the outer edge of disturbance (new) to prevent potential harm to the adjacent, undisturbed wetland. Wetland areas should be restored when feasible.
Route 121	Silt fence check dams are in disrepair due previous storm events. The silt fence at the wetland edge is also in need of repair, but this area appears to be stabilizing with	Continue to monitor and maintain as necessary. 6/1/07	Silt fence needs attention

Areas of Inspection	Observation	Recommended Action	Corrected Action
Wheeler's Farm Road	<p>be stabilizing with vegetation (east). 6/1/07</p> <p>Snow and sediment were piled on the silt fence due to snow clearing (east) 3/19-5/3/07. Silt fence may need to be extended near the wetland, downgradient of the dewatering area here. The stockpile near the road remains uncovered. 4/13-6/1/07</p>	<p>Continue to monitor. Silt fence needs repair. Any remaining sediment needs to be pulled back to the work side of the fence. See Dewatering Section. 3/23-6/1/07. All inactive stockpiles should be covered. 6/1/07</p>	<p>Silt fence and stockpiles need attention</p>
Woodbridge, CT SCCRWA (Glen Dam Reservoir) Dillon Rd to Morris Rd	<p>Increased grass growth was noted in the recently restored upland area, just outside the access gate. 6/1/07</p>	<p>Continue to monitor for stabilization. Re-seed if necessary. 6/1/07</p>	<p>Increased grass growth noted</p>
Pease Road	<p>The spoil pile from foundation drilling was placed on a plastic liner here (noted last week). 6/1/07</p>	<p>Cover the pile with plastic if necessary. 6/1/07</p>	<p>Spoil pile was placed on a plastic liner</p>
JCC	<p>Silt fence remains along the stream and wetland area. Hydro-seed was applied to the remaining disturbed areas. 6/1/07</p>	<p>Continue to monitor for stabilization and adjust controls as necessary. 6/1/07</p>	<p>Hydro-seed was applied to the remaining disturbed areas</p>
B'Nai Jacob	<p>Mats were used in the wetland where necessary. However, ruts were noted in the upland areas of the ROW here. Soils were too soft to support equipment. Stormwater continues to flow within the large rut located along the edge of ROW. 4/27-6/1/07</p>	<p>Stabilize soil (tracks) as soon as practicable. Use mats where necessary to reduce overall soil disturbance. 6/1/07</p>	<p>Needs attention</p>
Bethany, CT Morris (Hamden) to Hatfield and Downs Rd	<p>Silt fence/haybales continue to be installed along portions of the access road and along wetland areas as work progresses. 6/1/07</p> <p>A temporary timber mat</p>	<p>Continue to monitor and adjust controls as work continues here. 6/1/07</p> <p>Continue to monitor and</p>	<p>Controls are being installed as work progresses</p> <p>A temporary bridge and</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Hamden,CT</p> <p>Tom Swamp Rd/Arrow Rd</p> <p>West Todd Street</p>	<p>bridge is in place at the first stream/wetland crossing within the ROW accessed from Route 69. Silt fence and haybales were installed at the crossing and mulch was applied to the disturbed stream banks. 6/1/07</p>	<p>adjust controls as necessary. 6/1/07</p>	<p>erosion controls are in place at the stream crossing. Mulch was applied to disturbed soil.</p>
	<p>Spoil was removed from the silt fence and erosion controls repaired. 6/1/07</p>	<p>Continue to monitor and adjust controls as necessary. 6/1/07</p>	<p>Spoil was removed from silt fence and controls repaired.</p>
	<p>Temporary culverts are in place within the access roads here. Stone sediment traps and haybale check dams remain at the outlets. Sediment accumulation was noted within the stone trap at the 2nd culvert outlet off Tom Swamp (east). 3/30-6/1/07</p>	<p>Continue to monitor and add/maintain controls as necessary. Remove sediment to restore capacity and function here when needed. 3/30-6/1/07</p>	<p>Needs proactive attention.</p>
	<p>Controls are in place at the water bar and culvert outlets but sediment from past rain events remains in the adjacent upland areas. 6/1/07</p>	<p>Continue to improve controls at the water bar outlets and stabilize remaining sediment to prevent potential sedimentation off site. 6/1/07</p>	<p>Needs proactive attention</p>
	<p>In approximately three areas, stormwater pooled along the perimeter controls and filtered though as concentrated flow off the ROW (4/27/07). This only occurs during large rain events and wetland resource areas were not affected by this off site flow. 6/1/07</p>	<p>Investigate additional solutions to prevent stormwater conveyances off site. Although good efforts were made to control stormwater flow, continue to improve the on-site containment. 6/1/07.</p>	<p>Good efforts were made but needs additional attention</p>
<p>A gap was noted between the haybales of the check dam at the culvert outlet off West Todd (east). Some sediment accumulation from a</p>	<p>Repair and reinforce the controls. Carefully remove sediment from the wetland if it is greater than 2" in depth. 4/20-5/10/07</p>	<p>Needs attention</p>	

Areas of Inspection	Observation	Recommended Action	Corrected Action
115-kV underground transmission line	<p>accumulation from a previous rain event was noted in the adjacent wetland.</p> <p>The overhead access road has been stabilized with stone. Silt fence and haybales remain at the intersection of the access road and Old Lane Rd. 6/1/07</p>	<p>5/10/07.</p> <p>Monitor during large rain events to confirm curb inlet protection is no longer needed. 6/1/07</p>	<p>Monitor during next large rain event</p>
<p>Inland Wetland and Watercourse encroachment and mitigation</p> <p>Orange, CT</p> <p>Sunset Drive, Pine Tree Rd (east), and Lambert Rd, Russell Ave, Racebrook Rd, and Route 34</p> <p>Hunting Hill Rd & Milford, CT Rt 121</p> <p>West River Street</p> <p>West River Street and Eisenhower Park</p> <p>East Rutland Road (western access point)</p>	<p>The ACOE permit is in hand and approved wetland work continues. 6/1/07</p> <p>Timber mat crane pads remain at the wetland areas here. A stone wetland crossing is in place at Lambert Rd. Approved foundations were installed in the wetland at both Russell Ave and Racebrook Rd. 6/1/07</p> <p>Timber mat crane pads remain adjacent to/in wetlands in these sections. 6/1/07</p> <p>Portions of the wetland have been disturbed outside of the crane pad work area in some locations. Controls are in place. 6/1/07</p> <p>A stone access road was constructed within the wetland accessed from West River Street. Timber mat crane pads remain within the wetland areas in these sections. 6/1/07</p> <p>A stone access road remains at the wetland</p>	<p>Follow general guidelines of the permit whenever work in wetlands occurs. 6/1/07</p> <p>Continue to monitor. 6/1/07</p> <p>Continue to monitor. Install controls as necessary. 6/1/07</p> <p>Continue to monitor. See EC Section. 6/1/07</p> <p>Continue to monitor. Adjust controls as necessary. 6/1/07</p> <p>Continue to monitor. Install controls as</p>	<p>NA</p> <p>NA at this time</p> <p>NA at this time</p> <p>NA</p> <p>NA at this time</p> <p>NA at this time</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Woodbridge, CT Pease Road/JCC/B'Nai Jacob</p>	<p>crossing off East Rutland. An existing stone culvert was already in place here. 6/1/07</p> <p>Mats remain in the potential wetland area near Pease Road. 6/1/07</p> <p>The wetland areas near the JCC and B'Nai Jacob have been cleared as a result of the permitted re-location of the ROW. Stone access roads were constructed through portions of the wetlands in these sections. 6/1/07</p>	<p>necessary. 6/1/07.</p> <p>Continue to monitor. The contractor states that this wetland was removed from the most recent version of the D&M plan, but flags were staked in the field. 6/1/07</p> <p>Continue to monitor. Adjust controls as necessary. 6/1/07.</p>	<p>NA at this time.</p> <p>NA at this time</p>
<p>Cow Path Lane, Salem Rd, Rimmon Rd, and Manville Rd</p>	<p>Timber mat crane pads remain within the wetlands in these sections. 6/1/07</p>	<p>Continue to monitor. 6/1/07</p>	<p>NA at this time</p>
<p>Bethany, CT Morris to Hatfield</p>	<p>Clearing for access and vegetative management was noted in the wetland areas in this section.</p>	<p>Continue to monitor. 6/1/07</p>	<p>NA at this time</p>
<p>Hamden,CT Tom Swamp/ Arrow Road</p>	<p>Boulders and silt fence are in place across the ATV path in an effort to prevent further (non project related) wetland disturbance in the Jepp Brook area. 3/30-6/1/07</p>	<p>None at this time. 6/1/07.</p>	<p>NA at this time</p>
<p>115-kV underground transmission line</p>	<p>The overhead access road was stabilized, but the water within the wetland remains turbid. 6/1/07</p>	<p>Monitor during next large rain event. Evaluate sediment accumulation within adjacent wetland. Carefully remove sediment from wetland if it is greater than 2" in depth. 6/1/07</p>	<p>Needs evaluation</p>
<p>State species of concern, threatened</p>	<p>According to the D&M plan, Wood Turtles are</p>	<p>Since wood turtles are no longer dormant and</p>	<p>Contractors stated that field crews have</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
and endangered species.	known to occur near the Wepawaug River at Eisenhower Park. Active work is currently occurring in this area. 4/5-6/1/07	active work is occurring here, field crews should receive the appropriate training in the recognition and removal of individual wood turtles from the construction area. 4/5-6/1/07 “Sweeps” should be performed before constructing access roads and stone pads and before the installation of timber mats in this area. 4/5-6/1/07.	received the appropriate training and sweeps are occurring.
<p>Vegetative clearing or stabilization</p> <p>All active roads</p> <p>Orange, CT</p> <p>Orange Center Rd, Sunset Dr, Ridge Rd, Russell Ave, Hall Drive, Rolling Ridge Rd, Overland Dr, Hunting Hill Place, Lambert Rd, and Route 34</p> <p>Milford , CT</p> <p>East Rutland Rd, Naugatuck Ave, Caswell Street, Wheelers Farm Road, Plains Road to Oronoque Rd, Lexington Lane, Woodruff Road, and Route 121, and West River Street</p>	<p>Vegetative clearing was noted within the ROW. Most species were invasive and were removed. “Hedgerows”, including cedars and similar short tree species were retained along the ROW where feasible. Select shrubs, especially those adjacent to wetlands, also remain in most areas. 6/1/07</p> <p>Wood chips are in place along the upland portions of the cleared ROW in these sections. 6/1/07</p> <p>Wood chips near the cul-de-sac off Hunting Hill Place are currently piled in a “depression” in the ROW and other piles were noted off Ridge Road and Route 152. 1/11-6/1/07</p> <p>Clearing appears to be complete in these sections at this time. 6/1/07</p>	<p>Continue to retain appropriate vegetation for stabilization. Retain as much vegetation as possible for screening. Confirm that clearing/cutting is limited only to areas defined in D&M plan. Provide as much buffer as possible for homeowners. 6/1/07</p> <p>Continue to maintain a depth of 3” or less so vegetative growth is not inhibited. 6/1/07</p> <p>Piles need to be either removed from the ROW or spread in appropriate upland areas to a depth of 3” or less. 1/11-6/1/07</p> <p>None at this time. 6/1/07</p>	<p>NA</p> <p>Wood chips were spread in appropriate locations.</p> <p>Needs attention when feasible.</p> <p>NA</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
<p>Woodbridge, CT B'Nai Jacob</p> <p>Pease Road/JCC Bypass, SCCRWA (Glen Dam Reservoir) Dillon Rd to Morris Rd Manville Road, Rimmon Rd (west), Salem Rd, Brookwood Dr and Cowpath Lane, Center Road</p> <p>Bethany, CT Morris to Hatfield,</p> <p>Downs Rd, Hoadley Rd, and Raccio Dr</p> <p>Hamden, CT Tom Swamp Rd/Arrow Rd, West Todd Street, Brooksvale Ave and Willow St</p>	<p>Major clearing has occurred in this section due to the relocation of the ROW here. 6/1/07</p> <p>Clearing appears to be complete in these sections at this time. 6/1/07</p> <p>Major clearing appears to be complete in these sections at this time. Small trees and shrubs were retained where feasible. 6/1/07</p> <p>Clearing appears to be complete in these sections at this time. 6/1/07.</p> <p>Clearing appears to be complete in these sections at this time. Small trees and shrubs were retained where feasible. 6/1/07</p>	<p>Continue to monitor. Add controls as necessary. 6/1/07</p> <p>None at this time. 6/1/07</p> <p>Continue to monitor. 6/1/07</p> <p>Continue to monitor. 6/1/07</p> <p>Continue to monitor. 6/1/07</p>	<p>NA</p> <p>Efforts were noted to retain shrubs and low growth.</p> <p>Efforts were noted to retain shrubs and low growth</p> <p>Efforts were noted to retain shrubs and low growth</p> <p>Efforts were noted to retain shrubs and low growth</p>
<p>Dewatering</p> <p>Orange, CT Route 34 and Dogburn Road (All other areas are inactive at this time)</p> <p>Woodbridge, CT Pease Rd/JCC, Manville Rd, Salem Rd, Brookwood Dr, and Cowpath Lane</p> <p>Milford, CT East Rutland (eastern access), Fresh Meadow Road, Route 121, Woodruff Rd, Naugatuck</p>	<p>Dewatering containment remain within the ROW in this section. This includes silt fence and haybale corrals and dewatering basins. 6/1/07</p> <p>Dewatering basins remain in place at the proposed drilling sites. 6/1/07</p> <p>Dewatering basins remain in place at new and proposed drilling sites. 6/1/07</p>	<p>Continue to monitor and adjust controls as necessary. 6/1/07</p> <p>Continue to monitor and adjust controls as necessary. 6/1/07</p> <p>Continue to monitor and adjust controls as necessary. 6/1/07</p>	<p>Dewatering areas installed proactively.</p> <p>Dewatering containment areas were installed proactively.</p> <p>Dewatering containment areas were installed proactively.</p>

Areas of Inspection	Observation	Recommended Action	Corrected Action
Ave Lexington Ln, Wheelers Farm Rd, Shelland Street (relocated), Caswell St, and Plains to Oronoque Rd. West River Street	Slurry from dewatering was pumped into containment bins within the ROW off West River St. 6/1/07	Continue to monitor and adjust controls as necessary. 6/1/07	Slurry from dewatering was pumped into containment bins to prevent potential damage to wetland areas here
Hamden and Bethany, CT Tom Swamp Rd/Arrow Rd and West Todd Street, Morris to Hatfield	Dewatering basins remain at new and proposed drilling sites. 6/1/07	Continue to monitor and adjust controls as necessary. 6/1/07	Dewatering containment areas were installed proactively.
Blasting	No blasting is proposed at this time. 6/1/07	None	NA
Spills, soils and material storage.	Contractor receiving yard is set up near Shelland St. in Milford. This also appears to be used for Segment 3 construction. 6/1/07	In general, store materials and equipment appropriately. Ensure that vehicles are equipped with spill kits. All construction vehicles should be parked at least 100 feet from a wetland or waterbody when feasible. 6/1/07	NA
Additional Observations	Non-project related activity was noted within the ROW off Sunset Dr. A trench was dug near the first structure and a pipe appears to have been installed to divert water from an unknown location. 1/18-5/17/07	Noted for the record. 1/18-5/17/07	NA

**Next likely scheduled
inspection:**

Thursday June 7, 2007

I have personally examined and am familiar with the information submitted in this document and all attachments and certify that based on reasonable investigation, including my inquiry of those individuals responsible for obtaining the information, the submitted information is true, accurate and complete to the best of my knowledge and belief, and I understand that any false statements made in this document or its attachments may be punishable as a criminal offense in accordance with Section 22a-6 under Section 53a-157 of the Connecticut General Statutes.

Field Inspector:

Lee Curtis, BSC Group



Route 69 (Bethany): Stone access road construction continues. Haybales and mulch continue to be installed/applied as work progresses.



Route 69: Silt fence, hay bales, and mulch are in place at the first stream crossing.



Route 69: Silt fence is in place along appropriate areas of the access Road.



Route 69: Mulch is in place on disturbed slopes



Center Road (Woodbridge): A stone access road was constructed here and hay mulch has been applied to disturbed slopes.



Route 34 (Orange): Drilling continues in this section. Erosion controls remain intact.



Ridge Road (Orange): Efforts to restore disturbed portions of the ROW were noted this week.



Eisenhower Park (Milford): Installation of structure #3839 was nearly complete at the time of inspection.



West River Street (Milford): Drilling continues within the wetland at the first structure off West River Street.



West River Street: Haybales and filter socks remain in place along the timber mat crane pad here.



West River Street: Hay mulch remains along disturbed areas.



West River Street: Portions of the wetland have been disturbed adjacent to the crane pads in some areas. Filter socks are in place along the pad and edge of disturbance.