



EAGLE
Environmental, Inc.



Hazardous Building Materials > Industrial Hygiene/IAQ > Environmental Assessments > Laboratory Services & Training

February 3, 2015

Mr. David Holmes
Capital Studio Architects
1379 Main Street
East Hartford, CT 06108

RE: Environmental Assessment Report
Department of Housing
CDBG-DR – Sandy Disaster Recovery Program
39 Attawan Avenue
Niantic, Connecticut
Application #1939
Eagle Project No. 14-028.12T10


Dear Mr. Holmes:


Please find the attached Environmental Assessment Report conducted at 39 Attawan Avenue located in Niantic, Connecticut (Site). The environmental assessment was originally performed in support of the planned renovations/repairs to the Site building under the State of Connecticut Department of Housing Community Development Block Grant – Disaster Recovery Program (Program). The initial assessment focused only on those areas of the building that are scheduled for renovation/repair work. Additional testing was performed per the request of the Architects and Department of Housing (DOH) to support the demolition of the building. The initial proposed scope of renovation/repair work was provided to Eagle Environmental, Inc. (Eagle) by Capital Studio Architects (CSA).

This assessment and report is intended to satisfy the review process of the National Environmental Policy Act (NEPA) Statutory Checklist Sections 13C (Lead-Based Paint), 13D (Asbestos), 13E (Radon) and 13F (Mold).

Please do not hesitate to contact us if you have any questions regarding the contents of this report.

Sincerely,
Eagle Environmental, Inc.


Report Prepared By:
Kristen Liljehult
Environmental Consultant II


Report Reviewed By:
Peter J. Folino
Project Manager

W:\Eagle\v\public\2014 Files\2014 Reports\Capital Studio Architects\Hurricane Sandy\39 Attawan Ave. - Niantic\39 Attawan Ave - Environmental Assessment Report.doc

8 SOUTH MAIN STREET, SUITE 3 • TERRYVILLE, CT 06786
PHONE (860) 589-8257 • FAX (860) 585-7034

TABLE OF CONTENTS

1. INTRODUCTION	2
1.1 INSPECTION AREA DESCRIPTION	2
2. SCOPE OF INSPECTION.....	2
2.1 ASBESTOS CONTAINING MATERIALS.....	2
2.2 LEAD-BASED PAINT	2
2.2.1 Lead Waste Characterization.....	4
2.3 RADON TESTING	4
2.4 MOLD INSPECTION.....	4
3. INSPECTION PROTOCOLS	4
3.1 ASBESTOS CONTAINING MATERIALS.....	4
3.1.1 Inspection.....	4
3.1.2 Bulk Sampling	4
3.1.3 Bulk Sample Analysis.....	5
3.2 LEAD-BASED PAINT	6
3.3 LEAD WASTE CHARACTERIZATION	6
3.3.1 Screen, Sample, and Segregate Method.....	6
3.3.2 Composite Sample and Demolish Method	7
3.4 RADON TESTING	7
3.5 MOLD INSPECTION.....	7
4. INSPECTION RESULTS	8
4.1 ASBESTOS CONTAINING MATERIALS.....	8
4.2 LEAD-BASED PAINT	9
4.2.1 Lead Waste Characterization.....	9
4.2.2 Dust Hazards.....	9
4.2.3 Soil Hazards.....	10
4.3 RADON	10
4.4 MOLD	10
5. COST ESTIMATES	10

LIST OF TABLES

Table I	Asbestos-Containing Materials Summary Table
Table II	Non Asbestos-Containing Materials Summary Table

APPENDICES

Appendix 1	Floor Plans
Appendix 2	Asbestos Bulk Sample Laboratory Reports
Appendix 3	XRF Lead-Based Paint Inspection Reports
Appendix 4	Lead-Based Paint Visual Assessment Forms
Appendix 5	TCLP Sample Laboratory Reports and Computation Tables
Appendix 6	Radon Testing Reports
Appendix 7	Mold Inspection Forms
Appendix 8	Abatement and Consulting Cost Estimates
Appendix 9	Eagle Environmental Inc. Licenses and Laboratory Certificates

1. INTRODUCTION

On April 18, June 3 and November 5, 2014, Eagle Environmental, Inc. conducted an environmental assessment and pre-demolition survey for the site building located at 39 Attawan Avenue in Niantic, Connecticut. The scope of the environmental assessment and pre-demolition survey included an inspection for asbestos-containing materials, a lead-based paint screen and TCLP (Toxic Characteristic Leachate Procedure) sample and a visual inspection for microbial contamination.

1.1 Inspection Area Description

The inspection was performed on suspect materials throughout the building as it is being demolished. The lead-based paint screen was performed throughout the building to support lead waste characterization testing.

2. SCOPE OF INSPECTION

2.1 Asbestos Containing Materials

The asbestos inspection was conducted in order to satisfy the United States Environmental Protection Agency (USEPA) National Emission Standard for Hazardous Air Pollutants Act (NESHAP) as amended November 20, 1990. The USEPA NESHAP final rule requires the identification and removal of all regulated ACM in a building prior to demolition.

The asbestos inspection was performed by Andrew Carnevale and Hannah Hintz; State of Connecticut licensed Asbestos Inspectors (license #000850 and 000816 respectively).

2.2 Lead-based Paint

A lead-based paint hazard screen was performed at the site building to comply with the Department of Housing and Urban Development (HUD) Lead Safe Housing Rule (24 CFR 35) for a residential property receiving Federal rehabilitation assistance under a program administered by HUD.

Certain lead-based paint requirements apply to each project depending on the level of Federal Funding allocated. The lead-based paint requirements include the following for each level of funding:

1. Residential property receiving \$5,000 or less per unit (Not Applicable to this Project):
 - a. Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.
 - b. Conduct a risk assessment in each unit receiving Federal funds, in common areas and the exteriors.
 - c. Interim control measures may be utilized throughout the building
 - d. Lead safe work practices are to be utilized during rehabilitation work that will disturb painted surfaces.

- e. After the completion of any rehabilitation work that has disturbed painted surfaces, clearances are to be performed.
2. Residential property receiving between \$5,000 and \$25,000 per unit:
- a. Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.
 - b. Lead safe work practices are to be utilized during rehabilitation work that will disturb lead-based painted surfaces.
 - c. Perform interim controls on all lead hazards identified during the lead hazard screen.
 - d. Perform clearance testing following interim control work and renovations.
 - e. Provide notice of lead-hazard reduction within 15 days of completion of work.
3. Residential property receiving greater than \$25,000 per unit:
- a. **Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.**
 - b. **Conduct a risk assessment in each unit receiving Federal funds, in common areas and the exteriors.**
 - c. **Abate all interior lead-based paint hazards identified during the lead inspection/risk assessment. Interim controls are acceptable on exterior surfaces that are not disturbed by rehabilitation and on paint-lead hazards that are below the de minimus levels.**
 - d. **Lead safe work practices are to be utilized during rehabilitation work that will disturb painted surfaces.**
 - e. **Perform clearance testing following abatement work.**
 - f. **Provide notice of lead-hazard reduction within 15 days of completion of work.**

The lead-based paint hazard screen was performed by Hannah Hintz and Kristen Liljehult State of Connecticut licensed Lead Inspectors/Risk Assessors (license #002244 and 002206 respectively).

In addition to HUD's Lead Safe Housing Rule, the State of Connecticut Department of Public Health Lead Poisoning Prevention and Control regulations apply when a child under the age of six (6) years old lives in the residence at the time of the inspection. The lead hazard screen was performed in accordance with State requirements, where applicable.

2.2.1 Lead Waste Characterization

The State of Connecticut Department of Energy and Environmental Protection (DEEP) regulates the disposal of hazardous waste. The required analytical test to determine a materials waste classification is the Toxicity Characteristic Leachate Procedure, or TCLP (Regulation of State DEEP 22a-449© - 101 (a) (1), incorporating 40 CFR 262.24). Eagle Environmental, Inc. collected samples of building materials for lead waste characterization.

2.3 Radon Testing

Radon testing for this program is performed on a case-by-case basis. Building's which are constructed on piers with its lowest level not in contact with the ground are not considered for Radon testing.

Buildings, which are not elevated off the ground, are tested for Radon under this Program. Radon testing is performed to comply with the National Environmental Policy Act (NEPA).

At a minimum, the Indoor Radon Potential Map of Connecticut was reviewed to determine each sites geographic location in respect to indoor radon potential.

2.4 Mold Inspection

Eagle performed a visual inspection for the presence of suspect mold within the inspection areas. The inspection included an investigation for signs of visible microbial growth including discoloring of building materials, mal odors and water intrusion that may inhibit microbial growth. The inspection was visual in nature and did not include any sampling or destructive investigations behind rigid walls or ceilings.

3. INSPECTION PROTOCOLS

3.1 Asbestos Containing Materials

3.1.1 Inspection

The asbestos-containing materials (ACM) inspection included the accessible interior and exterior portions of the building in support of building demolition. Semi-destructive testing techniques were utilized during the inspection process. This included removing small pieces of suspect materials for analysis (bulk sampling). Wood, glass, metal and fiberglass are not defined as suspect materials and are not sampled.

During the inspection, suspect materials are located, sampled, quantified and the friability of the material is determined. Friable materials are those materials that hand pressure can crumble, pulverize or reduce to powder when dry. An estimated quantity of identified ACM is provided for positive materials only. The materials are quantified in linear or square feet, depending on the nature of the material.

3.1.2 Bulk Sampling

During the sampling process, suspect ACM is separated into three (3) USEPA categories. These categories are: Thermal System Insulation (TSI), Surfacing Materials (SURF), and Miscellaneous materials (MISC). TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe covering, boiler insulation, duct wrap, and mudpack fitting cement. Surfacing ACM includes all ACM that is sprayed, toweled or otherwise applied to an existing surface. These

applications are most commonly used in fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACM not listed in thermal or surfacing, such as linoleum, vinyl asbestos flooring, and ceiling tile.

Bulk sampling was performed in a random method. Bulk sampling methods and number of samples collected meets or exceeds the USEPA requirements.

3.1.3 Bulk Sample Analysis

The samples of the suspect asbestos containing materials were sent to a State of Connecticut Department of Public Health (DPH) approved laboratory for analysis by Polarized Light Microscopy (PLM). PLM is the USEPA accepted method of analysis for identification of asbestos in bulk matrixes. Samples are collected individually or in sets. When sets of samples are collected, each set is systematically analyzed until one sample is determined to contain asbestos. Upon the determination of the presence of asbestos in one sample in the set, analysis of the remaining samples in the set is discontinued. If no asbestos is observed during analysis of the set of samples, the suspect material is determined to be negative for asbestos content.

Sample analysis results are reported in percentage of asbestos and non-asbestos components. The USEPA defines any material that contains greater than one percent asbestos, utilizing PLM, as being an asbestos-containing material (ACM). Suspect materials containing greater than one percent (1%) asbestos utilizing the PLM Point Count Method and the NOB TEM method are also considered to be asbestos-containing. Materials determined to contain greater than one percent (1%) asbestos is regulated by the USEPA, the State of Connecticut Department of Public Health and Department of Energy and Environmental Protection and the United States Department of Labor. Sample results indicating "no asbestos detected" (NAD) are specified as non-asbestos containing materials. Samples results indicating "Did Not Analyze" (DNA) are not analyzed due to the stop on first positive request to the laboratory.

3.1.3.1 Friable ACM Analysis

Certain samples of friable materials shown to contain less than 10% asbestos are analyzed further by the "Point Count Method". This procedure is recommended by the United States Environmental Protection Agency to confirm friable bulk samples shown to have less than 10% asbestos by PLM to be definitively negative or positive for asbestos. This method is accepted as providing statistically reliable results when analyzing bulk samples with very low asbestos concentrations. Friable materials containing "Trace" or "less than one percent (1%)" asbestos must be analyzed by the PLM Point Count Method. No samples were further analyzed by the PLM Point Count Method for the 39 Attawan Avenue, Niantic, Connecticut.

3.1.3.2 Non Friable ACM Analysis

Certain samples of organically bound non-friable materials shown to contain "less than 1% asbestos", "TRACE" or "NAD" are recommended for analyses by the "NOB TEM ELAP 198.4 Method". This procedure is recommended by the United States Environmental Protection Agency to further evaluate non-friable organically bound materials for asbestos. Suspect materials confirmed by NOB TEM to be "less than 1% asbestos", "TRACE" or "NAD" are considered non-asbestos containing. No samples were further analyzed by the NOB TEM Method for the 39 Attawan Avenue, Niantic, Connecticut.

3.2 Lead-based Paint

The lead hazard screen was performed utilizing an X-Ray Fluorescence (XRF) Radiation Monitoring Device (RMD) Lead Paint Analyzer (LPA 1), serial number 2753 throughout the building.

Due to the level of proposed Federal Funding for this project, the lead-based paint screen included testing surfaces where defective paint or surface coatings were identified. A visual inspection was performed to evaluate the condition of surface coating associated with the building. Where surface coatings were defective (peeling, chipping, flaking, etc.), paint testing was performed. Component and surface locations are identified by side designations represented by the letters "A", "B", "C", and "D". The "A" side is considered the front of the building with the "B", "C", and "D" sides following in a clockwise order.

The data is presented on computer generated Lead Inspection Reports contained in Appendix 3. The Summary Report provides an inventory of each surface coating that contains lead at or above 1.0 mg/cm². The Detailed Report is an inventory of each tested surface on a room-by-room basis.

For the purpose of this report, lead-based paint is defined as surface coatings that contain ≥ 1.0 mg/cm² of lead by XRF.

In addition to XRF testing, dust samples are collected at the time of inspection if defective lead-based paint is identified. The exterior grounds are evaluated as well and if bare areas of soil are identified, soil samples are collected. Any dust or soil hazards identified are incorporated into the Lead-Based Paint Hazard Reduction or Abatement Plan.

3.3 Lead Waste Characterization

Lead-contaminated debris, not contaminated with other hazardous materials, is classified either as hazardous lead waste or as non-hazardous solid waste. The required analytical test to determine which of these classifications is appropriate for a given quantity of waste is the Toxicity Characteristic Leachate Procedure, or TCLP (Regulation of State DEP 22a-449© - 101 (a) (1), incorporating 40 CFR 262.24).

The TCLP test subjects a 100 gram sample of waste material to a simulated landfill leaching condition, and assesses the ability of the sample to leach out lead into the environment. The waste is classified as hazardous lead waste if the TCLP sample result is greater than 5.0 mg/l of lead. The waste is classified as non-hazardous solid waste if the TCLP sample result is less than 5.0 mg/l of lead.

There are two (2) primary approaches for TCLP sampling. Both methods utilize the data generated during the lead screen to determine which building materials contain lead in paint coatings and what percentage of the waste stream will consist of the leaded materials. The two (2) basic approaches are described below.

3.3.1 Screen, Sample, and Segregate Method

The Screen, Sample, and Segregate method of TCLP sampling is conducted in accordance with the State of Connecticut Department of Environmental Protection Guidance for the Management and Disposal of Lead-Contaminated Materials Generated in the Lead Abatement, Renovation, and Demolition Industries. This method entails screening the building components scheduled to be removed with an XRF lead paint analyzer. Components that are determined to be lead containing are sampled and

analyzed by TCLP based on their contribution into the waste stream. The waste stream is made up of those building components that will be removed from the structure as part of the renovation or demolition process. It is very important to accurately identify the waste stream in order for the TCLP sample to be truly representative.

The TCLP sample consists of the building materials that contain lead. The building materials are carefully removed at the site using coring devices or by saw cutting. The building materials are then placed directly into polyethylene zip lock bags for transmission to the laboratory.

3.3.2 Composite Sample and Demolish Method

The Composite Sample and Demolish Method of TCLP sampling is conducted in accordance with the State of Connecticut Department of Environmental Protection Guidance for the Management and Disposal of Lead-Contaminated Materials Generated in the Lead Abatement, Renovation, and Demolition Industries. This method utilizes composite samples to assess the lead content of the entire quantity of debris to be removed. This sampling method is best utilized for whole building demolitions where the quantity of non-lead debris is expected to be much greater than that of the leaded debris. The first step in the sampling process requires the inspector to identify the potential waste stream of the structure to be demolished. The waste stream is made up of those building components that will be disposed of once the structure is demolished. The inspector calculates the mass by weight of each group of building components within the building (i.e. studs, framing, sheathing, siding, doors, windows, etc.). The lead testing results enables the inspector to determine the percentages of components, within each group, that contain lead. With this information, the inspector can then calculate the percent by weight contribution of each components contribution into the waste stream. This takes into account the ratio of leaded components verse non-leaded components within each group.

The actual sampling is performed by collecting samples of each building component. The components are then mixed together in proportion to their percent by weight of the total quantity of debris to be removed.

This study utilized the Composite Sample and Demolish Method to characterize the primary waste stream identified during the inspection.

3.4 Radon Testing

The site building is scheduled to be demolished; therefore, radon testing was not performed for this site building.

3.5 Mold Inspection

Eagle Environmental, Inc. performed a visual inspection within the limits of the inspection area for potential microbial growth. The visual inspection was performed to evaluate building materials for signs of water damage and suspect microbial growth. Building materials such as gypsum board, cellulose ceiling tiles, paper pipe coverings or duct coverings and heating, ventilation and air conditioning components were visually assessed. Only visible accessible materials were inspected within the proposed areas of renovation/repair.

Discoloration and decay of the aforementioned building materials may signify mold growth. Water damage or damp conditions may also signify suitable conditions for mold growth.

Suspect mold growth or conditions that may sustain mold growth were documented during the inspection process. In general, the location, color of suspect growth and estimated quantity of impacted building materials were recorded during the inspection process.

Eagle used an Extech Instruments Model MO290 Moisture/Humidity Meter to measure the relative moisture content of accessible representative building materials that may have been impacted by water during the storm. A "dry standard" for each component was determined by averaging the moisture measurements for materials in un-impacted areas. The "dry standard" was used as a baseline comparison to determine if the materials were wet. Moisture measurements were recorded on the Mold Moisture Reading Form.

4. INSPECTION RESULTS

4.1 Asbestos Containing Materials

During the course of the building inspection forty-eight (48) bulk samples of suspect ACM were collected. Of the forty-eight (48) bulk samples collected, forty-five (45) samples were analyzed by PLM based on the "stop on first positive" request to the laboratory.

The summaries of asbestos and non-asbestos materials are presented in Tables I and II respectively. The asbestos analysis laboratory reports are provided in Appendix 2.

Asbestos containing materials were identified on the 2nd floor bathroom 12"x12" self adhesive white floor tiles, the white caulk at the storm window/wood casings and the black caulk flashing cement under the metal flashing.

Any suspect material not specifically identified in this report as non-ACM should be assumed to contain asbestos unless sample results prove otherwise.

All regulated friable and regulated non-friable ACM must be removed prior to demolition. A State of Connecticut Licensed Asbestos Abatement Contractor must be retained to perform the removal work. Visual inspections and air clearances must be performed within each abatement area at the completion of the abatement work. The visual inspections and air clearances must be performed by a State of Connecticut licensed Asbestos Project Monitor. The abatement areas must meet final visual and air clearance inspection criteria prior to building demolition. Re-occupancy air monitoring is required if the building will be re-entered by any person following abatement and prior to demolition. This includes but is not limited to entry for utility disconnects, salvage, equipment removal, etc.

The Asbestos Abatement Contractor must submit a notice of asbestos abatement to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) days prior to the commencement of any asbestos abatement activities involving the abatement of greater than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials. The asbestos abatement notification satisfies the DPH regulatory requirements for demolition notification. For asbestos abatement projects involving less than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials or projects where no regulated asbestos-containing materials are identified, the facility owner or any person who will be conducting demolition must submit a demolition notification to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) days prior to the commencement of demolition activities.

4.2 Lead-based Paint

A copy of this lead-hazard screen report must be provided to residence within fifteen (15) days of the evaluation. A total of one hundred nineteen (119) XRF readings were collected during the lead-hazard screen of the building. From the one hundred nineteen (119) readings, fifty (50) were found to contain toxic levels of lead-based paint.

The general inventory of surfaces containing lead-based paint include the following

- The majority of the Sun Room (Enclosed front porch) painted wood components
- Various original wood window systems
- Various door and door trim components
- Exterior wood clapboard facades (exposed and under vinyl siding) and window trim components

A complete inventory of tested building materials is presented in Detailed Reports contained Appendix 3.

This residence is considered target housing by the USEPA. All lead-hazard remediation work shall be performed compliance with the USEPA Renovation, Remodeling and Painting (RRP) Rule as prescribed by 40 CFR Part 745.80 Subpart E. Including USEPA RRP Firm Certification, USEPA RRP Renovator Certification, Disclosure and Notification, Placement of Warning Signs, Lead-Safe Work Practice, Cleaning and Post Remediation Lead Dust Clearance by an approved USEPA method.

The U.S. Department of Labor Occupation Safety and Health Administration (OSHA) regulates lead dust exposure to workers in the construction industry under 29 CFR 1926.62 Lead Exposure in Construction; Interim Final Rule. Currently, OSHA does not define a threshold level of lead in paint that may cause worker exposure. Any detectable level of lead in paint ($>0.0 \text{ mg/cm}^2 \pm 0.3 \text{ mg/cm}^2$ by XRF or $>0.01 \%$ by AAS) requires task specific exposure monitoring. Contractors performing lead disturbing tasks on this project must comply with the OSHA Lead in Construction Standard.

4.2.1 Lead Waste Characterization

One (1) composite TCLP sample was collected and prepared for waste characterization purposes. The building components that were identified within the waste stream included solid wood with and without coatings of lead-based paint, sheetrock without coatings of lead-based paint, window glass and asphalt roofing shingles. Detailed computations estimating the contributions of each of these components to the total waste stream are presented in Appendix 5.

The result of the TCLP sample representative of the waste stream was 12 mg/L characterizing the waste stream as hazardous lead waste.

In order to keep disposal costs down, Eagle recommends removing the wood clapboard siding and segregating it for disposal as hazardous lead waste. Another TCLP sample must be performed on the remaining structure to determine if it may be disposed of as general construction debris.

4.2.2 Dust Hazards

The building is scheduled to be demolished; therefore, dust samples were not required.

4.2.3 Soil Hazards

No soil samples were collected at the time of inspection as there were no bare areas of soil identified. The owner may maintain the ground cover in its current condition.

4.3 Radon

Radon testing was not performed at this Site since the building scheduled to be demolished.

4.4 Mold

The visual microbial inspection observed no evidence of water intrusion, damage or microbial growth. The mold inspection forms are provided in Appendix 7.

5. COST ESTIMATES

The cost estimates include only the abatement or remediation work necessary to support the renovation/repair work. Other regulated or hazardous materials may be present and were not inspected for under this scope of services and are not included within the estimate.

This is a budgetary opinion of cost that is expected to be within -15 to + 30 percent of the actual cost. Eagle Environmental, Inc. has no control over the cost of labor, materials, equipment or services furnished by others, or over the Contractor or Contractors' methods of determining prices, or over competitive bidding or market conditions. Eagle Environmental, Inc.'s opinion of probable cost of abatement are made on the basis of Eagle Environmental, Inc.'s experience and qualifications and represent Eagle Environmental, Inc.'s judgment as an experienced and qualified consultant familiar with the abatement industry; but Eagle Environmental, Inc. cannot and does not guarantee that proposals, bids or actual Total Project or Abatement Cost will not vary from opinions of probable cost prepared by Eagle Environmental, Inc. If, prior to the bidding or negotiating phase, the Owner wishes greater assurance as to Total Project or Abatement Cost, the Owner shall employ an independent cost estimator.

The cost estimates are provided in Appendix 8.

TABLE I
ASBESTOS CONTAINING MATERIALS SUMMARY TABLE

TABLE I
ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT

LOCATION(S)	MATERIAL TYPE	SAMPLE NUMBER	CATEGORY	BULK SAMPLE ANALYSIS RESULTS				ESTIMATED QUANTITY	F/NF
				PLM	PLM/PC	TEM NOB	ACM		
2nd Floor Bath	12"x12" self adhesive white floor tiles	11-5 HH 03	MISC	2% Chrys			YES	60 SF	NF
		11-5 HH 04							
Façade C, D	White caulk at storm window/wood casing	11-5 HH 07	MISC	8% Anth			YES	4 each @ 13 LF	NF
		11-5 HH 08							
Lower Roof	Black caulk / flashing cement under metal flashing	11-5 HH 19	MISC	8% Chrys			YES	40 LF	NF
		11-5 HH 20							
KEY									
DNA = DID NOT ANALYZE									
NAD = NO ASBESTOS DETECTED									
F = FRIABLE									
NF = NON-FRIABLE									
TSI = THERMAL SYSTEMS INSULATION									
SURF = SURFACING MATERIAL									
MISC = MISCELLANEOUS MATERIAL									
ANALYTICAL METHODS									
PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT									
TEM NOB = NEW YORK ELAP 198.4 METHOD									
PLM = EPA 600/R-93/116									
PS = Previously Sampled									
EA = Each									
BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION									

TABLE II

NON-ASBESTOS-CONTAINING MATERIALS SUMMARY TABLE

TABLE II
NON - ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT

SAMPLE LOCATION(S)	MATERIAL TYPE	SAMPLE NUMBER	CATEGORY	BULK SAMPLE ANALYSIS RESULTS		
				PLM	PLM/PC	TEM NOB
Crawl Space	Cement panel	4-18-AC-01	MISC	NAD		NO
		4-18-AC-02		NAD		NO
Kitchen, Living Room	Sheetrock	4-18-AC-05	MISC	NAD		NO
		4-18-AC-06		NAD		NO
		4-18-AC-07		NAD		NO
		4-18-AC-08		NAD		NO
		4-18-AC-09		NAD		NO
		4-18-AC-10		NAD		NO
Kitchen	Sheetrock/joint compound composite	11-5 HH 01	MISC	NAD		NO
		11-5 HH 02		NAD		NO
		11-5 HH 25		NAD		NO
		11-5 HH 26		NAD		NO
		11-5 HH 27		NAD		NO
		11-5 HH 28		NAD		NO
Living Room	Seating at backsplash	4-18-AC-11	MISC	NAD		NO
		4-18-AC-12		NAD		NO
Bedroom 3	Residual adhesive on wall	4-18-AC-13	MISC	NAD		NO
		4-18-AC-14		NAD		NO
Façade B	Wood window glazing compound	4-18-AC-15	MISC	NAD		NO
		4-18-AC-16		NAD		NO
Fac B, D	Break away panels	11-5 HH 05	MISC	NAD		NO
		11-5 HH 06		NAD		NO
Fac C	Paper under siding	4-18-AC-03	MISC	NAD		NO
		4-18-AC-04		NAD		NO
Main Roof	Tar paper	11-5 HH 09	MISC	NAD		NO
		11-5 HH 10		NAD		NO
KEY				ANALYTICAL METHODS		
DNA = DID NOT ANALYZE				PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT		
NAD=NO ASBESTOS DETECTED				TEM NOB = NEW YORK ELAP 198.4 METHOD		
F = FRIABLE				PLM = EPA 600/R-93/116		
NF = NON-FRIABLE				PS = Previously Sampled		
TSI = THERMAL SYSTEMS INSULATION				EA = Each		
SURF = SURFACING MATERIAL						
MISC = MISCELLANEOUS MATERIAL						
BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION						

TABLE II
NON - ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT

SAMPLE LOCATION(S)	MATERIAL TYPE	SAMPLE NUMBER	CATEGORY	BULK SAMPLE ANALYSIS RESULTS		
				PLM	PLM PC	ACM
Lower Roof	Black asphalt roof shingle top layer	11-5 HH 11	MISC	NAD		NO
		11-5 HH 12		NAD		
	Red and white asphalt shingle bottom layer	11-5 HH 13	MISC	NAD		NO
		11-5 HH 14		NAD		
	Asphalt rolled roofing at flashing	11-5 HH 15	MISC	NAD		NO
		11-5 HH 16		NAD		
	Black caulk surrounding asphalt rolled roofing	11-5 HH 17	MISC	NAD		NO
		11-5 HH 18		NAD		
	Black flashing tape at metal flashing	11-5 HH 21	MISC	NAD		NO
		11-5 HH 22		NAD		
Porch Roof	Clear caulk at smoke vent	11-5 HH 23	MISC	NAD		NO
		11-5 HH 24		NAD		
Porch Roof	Black asphalt shingles	4-18-AC-17	MISC	NAD		NO
		4-18-AC-18		NAD		
Porch Roof	Bottom layer shingle	4-18-AC-19	MISC	NAD		NO
		4-18-AC-20		NAD		
KEY				ANALYTICAL METHODS		
DNA = DID NOT ANALYZE				PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT		
NAD=NO ASBESTOS DETECTED				TEM NOB = NEW YORK ELAP 198.4 METHOD		
F = FRIABLE				PLM = EPA 600/R-93/116		
NF = NON-FRIABLE				PS = Previously Sampled		
TSI = THERMAL SYSTEMS INSULATION				EA = Each		
SURF = SURFACING MATERIAL						
MISC = MISCELLANEOUS MATERIAL						
BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION						

APPENDIX 1
FLOOR PLANS

CAPITAL STUDIO ARCHITECTS


39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT

EAGLE PROJECT NUMBER: 14-028.12T10

INDEX OF DRAWINGS

SP-1 SITE PLAN
FP-1 FIRST FLOOR PLAN
FP-2 SECOND FLOOR PLAN

LOCATION MAP



FEBRUARY 3, 2015



8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SITE PLAN

SIDE-C

BARE SOIL DRIVEWAY

GARAGE

GRASS

WOOD FENCE

RESIDENCE

SIDE-B

DART STREET

SIDE-D

PORCH

NEIGHBOR'S HOME

GRASS

ATTAWAN AVENUE

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

SP-1

SHEET 1 OF 3

DATE: 02/03/2015
PROJECT NO.: 14-028.12-T10
DRAWN BY: VB
REVIEWED BY: AH


ENVIRONMENTAL REVIEW
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT
SITE PLAN

FIRST FLOOR

SIDE-C

WINDOW KEY:

- FX** = FIXED
- OW** = OLDER OR ORIGINAL WOOD SASH (TESTED POSITIVE FOR LEAD-BASED PAINT)
- V** = VINYL SASH



NOT TO SCALE

C = CLOSET EVALUATED WITH ADJACENT ROOM



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

FP-1

SHEET 2 OF 3

DATE: 02/03/2015
PROJECT NO.: 14-028.12-T10
DRAWN BY: VB,
REVIEWED BY: AH

ENVIRONMENTAL REVIEW
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT
FIRST FLOOR PLAN

SECOND FLOOR


SIDE-C

WINDOW KEY:

FX = FIXED

OW = OLDER OR ORIGINAL WOOD SASH (TESTED POSITIVE FOR LEAD-BASED PAINT)

V = VINYL SASH



SIDE-B

SIDE-D

SIDE-A (STREET SIDE)

NOT TO SCALE

C = CLOSET EVALUATED WITH ADJACENT ROOM



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

FP-2

SHEET 3 OF 3

DATE: 02/03/2015
PROJECT NO.: 14-028.12-T10
DRAWN BY: VB
REVIEWED BY: AH

ENVIRONMENTAL REVIEW
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT
SECOND FLOOR PLAN

APPENDIX 2

ASBESTOS BULK SAMPLE LABORATORY REPORTS



EMSL - MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL - CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06492 (203) 284-5948 (203) 284-5978 Fax	EMSL - NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL - NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
---	---	--	---

Your Name: Brandy LeBlanc **Project Manager:** PF

Company: Eagle Environmental, Inc.

Street: 8 South Main Street, Suite 3

City/State/Zip: Terryville, CT 06786

Phone: 860-589-8257 ext. 108 **Fax:** 860-585-7034 **Email:** bleblanc@eagleenviro.com; nporter@eagleenviro.com; dwynne@eagleenviro.com; rsloch@eagleenviro.com

Project Name: CSA-SSS **Project #:** 14-028.12T10

Project Location: 39 Attawan Avenue, Niantic **Project State (US):** CT

TURNAROUND TIME

3 Hours
 6 Hours
 24 Hours
 48 Hours
 72 Hours
 4 Days
 5 Days
 6-10 Days

SAMPLE MATRIX

Air
 Bulk
 Soil
 Wipe
 Micro-Vac
 Drinking Water
 Wastewater
 Chips
 Other

ASBESTOS ANALYSIS

PCM - Air

NIOSH 7400 (A) Issue 2: August 1994
 OSHA w/TWA

TEM AIR

AHERA 40 CFR, Part 763 Subpart E
 NIOSH 7402 Issue 2
 EPA Level II

PLM - Bulk

EPA 600/R-93/116
 NY Stratified Point Count
 California Air Resource Board (CARB) 435
 NIOSH 9002
 PLM NOB (Gravimetric) NYS 198.1
 EPA Point Count (400 Points)
 EPA Point Count (1,000 Points)
 Standard Addition Point Count

SOILS

EPA Protocol Qualitative
 EPA Protocol Quantitative
 EMSL MSD 9000 Method fibers/gram
 Superfund EPA 540-R097-028 (dust generation)

TEM BULK

Drop Mount (Qualitative)
 Chatfield SOP-1988-02
 TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC

ASTM D 5755-95 (Quantitative)

TEM WIPE

ASTM D-6480-99
 Qualitative

TEM WATER

EPA 100.1
 EPA 100.2
 NYS 198.2
 Other:

LEAD ANALYSIS

Flame Atomic Absorption

Wipe, SW846-7420 ASTM non ASTM
 Soil, SW846-7420
 Air, NIOSH 7082
 Chips, SW846-7420 or ACAC 5.009 (974.02)
 Wastewater, SW 846-7420
 TCLP LEAD SW846-1311/7420

Graphite Furnace Atomic Absorption

Air, NIOSH 7105
 Wastewater, SW846-7421
 Soil, SW846-7421
 Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma

Wipe, SW846-6010 ASTM non ASTM
 Soil, SW846-6010
 Air, NIOSH 7300

MATERIALS ANALYSIS

Full Particle Identification
 Optical Particle Identification
 Dust Mites and Insect Fragments
 Particle Size & Distribution
 Product Comparison
 Paint Characterization
 Failure Analysis
 Corrosion Analysis
 Glove Box Containment Study
 Petrographic Examination of Concrete
 Portland Cement in Workplace Atmospheres (OSHA ID-143)
 Man Made Vitreous Fibers - MMVF's
 Synthetic Fiber Identification
 Other:

MICROBIAL ANALYSIS

Air Samples

Mold & Fungi by Air O Cell
 Mold & Fungi by Agar Plate count & Id
 Bacterial Count and Gram Stain
 Bacterial Count and Identification

Water Samples

Total Coliforms, Fecal Coliforms
 Escherichia Coli, Fecal Streptococcus
 Legionella
 Salmonella
 Giardia and Cryptosporidium

Wipe and Bulk Samples

Mold & Fungi - Direct Examination
 Mold & Fungi - (Culture follow up to direct examination if necessary)
 Mold & Fungi - Culture (Count & ID)
 Mold & Fungi - Culture (Count only)
 Bacterial Count & Gram Stain
 Bacterial Count & Identification (3 most prominent types)
 Other:

IAQ ANALYSIS

Nuisance Dust (NIOSH 0500 & 0600)
 Airborne Dust (PM10, TSP, NIOSH 7500)
 Silica Analysis by XRD
 HVAC Efficiency
 Carbon Black
 Airborne Oil Mist
 Other:

EMSL MANHATTAN LAB
 RECEIVED
 NOV - 7 2014
 11:11

031442890

Additional Information/Comments/Instructions: ****PLEASE STOP ON 1ST POSITIVE WITHIN SETS**

Client Sample # (S)	11-5-HH-01	11-5-HH-28	TOTAL SAMPLE #
Relinquished:	HANNAH HINTZ	Date: 11-5-14	Time: PM
Received:	RENEE SIOCH	Date: 11-5-14	Time: PM
Relinquished:	RENEE SIOCH	Date: 11-6-14	Time: PM
Received:		Date: 11/7/14	Time: 10:11 am

11/7/14 10:10 am

FX 7900 8443 3850



EMSL – MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL – CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06492 (203) 284-5948 (203) 284-5978 Fax	EMSL – NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL – NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
--	--	---	--

SAMPLE NUMBER	SAMPLE DESCRIPTION	ROOM or LOCATION	VOLUME Air (L)	Area (Inches sq.)
11-5-HH-01	12" X 12" Self-adhesive white floor tile	Kitchen		NAD
11-5-HH-02	12" X 12" Self-adhesive white floor tile	Kitchen		NAD
11-5-HH-03	12" X 12" Self-adhesive pattern floor tile	2dFIBath		290 Chris
11-5-HH-04	12" X 12" Self-adhesive pattern floor tile	2dFIBath		DNA
11-5-HH-05	Break away panels	Ext. D		NAD
11-5-HH-06	Break away panels	Ext. B		NAD
11-5-HH-07	White caulk at storm window/woodcasing	Ext. D		290 Anth
11-5-HH-08	White caulk at storm window/woodcasing	Ext. D		DNA
11-5-HH-09	Tar paper	Main Roof		NAD
11-5-HH-10	Tar paper	Main Roof		
11-5-HH-11	Black asphalt roof shingle (top layer)	LowerRoof		
11-5-HH-12	Black asphalt roof shingle (top layer)	LowerRoof		
11-5-HH-13	Red & white asphalt shingle (bottom layer)	LowerRoof		
11-5-HH-14	Red & white asphalt shingle (bottom layer)	LowerRoof		
11-5-HH-15	Asphalt rolled roofing at flashing	LowerRoof		
11-5-HH-16	Asphalt rolled roofing at flashing	LowerRoof		
11-5-HH-17	Black caulk surrounding asphalt rolled roofing	LowerRoof		
11-5-HH-18	Black caulk surrounding asphalt rolled roofing	LowerRoof		
11-5-HH-19	Black flashing cement under metal flashing	LowerRoof		
11-5-HH-20	Black flashing cement under metal flashing	LowerRoof		
11-5-HH-21	Black flashing tape at metal flashing	LowerRoof		NAD
11-5-HH-22	Black flashing tape at metal flashing	LowerRoof		
11-5-HH-23	Clear caulk at smoke vent	LowerRoof		
11-5-HH-24	Clear caulk at smoke vent	LowerRoof		

EMSL MANHATTAN RECEIVED
 14 NOV - 7 AM 10: 2
 8:30 CHRYS
 AB DNA

031442890

[Signature]
 10:40am

Rec'd by *[Signature]* 11/14 10:11am

Henry 11/8 7:44am

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031442890
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 11/07/14 10:11 AM
 Analysis Date: 11/8/2014
 Collected: 11/5/2014

Project: 14-028.12T10/ CSA-SSS/ 39 ATTAWAN AVE / NIAN TIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11-5-HH-01 031442890-0001	12X12 SELF ADHESIVE WHITE FLOOR TILE / KITCHEN	White Non-Fibrous Homogeneous		50% Ca Carbonate 35% Matrix 15% Non-fibrous (other)	None Detected
11-5-HH-02 031442890-0002	12X12 SELF ADHESIVE WHITE FLOOR TILE / KITCHEN	Gray Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (other)	None Detected
11-5-HH-03 031442890-0003	12X12 SELF ADHESIVE WHITE FLOOR TILE / 2ND FL BATH	Tan Non-Fibrous Homogeneous		65% Ca Carbonate 33% Non-fibrous (other)	2% Chrysotile
11-5-HH-04 031442890-0004	12X12 SELF ADHESIVE WHITE FLOOR TILE / 2ND FL BATH				Stop Positive (Not Analyzed)
11-5-HH-05 031442890-0005	BREAK AWAY PANELS / EXT D	Gray Non-Fibrous Homogeneous	5% Glass	20% Quartz 75% Non-fibrous (other)	None Detected
11-5-HH-06 031442890-0006	BREAK AWAY PANELS / EXT B	Gray Non-Fibrous Homogeneous		55% Quartz 45% Non-fibrous (other)	None Detected
11-5-HH-07 031442890-0007	WHITE CAULK AT STORM WINDOW / WOOD CASING / EXT D	Gray/Tan Non-Fibrous Homogeneous	8% Fibrous (other)	90% Non-fibrous (other)	2% Anthophyllite

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from 11/08/2014 09:49:13

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031442890
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 11/07/14 10:11 AM
 Analysis Date: 11/8/2014
 Collected: 11/5/2014

Project: 14-028.12T10/ CSA-SSS/ 39 ATTAWAN AVE / NIAN TIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11-5-HH-08 031442890-0008	WHITE CAULK AT STORM WINDOW / WOOD CASING / EXT D				Stop Positive (Not Analyzed)
11-5-HH-09 031442890-0009	TAR PAPER / MAIN ROOF	Black Fibrous Homogeneous	12% Glass	45% Matrix 43% Non-fibrous (other)	None Detected
11-5-HH-10 031442890-0010	TAR PAPER / MAIN ROOF	Black Fibrous Homogeneous	70% Cellulose 15% Synthetic	15% Non-fibrous (other)	None Detected
11-5-HH-11 031442890-0011	BLACK ASPHALT ROOF SHINGLE TOP LAYER / LOWER ROOF	Black Fibrous Homogeneous	15% Glass	35% Matrix 50% Non-fibrous (other)	None Detected
11-5-HH-12 031442890-0012	BLACK ASPHALT ROOF SHINGLE TOP LAYER / LOWER ROOF	Black Fibrous Homogeneous	25% Glass	75% Non-fibrous (other)	None Detected
11-5-HH-13 031442890-0013	RED AND WHITE ASPHALT SHINGLE BOTTOM LAYER	Brown/Gray Fibrous Homogeneous	10% Glass	15% Quartz 45% Ca Carbonate 30% Non-fibrous (other)	None Detected
11-5-HH-14 031442890-0014	RED AND WHITE ASPHALT SHINGLE BOTTOM LAYER	Black Non-Fibrous Homogeneous	15% Glass	40% Matrix 45% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from 11/08/2014 09:49:13

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031442890
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 11/07/14 10:11 AM
 Analysis Date: 11/8/2014
 Collected: 11/5/2014

Project: 14-028.12T10/ CSA-SSS/ 39 ATTAWAN AVE / NIAN TIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11-5-HH-15 031442890-0015	ASPHALT ROLLED ROOFING AT FLASHING / LOWER ROOF	Black Fibrous Homogeneous	18% Glass	5% Quartz 45% Matrix 32% Non-fibrous (other)	None Detected
11-5-HH-16 031442890-0016	ASPHALT ROLLED ROOFING AT FLASHING / LOWER ROOF	Black Non-Fibrous Homogeneous		35% Matrix 65% Non-fibrous (other)	None Detected
11-5-HH-17 031442890-0017	BLACK CAULK SURROUNDING ASPHALT ROLLED ROOFING - LOWER ROOF	Black Non-Fibrous Homogeneous		10% Ca Carbonate 75% Matrix 15% Non-fibrous (other)	None Detected
11-5-HH-18 031442890-0018	BLACK CAULK SURROUNDING ASPHALT ROLLED ROOFING - LOWER ROOF	Black Non-Fibrous Homogeneous		30% Matrix 70% Non-fibrous (other)	None Detected
11-5-HH-19 031442890-0019	BLACK CAULK FLASHING CEMENT UNDER METAL FLASHING - LOER	Red/Black Fibrous Homogeneous		92% Non-fibrous (other)	8% Chrysotile
11-5-HH-20 031442890-0020	BLACK CAULK FLASHING CEMENT UNDER METAL FLASHING				Stop Positive (Not Analyzed)

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from 11/08/2014 09:49:13

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031442890
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 11/07/14 10:11 AM
 Analysis Date: 11/8/2014
 Collected: 11/5/2014

Project: 14-028.12T10/ CSA-SSS/ 39 ATTAWAN AVE / NIAN TIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11-5-HH-21 031442890-0021	BLACK FLASHING TAPE AT METAL FLASHING / LOWER - ROOF	Black Non-Fibrous Homogeneous	7% Cellulose	80% Matrix 13% Non-fibrous (other)	None Detected
11-5-HH-22 031442890-0022	BLACK FLASHING TAPE AT METAL FLASHING / LOWER - ROOF	Black Non-Fibrous Homogeneous		38% Matrix 62% Non-fibrous (other)	None Detected
11-5-HH-23 031442890-0023	CLEAR CAULK AT SMOKE VENT/ LOWER ROOF	Clear Non-Fibrous Homogeneous		87% Matrix 13% Non-fibrous (other)	None Detected
11-5-HH-24 031442890-0024	CLEAR CAULK AT SMOKE VENT/ LOWER ROOF	Clear Non-Fibrous Homogeneous		20% Matrix 80% Non-fibrous (other)	None Detected
11-5-HH-25 031442890-0025	SEATING AT BACKSPLASH / KITCHEN	White Non-Fibrous Homogeneous		35% Quartz 65% Non-fibrous (other)	None Detected
11-5-HH-26 031442890-0026	SEATING AT BACKSPLASH / KITCHEN	Gray/White Non-Fibrous Homogeneous	2% Cellulose	35% Matrix 63% Non-fibrous (other)	None Detected
11-5-HH-27 031442890-0027	JOINT COMPOUND AT BLACKSPLASHK / KITCHEN	Tan/White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (other)	None Detected
Inseparable paint / coating layer included in analysis					
11-5-HH-28 031442890-0028	JOINT COMPOUND AT BLACKSPLASHK / KITCHEN	White Non-Fibrous Homogeneous		38% Matrix 62% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from 11/08/2014 09:49:13



EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018
Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031442890
CustomerID: EEVM50
CustomerPO:
ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
Fax: (860) 585-7034
Received: 11/07/14 10:11 AM
Analysis Date: 11/8/2014
Collected: 11/5/2014

Project: 14-028.12T10/ CSA-SSS/ 39 ATTAWAN AVE / NIAN TIC

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date:: 11/7/2014 Sample Receipt Time: 10:11 AM
Analysis Completed Date: 11/8/2014 Analysis Completed Time: 7:42 AM

Analyst(s):

Henry Akintunde PLM (11)

Shahrakur Mahmud PLM (14)

Samples reviewed and approved by:

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Initial report from 11/08/2014 09:49:13



EMSL - MA
 7 Constitution Way, Ste 107
 Woburn, MA 01801
 (781) 933-8411
 (781) 933-8412 Fax

EMSL - CT
 29 N. Plains Hwy, Unit 4
 Wallingford, CT 06492
 (203) 284-5948
 (203) 284-5978 Fax

EMSL - NY
 307 West 38th Street
 New York, NY 10018
 (866) 448-3675
 (212) 290-0058 Fax

EMSL - NJ
 107 Haddon Avenue
 Westmont, NJ 08108
 (800) 220-3675
 (856) 858-4960 Fax

Your Name: Brandy LaBlanc **Project Manager:** PF

Company: Eagle Environmental, Inc.

Street: 8 South Main Street, Suite 3

City/State/Zip: Terryville, CT 06786

Phone: 860-589-8257 ext. 203 **Fax:** 860-585-7034 **Email:** bleblanc@eagleenviro.com; nporter@eagleenviro.com; dwynne@eagleenviro.com; rstoeh@eagleenviro.com

Project Name: CSA-Super Storm Sandy Project **Project #:** 14-020.12T8

Project Location: 39 Attawan Ave., Niantic **Project State (US):** CT

TURNAROUND TIME

3 Hours 6 Hours 24 Hours 48 Hours 72 Hours 4 Days 5 Days 6-10 Days

SAMPLE MATRIX

Air Bulk Soil Wipe Micro-Vac Drinking Water Wastewater Chips Other

ASBESTOS ANALYSIS

PCM - Air
 NIOSH 7400 (A) Issue 2: August 1994
 OSHA w/TWA

TEM AIR
 AHERA 40 CFR, Part 763 Subpart E
 NIOSH 7402 Issue 2
 EPA Level II

PLM - Bulk
 EPA 600/R-93/116
 NY Stratified Point Count
 California Air Resource Board (CARB) 435
 NIOSH 9002
 PLM NOB (Gravimetric) NYS 198.1
 EPA Point Count (400 Points)
 EPA Point Count (1,000 Points)
 Standard Addition Point Count

SOILS
 EPA Protocol Qualitative
 EPA Protocol Quantitative
 EMSL MSD 9000 Method fibers/gram
 Superfund EPA 540-R097-02B (dust generation)

TEM BULK
 Drop Mount (Qualitative)
 Chatfield SOP-1988-02
 TEM NOB (Gravimetric) NY 198.4

TEM MICROVAC
 ASTM D-5755-95 (Quantitative)

TEM WIPE
 ASTM D-6480-99
 Qualitative

TEM WATER
 EPA 100.1
 EPA 100.2
 NYS 198.2
 Other:

LEAD ANALYSIS

Flame Atomic Absorption
 Wipe, SW846-7420 ASTM non ASTM
 Soil, SW846-7420
 Air, NIOSH 7082
 Chips, SW846-7420 or AOAC 5.009 (974.02)
 Wastewater, SW 846-7420
 TOLP LEAD SW846-1311/7420

Graphite Furnace Atomic Absorption
 Air, NIOSH 7105
 Wastewater, SW846-7421
 Soil, SW846-7421
 Drinking Water, EPA 239.2

ICP - Inductively Coupled Plasma
 Wipe, SW846-6010 ASTM non ASTM
 Soil, SW846-6010
 Air, NIOSH 7300

MATERIALS ANALYSIS

Full Particle Identification
 Optical Particle Identification
 Dust Mitas and Insect Fragments
 Particle Size & Distribution
 Product Comparison
 Paint Characterization
 Failure Analysis
 Corrosion Analysis
 Glove Box Containment Study
 Petrographic Examination of Concrete
 Portland Cement in Workplace Atmospheres (OSHA ID-143)
 Man Made Vitrous Fibers - MMVF's
 Synthetic Fiber Identification
 Other:

MICROBIAL ANALYSIS

Air Samples
 Mold & Fungi by Air O Cell
 Mold & Fungi by Agar Plate count & id
 Bacterial Count and Gram Stain
 Bacterial Count and Identification

Water Samples
 Total Coliforms, Fecal Coliforms
 Escherichia Coli, Fecal Streptococcus
 Legionella
 Salmonella
 Giardia and Cryptosporidium

Wipe and Bulk Samples
 Mold & Fungi - Direct Examination
 Mold & Fungi - (Culture follow up to direct examination if necessary)
 Mold & Fungi - Culture (Count & ID)
 Mold & Fungi - Culture (Count only)
 Bacterial Count & Gram Stain
 Bacterial Count & Identification (3 most prominent types)
 Other:

IAQ ANALYSIS

Nuisance Dust (NIOSH 0500 & 0600)
 Airborne Dust (PM10, TSP)
 Silica Analysis by XRD Niosh 7500
 HVAC Efficiency
 Carbon Black
 Airborne Oil Mist
 Other:

RECEIVED
 APR 21 2014
 BY: [Signature] 8:00am
 Dref Bay

Additional Information/Comments/Instructions: ****PLEASE STOP ON 1ST POSITIVE WITHIN SETS**

Client Sample # (S)	4-18-AC-01	4-18-AC-20	TOTAL SAMPLE #
Relinquished:	ANDREW CARNEVALE	Date: 4-18-2014	Time: PM
Received:	NANCY PORTER	Date: 4-18-2014	Time: PM
Relinquished:	NANCY PORTER	Date: 4-18-2014	Time: PM
Received:		Date:	Time:

241401366



EMSL - MA
7 Constitution Way, Ste 107
Woburn, MA 01801
(781) 933-8411
(781) 933-8412 Fax

EMSL - CT
29 N. Plains Hwy, Unit 4
Wallingford, CT 06492
(203) 284-5948
(203) 284-5978 Fax

EMSL - NY
307 West 38th Street
New York, NY 10018
(866) 448-3675
(212) 290-0058 Fax

EMSL - NJ
107 Haddon Avenue
Westmont, NJ 08108
(800) 220-3675
(856) 858-4960 Fax

SAMPLE NUMBER	SAMPLE DESCRIPTION	ROOM or LOCATION	VOLUME Air (L)	Area (Inches sq.)
4-18-AC-01	Cement panel	Crawl Spac		NAD
4-18-AC-02	Cement panel	Crawl Spac		
4-18-AC-03	Paper under siding	Fac C		
4-18-AC-04	Paper under siding	Fac C		
4-18-AC-05	Sheetrock	Living Rm		
4-18-AC-06	Sheetrock	Kitchen		
4-18-AC-07	Joint compound	Kitchen		
4-18-AC-08	Joint compound	Kitchen		
4-18-AC-09	Sheetrock/joint compound composite	Kitchen		
4-18-AC-10	Sheetrock/joint compound composite	Kitchen		
4-18-AC-11	Residual adhesive on wall	Living Rm		
4-18-AC-12	Residual adhesive on wall	Living Rm		
4-18-AC-13	Batting insulation paper	Bedroom 3		
4-18-AC-14	Batting insulation paper	Bedroom 3		
4-18-AC-15	Wood window glazing compound	Fac B		
4-18-AC-16	Wood window glazing compound	Fac B		
4-18-AC-17	Black asphalt shingles	Porch Roof		
4-18-AC-18	Black asphalt shingles	Porch Roof		
4-18-AC-19	Bottom layer shingle	Porch Roof		
4-18-AC-20	Bottom layer shingle	Porch Roof		

RECEIVED
APR 21 2014
By _____

**EMSL Analytical, Inc.**

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
 Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241401366
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 04/21/14 9:00 AM
 Analysis Date: 4/21/2014
 Collected: 4/18/2014

Project: 14-020.12T8/CSA-SUPER STORM SANDY PROJECT, 39 ATTAWAN AVE., NIAN TIC, CT

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
4-18-AC-01 241401366-0001	Crawl Space - cement panel	Gray Non-Fibrous Homogeneous	<1% Fibrous (other)	15% Quartz 20% Ca Carbonate 65% Non-fibrous (other)	None Detected
4-18-AC-02 241401366-0002	Crawl Space - cement panel	Gray Non-Fibrous Homogeneous	<1% Glass <1% Fibrous (other)	20% Quartz 20% Ca Carbonate 60% Non-fibrous (other)	None Detected
4-18-AC-03 241401366-0003	Fac C - paper under siding	Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (other)	None Detected
4-18-AC-04 241401366-0004	Fac C - paper under siding	Black Non-Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (other)	None Detected
4-18-AC-05 241401366-0005	Living Rm - sheetrock	White Fibrous Homogeneous	<1% Cellulose	25% Gypsum 75% Non-fibrous (other)	None Detected
4-18-AC-06 241401366-0006	Kitchen - sheetrock	White Fibrous Homogeneous	<1% Cellulose	30% Gypsum 70% Non-fibrous (other)	None Detected
4-18-AC-07 241401366-0007	Kitchen - joint compound	White Non-Fibrous Homogeneous		30% Ca Carbonate 70% Non-fibrous (other)	None Detected
4-18-AC-08 241401366-0008	Kitchen - joint compound	White Non-Fibrous Homogeneous		35% Ca Carbonate 65% Non-fibrous (other)	None Detected

Analyst(s)

Edward Leary (20)

Gloria V. Oriol, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, bulk materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0.

Initial report from 04/21/2014 17:49:50

**EMSL Analytical, Inc.**

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
 Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241401366
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 04/21/14 9:00 AM
 Analysis Date: 4/21/2014
 Collected: 4/18/2014

Project: 14-020.12T8/CSA-SUPER STORM SANDY PROJECT, 39 ATTAWAN AVE., NIANTIC, CT

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
4-18-AC-09 241401366-0009	Kitchen - sheetrock/joint compound composite	Gray/White Fibrous Homogeneous	<1% Cellulose	20% Gypsum 10% Ca Carbonate 70% Non-fibrous (other)	None Detected
4-18-AC-10 241401366-0010	Kitchen - sheetrock/joint compound composite	Gray/White Fibrous Homogeneous	<1% Cellulose	25% Gypsum 12% Ca Carbonate 63% Non-fibrous (other)	None Detected
4-18-AC-11 241401366-0011	Living Rm - residual adhesive on wall	Brown Non-Fibrous Homogeneous	15% Cellulose	85% Non-fibrous (other)	None Detected
4-18-AC-12 241401366-0012	Living Rm - residual adhesive on wall	Brown Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected
4-18-AC-13 241401366-0013	Bedroom 3 - batting insulation paper	Brown/Black Fibrous Homogeneous	30% Min. Wool 50% Cellulose	20% Non-fibrous (other)	None Detected
4-18-AC-14 241401366-0014	Bedroom 3 - batting insulation paper	Brown/Black Fibrous Homogeneous	60% Cellulose 20% Min. Wool	20% Non-fibrous (other)	None Detected
4-18-AC-15 241401366-0015	Fac B - wood window glazing compound	Tan Non-Fibrous Homogeneous	<1% Fibrous (other)	10% Ca Carbonate 90% Non-fibrous (other)	None Detected
4-18-AC-16 241401366-0016	Fac B - wood window glazing compound	Tan Non-Fibrous Homogeneous	<1% Fibrous (other)	15% Ca Carbonate 85% Non-fibrous (other)	None Detected

Analyst(s)

Edward Leary (20)

Gloria V. Oriol, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-fragile organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0,

Initial report from 04/21/2014 17:49:50



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241401366
CustomerID: EEVM50
CustomerPO:
ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
Fax: (860) 585-7034
Received: 04/21/14 9:00 AM
Analysis Date: 4/21/2014
Collected: 4/18/2014

Project: 14-020.12T8/CSA-SUPER STORM SANDY PROJECT, 39 ATTAWAN AVE., NIAN TIC, CT

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
4-18-AC-17 241401366-0017	Porch Roof - black asphalt shingles	White/Black Fibrous Homogeneous	40% Cellulose	60% Non-fibrous (other)	None Detected
4-18-AC-18 241401366-0018	Porch Roof - black asphalt shingles	White/Black Fibrous Homogeneous	30% Cellulose	70% Non-fibrous (other)	None Detected
4-18-AC-19 241401366-0019	Porch Roof - bottom layer shingle	Black Fibrous Homogeneous	45% Cellulose	55% Non-fibrous (other)	None Detected
4-18-AC-20 241401366-0020	Porch Roof - bottom layer shingle	Black Fibrous Homogeneous	55% Cellulose	45% Non-fibrous (other)	None Detected

Analyst(s)

Edward Leary (20)

Gloria V. Oriol, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-fragile organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0,

Initial report from 04/21/2014 17:49:50

APPENDIX 3

XRF LEAD-BASED PAINT INSPECTION REPORTS

LEAD PAINT INSPECTION REPORT

REPORT NUMBER: S#02753 - 04/18/14 10:39

INSPECTION FOR: Mr. David Holmes
Capital Studio Architects
1379 Main Street
East Hartford, CT 06108

PERFORMED AT: 39 Attawan Avenue
Niantic, Connecticut
Various Areas

INSPECTION DATE: 04/18/14

INSTRUMENT TYPE: R M D
MODEL LPA-1
XRF TYPE ANALYZER
Serial Number: 02753

ACTION LEVEL: 1.0 mg/cm²

OPERATOR LICENSE: 002244

A lead-based paint screen was performed in various water damaged areas at 39 Attawan Avenue located in Niantic, Connecticut

SIGNED: _____



Hannah Flintz
Lead Inspector/Risk Assessor
Eagle Environmental, Inc.
8 South Main Street, Suite 3
Terryville, CT 06786

Date: _____

4/18/14

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Inspection Date: 04/18/14 39 Attawan Avenue
 Report Date: 4/18/2014 Niantic, Connecticut
 Abatement Level: 1.0 Various Areas
 Report No. S#02753 - 04/18/14 10:39
 Total Readings: 48 Actionable: 12
 Job Started: 04/18/14 10:39
 Job Finished: 04/18/14 14:03

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Exterior Room 001 Facade D									
006	B	Clapboard	Lft		P	Wood	White	7.0	QM
004	D	Clapboard	Ctr		P	Wood	White	8.6	QM
005	D	Clapboard	Ctr		P	Wood	red	1.2	QM
007	D	Window	Ctr	Casing	P	Wood	blue	3.0	QM
008	D	Window	Ctr	Sill	P	Wood	blue	4.1	QM
Interior Room 001 Sun Room									
012	B	Box beam	Lft		P	Wood	White	>9.9	QM
009	B	Window	Lft	Mullion	P	Wood	White	>9.9	QM
011	B	Window	Lft	Casing	P	Wood	White	>9.9	QM
013	D	Window	Ctr	Rgt casing	P	Wood	White	>9.9	QM
Interior Room 006 Bedroom 3									
024	D	Window	Rgt	Jamb	P	Wood	White	1.0	QM
026	D	Window	Rgt	Sash	P	Wood	White	6.1	QM
025	D	Window	Rgt	Well	P	Wood	White	7.5	QM
Exterior Room 999									
Calibration Readings									

---- End of Readings ----

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Inspection Date: 04/18/14 39 Attawan Avenue
 Report Date: 4/18/2014 Niantic, Connecticut
 Abatement Level: 1.0 Various Areas
 Report No. S#02753 - 04/18/14 10:39
 Total Readings: 48
 Job Started: 04/18/14 10:39
 Job Finished: 04/18/14 14:03

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Exterior Room 001 Facade D									
006	B	Clapboard	Lft		P	Wood	White	7.0	QM
004	D	Clapboard	Ctr		P	Wood	White	8.6	QM
005	D	Clapboard	Ctr		P	Wood	red	1.2	QM
007	D	Window	Ctr	Casing	P	Wood	blue	3.0	QM
008	D	Window	Ctr	Sill	P	Wood	blue	4.1	QM
Exterior Room 003 Fr Porch									
039	-	Box Beam	Ctr		P	Wood	White	0.2	QM
041	-	Floor	Lft		P	Wood	No Paint	0.0	QM
040	A	Crown Mldg	Ctr		P	Wood	White	-0.2	QM
045	A	Fascia	Rgt		P	Wood	White	-0.3	QM
042	A	Door	Rgt	Casing	P	Wood	White	-0.1	QM
043	A	Door	Rgt	threshold	P	Wood	White	-0.2	QM
044	A	Door	Rgt	Kick plate	P	Wood	White	0.0	QM
035	A	Stairs	Rgt	Stringers	P	Wood	White	-0.1	QM
036	A	Stairs	Rgt	Treads	P	Wood	No Paint	-0.1	QM
037	A	Stairs	Rgt	Risers	P	Wood	No Paint	0.0	QM
038	A	Railing	Rgt	Railing	P	Wood	White	0.0	QM
027	D	Window	Ctr	Casing	P	Wood	stain	-0.2	QM
028	D	Window	Ctr	Sash	P	Wood	stain	0.1	QM
030	D	Window	Ctr	Apron	P	Wood	stain	-0.1	QM
029	D	Window	Ctr	Sill	P	Wood	stain	-0.1	QM
Interior Room 001 Sun Room									
012	B	Box beam	Lft		P	Wood	White	>9.9	QM
009	B	Window	Lft	Mullion	P	Wood	White	>9.9	QM
010	B	Window	Lft	Stop	P	Wood	White	-0.4	QM
011	B	Window	Lft	Casing	P	Wood	White	>9.9	QM
013	D	Window	Ctr	Rgt casing	P	Wood	White	>9.9	QM
031	D	Win. Stop	Ctr		P	Wood	Stain	0.0	QM
Interior Room 002 Kitchen									
020	B	Wall	Ctr		P	Dry Wall	Blue	-0.1	QM
Interior Room 003 Living Rm									
014	D	Wall	Ctr		P	Wood	stain	-0.4	QM
015	D	Window	Ctr	Casing	P	Wood	stain	-0.3	QM
016	D	Window	Ctr	Stop	P	Wood	stain	-0.1	QM
017	D	Window	Ctr	Sash	P	Wood	stain	-0.1	QM
018	D	Window	Ctr	Apron	P	Wood	stain	-0.1	QM
019	D	Window	Ctr	Sill	P	Wood	stain	0.2	QM

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Interior Room 004 Bedroom 1									
021	A	Window	Lft	Casing	P	Wood	green	-0.2	QM
Comment: Walls are unpainted									
Interior Room 005 Bedroom 2									
023	A	Wall	Rgt		P	Panel	stain	-0.1	QM
022	A	Window	Rgt	Casing	P	Wood	stain	-0.1	QM
Comment: Walls are unpainted									
Interior Room 006 Bedroom 3									
024	D	Window	Rgt	Jamb	P	Wood	White	1.0	QM
026	D	Window	Rgt	Sash	P	Wood	White	6.1	QM
025	D	Window	Rgt	Well	P	Wood	White	7.5	QM
Exterior Room 999									
001								1.1	TC
002								1.0	TC
003								1.0	TC
032								1.0	TC
033								1.1	TC
034								1.0	TC
046								1.1	TC
047								1.1	TC
048								1.0	TC

---- End of Readings ----

LEAD PAINT INSPECTION REPORT

REPORT NUMBER: S#02753 - 06/03/14 11:24

INSPECTION FOR: Mr. David Holmes
Capital Studio Architects
1379 Main Street
East Hartford, CT 06108

PERFORMED AT: 39 Attawan Avenue
Niantic, Connecticut

INSPECTION DATE: 06/03/14

INSTRUMENT TYPE: R M D
MODEL LPA-1
XRF TYPE ANALYZER
Serial Number: 02753

ACTION LEVEL: 1.0 mg/cm²

OPERATOR LICENSE: 002206

A Lead-Based Paint Hazard Screen was performed for the interiors and exteriors of the dwelling.

SIGNED: _____



Kristen Liljehult
Lead Inspector / Risk Assessor
Eagle Environmental, Inc.
8 South Main Street, Suite # 3
Terryville, CT 06786

Date: _____

6/3/14

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Inspection Date: 06/03/14 39 Attawan Avenue
 Report Date: 6/3/2014 Niantic, Connecticut
 Abatement Level: 1.0
 Report No. S#02753 - 06/03/14 11:24
 Total Readings: 71 Actionable: 38
 Job Started: 06/03/14 11:24
 Job Finished: 06/03/14 14:23

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Exterior Room 001 Facade A									
059	A	Window	Rgt	Casing	P	Wood	white	2.5	QM
061	A	Window	Rgt	Sash	P	Wood	white	7.5	QM
060	A	Window	Rgt	Sill	P	Wood	white	1.6	QM
Exterior Room 004 Facade D									
068	D	Facade under vinyl siding	Lft		P	Wood	white	2.2	QM
065	D	Window	Lft	Casing	P	Wood	blue	6.0	QM
067	D	Window	Lft	Sash	P	Wood	white	2.4	QM
066	D	Window	Lft	Sill	P	Wood	blue	1.5	QM
Interior Room 001 Enc. Porch									
019	-	Corner board	Ctr		P	Wood	beige	>9.9	QM
018	-	Floor	Ctr		P	Wood	white	1.5	QM
014	A	Boxbeam	Ctr		P	Wood	beige	>9.9	QM
009	A	Window	Rgt	Casing	P	Wood	beige	8.8	QM
020	B	Column	Ctr		P	Wood	beige	>9.9	QM
004	C	Wall	Ctr		P	Wood	beige	>9.9	QM
022	C	Wall	Ctr		P	Wood	beige	>9.9	QM
006	C	Window	Lft	Casing	P	Wood	white	>9.9	QM
008	C	Window	Lft	Blind stop	P	Wood	beige	3.2	QM
007	C	Window	Lft	Sash	P	Wood	beige	7.7	QM
015	C	Window	Rgt	Sash	P	Wood	beige	7.6	QM
025	C	Door	Lft	Threshold	P	Wood	beige	3.3	QM
005	C	Door	Ctr	Casing	P	Wood	white	>9.9	QM
021	D	Wall	Ctr		P	Wood	beige	>9.9	QM
016	D	Window	Rgt	Sash	P	Wood	white	9.5	QM
017	D	Window	Rgt	Well	P	Wood	white	>9.9	QM
Interior Room 002 Living Rm									
026	A	Door	Ctr	n/a	P	Wood	beige	3.0	QM
028	A	Door	Ctr	Jamb	P	Wood	beige	3.9	QM
029	A	Door	Ctr	Stop	P	Wood	white	8.7	QM
Interior Room 003 Dining Rm									
030	A	Door	Rgt	n/a	P	Wood	beige	>9.9	QM
Interior Room 005 Bath									
039	A	Wall	Ctr		P	Wood	blue	>9.9	QM
042	C	Column	Ctr		P	Wood	blue	>9.9	QM

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Interior Room 006 Rear Entry									
043	A	Wall	Ctr		P	Wood	beige	8.7	QM
047	A	Door	Ctr	Casing	P	Wood	beige	8.3	QM
048	A	Door	Ctr	Threshold	P	Wood	beige	5.0	QM
049	A	Door	Ctr	Kick plate	P	Wood	beige	6.6	QM
Interior Room 012 Bedroom 4									
053	D	Window	Rgt	Jamb	P	Wood	white	2.1	QM
054	D	Window	Rgt	Blind stop	P	Wood	white	3.0	QM
055	D	Window	Rgt	Ext. Sash	P	Wood	white	4.1	QM
051	D	Window	Rgt	Well	P	Wood	white	7.8	QM
052	D	Window	Rgt	Part. bead	P	Wood	white	3.7	QM
Calibration Readings									
---- End of Readings ----									

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Inspection Date: 06/03/14 39 Attawan Avenue
 Report Date: 6/3/2014 Niantic, Connecticut
 Abatement Level: 1.0
 Report No. S#02753 - 06/03/14 11:24
 Total Readings: 71
 Job Started: 06/03/14 11:24
 Job Finished: 06/03/14 14:23

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Exterior Room 001 Facade A									
056	A	Facade	Rgt		P	Wood	beige	-0.1	QM
062	A	Porch	Rgt	Boxbeam	P	Wood	white	-0.2	QM
063	A	Porch	Rgt	Railing	P	Wood	white	-0.4	QM
064	A	Porch	Rgt	Column	P	Wood	white	-0.2	QM
059	A	Window	Rgt	Casing	P	Wood	white	2.5	QM
061	A	Window	Rgt	Sash	P	Wood	white	7.5	QM
060	A	Window	Rgt	Sill	P	Wood	white	1.6	QM
057	A	Door	Rgt	Casing	P	Wood	white	0.0	QM
058	A	Door	Rgt	Kick plate	P	Wood	white	0.1	QM
Exterior Room 004 Facade D									
068	D	Facade	Lft		P	Wood	white	2.2	QM
		under vinyl siding							
065	D	Window	Lft	Casing	P	Wood	blue	6.0	QM
067	D	Window	Lft	Sash	P	Wood	white	2.4	QM
066	D	Window	Lft	Sill	P	Wood	blue	1.5	QM
Interior Room 001 Enc. Porch									
024	-	Ladder	Lft		P	Wood	beige	-0.4	QM
019	-	Corner board	Ctr		P	Wood	beige	>9.9	QM
018	-	Floor	Ctr		P	Wood	white	1.5	QM
014	A	Boxbeam	Ctr		P	Wood	beige	>9.9	QM
009	A	Window	Rgt	Casing	P	Wood	beige	8.8	QM
010	A	Door	Ctr	Casing	P	Wood	beige	-0.1	QM
011	A	Door	Ctr	Jamb	P	Wood	beige	-0.1	QM
012	A	Door	Ctr	Stop	P	Wood	beige	-0.2	QM
013	A	Door	Ctr	Threshold	P	Wood	gray	0.1	QM
020	B	Column	Ctr		P	Wood	beige	>9.9	QM
004	C	Wall	Ctr		P	Wood	beige	>9.9	QM
022	C	Wall	Ctr		P	Wood	beige	>9.9	QM
006	C	Window	Lft	Casing	P	Wood	white	>9.9	QM
008	C	Window	Lft	Blind stop	P	Wood	beige	3.2	QM
007	C	Window	Lft	Sash	P	Wood	beige	7.7	QM
015	C	Window	Rgt	Sash	P	Wood	beige	7.6	QM
025	C	Door	Lft	Threshold	P	Wood	beige	3.3	QM
005	C	Door	Ctr	Casing	P	Wood	white	>9.9	QM
021	D	Wall	Ctr		P	Wood	beige	>9.9	QM
023	D	Baseboard	Ctr		P	Wood	beige	0.3	QM
016	D	Window	Rgt	Sash	P	Wood	white	9.5	QM
017	D	Window	Rgt	Well	P	Wood	white	>9.9	QM

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
Interior Room 002 Living Rm									
026	A	Door	Ctr	n/a	P	Wood	beige	3.0	QM
027	A	Door	Ctr	Casing	P	Wood	no paint	0.0	QM
028	A	Door	Ctr	Jamb	P	Wood	beige	3.9	QM
029	A	Door	Ctr	Stop	P	Wood	white	8.7	QM
Interior Room 003 Dining Rm									
030	A	Door	Rgt	n/a	P	Wood	beige	>9.9	QM
031	A	Door	Rgt	Casing	P	Wood	no paint	0.0	QM
032	A	Door	Rgt	Jamb	P	Wood	no paint	0.1	QM
Interior Room 004 Kitchen									
037	-	Ceiling	Ctr		P	Dry wall	white	-0.2	QM
033	A	Wall	Ctr		P	Dry wall	white	-0.1	QM
038	A	Stairs	Ctr	Outer Wall	P	Wood	white	-0.1	QM
034	B	Wall	Ctr		P	Dry wall	white	-0.3	QM
035	C	Wall	Ctr		P	Dry wall	white	-0.2	QM
036	D	Wall	Ctr		P	Dry wall	white	-0.3	QM
Interior Room 005 Bath									
039	A	Wall	Ctr		P	Wood	blue	>9.9	QM
042	C	Column	Ctr		P	Wood	blue	>9.9	QM
040	D	Door	Ctr	n/a	P	Wood	blue	-0.4	QM
041	D	Door	Ctr	Jamb	P	Wood	blue	-0.1	QM
Interior Room 006 Rear Entry									
045	-	Floor	Ctr		P	Wood	blue	-0.3	QM
046	-	Floor	Ctr		P	Wood	blue	0.1	QM
043	A	Wall	Ctr		P	Wood	beige	8.7	QM
047	A	Door	Ctr	Casing	P	Wood	beige	8.3	QM
048	A	Door	Ctr	Threshold	P	Wood	beige	5.0	QM
049	A	Door	Ctr	Kick plate	P	Wood	beige	6.6	QM
044	B	Wall	Ctr		P	Wood	beige	0.6	QM
Interior Room 011 Bath									
050	C	Pipe	Rgt		P	Metal	white	0.7	TC
Interior Room 012 Bedroom 4									
053	D	Window	Rgt	Jamb	P	Wood	white	2.1	QM
054	D	Window	Rgt	Blind stop	P	Wood	white	3.0	QM
055	D	Window	Rgt	Ext. Sash	P	Wood	white	4.1	QM
051	D	Window	Rgt	Well	P	Wood	white	7.8	QM
052	D	Window	Rgt	Part. bead	P	Wood	white	3.7	QM
Calibration Readings									
001								1.1	TC
002								1.0	TC
003								1.0	TC
069								0.8	TC

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
070								1.1	TC
071								1.1	TC
----- End of Readings -----									

APPENDIX 4

LEAD-BASED PAINT VISUAL ASSESSMENT FORMS



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 39 Attawan Avenue, Niantic, CT

Room No: Enclosed Porch 001

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	I F P	carpet - I mod floor - XRF	
Wall	A B C D	I F P	XRF "C" wall - ch powder/shingles	
Ceiling	A B C D	I F P	insulation	
Door	A B C D	I F P		
Door Casing	A B C D	I F P	XRF ⊖	
Door Jamb	A B C D	I F P	XRF ⊖	
Baseboard	A B C D	I F P		
Window Casing	A B C D	I F P		
Window Stop	A B C D	I F P	vinyl window systems	
Window Jamb	A B C D	I F P	on "A" B"	
Window Sash	A B C D	I F P	orig wood win.	
Window Well	A B C D	I F P	"C, D"	
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P	XRF	
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
Fix Beam	A B C D	I F P	XRF ⊖	
Columns	A B C D	I F P	XRF ⊖	
Window systems	A B C D	I F P	XRF	
Window trim	A B C D	I F P	XRF	
Door Stop	A B C D	I F P	XRF ⊖	
Door covered open	A B C D	I F P	XRF ⊖	
Door Threshold covered	A B C D	I F P	XRF ⊖	
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 39 Attawan Avenue, Niantic, CT

Room No: Kitchen 004

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	I F P	vinyl floor tiles/plywood	
Wall	(A) (B) (C) (D)	I F (P)	XRFE	
Ceiling	A B C D	I F (P)	XRFE	
Door	A B C D	I F P	n/a	
Door Casing	(A) (B) (C) D	(I) F P	no paint	
Door Jamb	A B C D	I F P	n/a	
Baseboard	A B C D	I F P	n/a	
Window Casing	A (B) (C) D	(I) F P		
Window Stop	A (B) (C) D	(I) F P		
Window Jamb	A B C D	I F P	vinyl replacements	
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A (B) (C) D	(I) F P		
Window Apron	A (B) (C) D	(I) F P		
Closet Door	A B C (D)	(I) F P		
Closet Door Casing	A B C (D)	(I) F P		
Closet Door Jamb	A B C (D)	(I) F P		
Closet Shelf	A B C (D)	(I) F P		
Shelf Support	A B C (D)	(I) F P		
Radiator	A B C D	(I) F P		
Crown Molding	A B C D	I F P		
Cabinet	(A) (B) (C) D	(I) F P		
Cabinet Door	(A) (B) (C) D	(I) F P		
Cabinet Frame	(A) (B) (C) D	(I) F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 39 Attawan Avenue, Niantic, CT

Room No: Hallway 014

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	① F P		
Wall	A B C D	① F P	Hard wood	
Ceiling	A B C D	① F P		
Door	A B C D	I F P		
Door Casing	A B C D	① F P		
Door Jamb	A B C D	I F P		
Baseboard	A B C D	I F P	n/a	
Window Casing	A B C D	I F P	↓	
Window Stop	A B C D	I F P		
Window Jamb	A B C D	I F P		
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
stair treads	A B C D	① F P	↓	
risers	A B C D	① F P		
handrail	A B C D	① F P		
well	A B C D	① F P		
ceiling	A B C D	① F P	sheetrock	
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 39 Attawan Avenue, Niantic, CT

Room No: Mud Room 006

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	I F (P)	XRF ⊖	
Wall	A B C D	I F (P)	XRF "A" (wall cladding) ⊕	
Ceiling	A B C D	I F P	Insulation - Asbestos ceiling joists ⊕	
Door	A B (C) D	(I) F P		
Door Casing	(A) B C D	I F (P)	XRF ⊕	
Door Jamb	A B (C) D	(I) F P		
Baseboard	A B C D	I F P	n/a	
Window Casing	A B C D	I F P		
Window Stop	A B C D	I F P		
Window Jamb	A B C D	I F P		
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P	↓	
Door Thresh	(A) B C D	I F (P)	XRF ⊕	
Door Kickplate	(A) B C D	I F (P)	XRF ⊕	
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		

APPENDIX 5
TCLP SAMPLE LABORATORY REPORTS AND
COMPUTATION TABLES



Thursday, November 13, 2014

Attn: Mr. Peter Folino
Eagle Environmental Inc.
8 South Main Street, Suite 3 ©
Terryville CT 06786

Project ID: CSA-39 ATTAWAN AVE., NIAN TIC
Sample ID#s: BH38529

This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.

This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,

A handwritten signature in cursive script that reads "Phyllis Shiller".

Phyllis Shiller
Laboratory Director

NELAC - #NY11301
CT Lab Registration #PH-0618
MA Lab Registration #MA-CT-007
ME Lab Registration #CT-007
NH Lab Registration #213693-A,B

NJ Lab Registration #CT-003
NY Lab Registration #11301
PA Lab Registration #68-03530
RI Lab Registration #63
VT Lab Registration #VT11301



Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

Analysis Report
November 13, 2014

FOR: Attn: Mr. Peter Folino
Eagle Environmental Inc.
8 South Main Street, Suite 3 ©
Terryville CT 06786

Sample Information

Matrix: SOLID
Location Code: EAGLEENV
Rush Request: Standard
P.O.#: 14-028-12T10

Custody Information

Collected by: KL
Received by: LB
Analyzed by: see "By" below

Date

11/06/14
11/10/14

Time

0:00
13:23

Laboratory Data

SDG ID: GBH38529
Phoenix ID: BH38529

Project ID: CSA-39 ATTAWAN AVE., NIAN TIC
Client ID: COMPOSITE

Parameter	Result	RL/ PQL	Units	Date/Time	By	Reference
TCLP Lead	12.0	0.10	mg/L	11/12/14	LK	SW6010
TCLP Metals Digestion	Completed			11/11/14	I/I	SW3005
TCLP Extraction for Metals	Completed			11/10/14	I	EPA 1311
TCLP Sample Size Reduction	Completed			11/10/14	SHOP	1311

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level

Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director

November 13, 2014

Reviewed and Released by: Greg Lawrence, Assistant Lab Director



Environmental Laboratories, Inc.
 587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
 Tel. (860) 645-1102 Fax (860) 645-0823

QA/QC Report

November 13, 2014

QA/QC Data

SDG I.D.: GBH38529

Parameter	Blank	Sample Result	Dup Result	Dup RPD	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits
QA/QC Batch 291889, QC Sample No: BH38558 (BH38529)												
ICP Metals - TCLP Extraction												
Lead	BRL	0.600	0.638	6.10	114	106	7.3	109	106	2.8	75 - 125	20

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

- RPD - Relative Percent Difference
- LCS - Laboratory Control Sample
- LCSD - Laboratory Control Sample Duplicate
- MS - Matrix Spike
- MS Dup - Matrix Spike Duplicate
- NC - No Criteria
- Intf - Interference

Phyllis Shiller, Laboratory Director
 November 13, 2014

Thursday, November 13, 2014

Page 1 of 1

Criteria: None

State: CT

Sample Criteria Exceedences Report

GBH38529 - EAGLEENV

SampleNo	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL	Analysis Units
BH38529	TCLP-PB	TCLP Lead	EPA / 40 CFR 261.24 / Toxicity Characteristics	12.0	0.10	5	5	mg/L

Phoenix Laboratories does not assume responsibility for the data contained in this report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

TABLE E

DEMOLITION WASTE CLASSIFICATION
 TCLP FIELD COMPUTATION TABLE
 39 ATTAWAN AVENUE
 NIAN TIC, CONNECTICUT

Component	Thickness (ft)	Thickness (ft)	Area (SF)	Volume (CF)	Density (lbs/CF)	Mass (lbs)	Totals (lbs)	Percent of Total Mass
Negative Wood (solid)	0.50	0.042	12685	528.5	35	18499.0	48219.8	80%
	0.75	0.063		0.0	35	0.0		
	1.00	0.083		0.0	35	0.0		
	1.50	0.125		0.0	35	0.0		
	2.00	0.167	3195	532.5	35	18637.5		
	4.00	0.333	950	316.7	35	11083.3		
	0.00	0.000		0.0	35	0.0		
Positive Wood (solid)	0.50	0.042	2835	118.1	35	4134.4	5041.5	9%
	0.75	0.063	340	21.3	35	743.8		
	1.00	0.083		0.0	35	0.0		
	1.50	0.125		0.0	35	0.0		
	2.00	0.167	28	4.7	35	163.3		
	4.00	0.333		0.0	35	0.0		
	0.00	0.000		0.0	35	0.0		
Negative Sheetrock	0.50	0.042	1100	45.8	52.8	2420.0	2420.0	4%
Glass	0.25	0.021	378	7.9	161	1267.9	1267.9	2%
Roofing	0.50	0.042	1650	68.8	45	3093.8	3093.8	5%
Total Mass							60042.9	100%

APPENDIX 6

RADON TESTING REPORTS

**RADON TESTING WAS NOT PERFORMED AT THE TIME OF INSPECTION AS THE
BUILDING IS SCHEDULED TO BE DEMOLISHED**

APPENDIX 7
MOLD INSPECTION FORMS



MOLD OBSERVATION FORM

Eagle Project No: 14-026-12710 Date: 4/18/14 Inspector: HH

Facility Address: 39 Attawan Ave, Niantic

Location	Observation	Sample Number
	No mold was observed at the	
	time of the inspection	



MOLD MOISTURE READING FORM

Eagle Project No: 14-028-12T10 Date: 4/18/14 Inspector: HH

Facility Address: _____

MOISTURE MODE						
ROOM	COMPONENT	SUBSTRATE	REL. SURFACE MOISTURE	DRY	AT RISK	WET
Kitchen	Wall	Sheetrock Wall	12.2 RH	✓		
Sun Rm	Wall	Sheetrock	11.7	✓		
Kitchen	Floor	Wood	11.8	✓		
bed Rm	Window	Wood	13.4	✓		
bed Rm 2	Window	Wood	13.6	✓		
Crawl	Joist	Wood	11.7	✓		

HYGROMETER MODE				
TIME	ROOM	% RELATIVE HUMIDITY	AIR TEMP.	DEW POINT TEMP.
10:50	Kitchen	28.8	64.6	30.7
10:54	Sun Rm	28.6	64	30.2
10:56	Kitchen	27.5	64.4	30.7
11:00	bed Rm	30.5	66.0	31.2
11:02	Bed 2	28.0	68.5	32.2
11:04	Crawl	40.2	52.7	29.1

APPENDIX 8
ABATEMENT AND CONSULTING
COST ESTIMATES

HAZARDOUS MATERIALS ABATEMENT COST ESTIMATES

APPLICATION NO. 1939
39 ATTAWAN AVENUE
NIANTIC, CONNECTICUT

ASBESTOS ABATEMENT COST ESTIMATE

MATERIAL	QUANTITY	UNIT COST	TOTAL COST
FLOOR TILE	60	\$ 25.00 SF	\$ 1,500.00
CAULK	54	\$ 18.00 LF	\$ 972.00
ROOF FLASHING CEMENT	40	\$ 6.00 LF	\$ 240.00
SUBTOTAL			\$ 2,712.00
ASBESTOS ABATEMENT CONTINGENCY			\$ 271.20
ASBESTOS TOTAL			\$ 2,983.20

LEAD BASED PAINT COST ESTIMATE

MATERIAL	QUANTITY	UNIT COST	TOTAL COST
LEAD-BASED PAINT SIDING REMOVAL	2,835	\$ 4.00 SF	\$ 11,340.00
SIDING DISPOSAL (HAZARDOUS LEAD WASTE)	45	\$ 385.00 YRD	\$ 17,325.00
SUBTOTAL			\$ 28,665.00
LEAD RENOVATION CONTINGENCY			\$ 5,733.00
LEAD RENOVATION TOTAL			\$ 34,398.00

HAZARDOUS MATERIALS ABATEMENT SUBTOTAL \$ 37,381.20

HAZARDOUS MATERIALS CONSULTING COST ESTIMATE

CONSULTING COST	QUANTITY	UNIT COST	TOTAL COST
HAZARDOUS MATERIALS CONSULTING CONTIN.	1	\$1,000.00 EACH	\$ 1,000.00
SUBTOTAL			\$ 1,000.00
CONSULTING CONTINGENCY			\$ 100.00
CONSULTING TOTAL			\$ 1,100.00

GRAND TOTAL \$ 38,481.20

APPENDIX 9
EAGLE ENVIROMENTAL, INC. LICENSES AND
LABORATORY CERTIFICATES

Certificate of Training

Awarded to

ANDREW CARNEVALE

For successful completion of a 4 Hour, 1/2 Day
**Asbestos Building Inspector
Annual Refresher Training**
January 2, 2014

This training was approved and given in accordance with the
Regulations for Connecticut State Agencies
RCSA 20-440-1-9 and RCSA 20-441 and meets the
requirements of the EPA Revised MAP under TSCA Title II of 4/4/94.

Presented by


Mystic Air Quality Consultants, Inc.
1204 North Road, Groton, CT 06340 (800) 247-7746


Certificate Number: ABIRF22726

Exam Grade: 100

Expiration Date: 01/02/2015

Exam Date: 01/02/2014



Christopher J. Eident, CIH, CSP, RS


George Williamson, Training Director
Richard Haffey, Training Director

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A
ASBESTOS CONSULTANT INSPECTOR

ANDREW C. CARNEVALE

LICENSE NO.
000850
CURRENT THROUGH
10/31/14
VALIDATION NO.
08-702940


SIGNATURE


COMMISSIONER

CERTIFICATE OF ACHIEVEMENT

This certifies that

Hannah Hintz

45 Frederick Street, Bristol, CT 06010
000-00-0583

has successfully completed the


INSPECTOR RISK ASSESSOR REFRESHER

Training Course

conducted by

Cardio ATC

73 William Franks Drive
West Springfield, MA 01089
(413) 781-0070




Principal Instructor

October 2, 2013
Date of Course

CTLRAR 354
Certificate Number

October 2, 2013
Exam Date

October 2, 2014
Expiration Date



Training Manager

Training received complies with the requirements of the
Connecticut Department of Public Health pursuant to Section 2-477 of the Connecticut General Statutes.

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A

LEAD INSPECTOR RISK ASSESSOR

HANNAH E. HINTZ

SIGNATURE

CERTIFICATION NO.
002244
CURRENT THROUGH
06/30/14
VALIDATION NO.
03-523637

COMMISSIONER

State of Connecticut, Department of Public Health

Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

EMSL ANALYTICAL, INC. - MANHATTAN, NY

LOCATED AT 307 West 38th Street IN New York, NY 10018

AND REGISTERED IN THE NAME OF Peter Frasca, Ph.D.

THIS CERTIFICATE IS ISSUED IN THE NAME OF James Hall WHO HAS BEEN DESIGNATED BY THE REGISTERED OWNER/AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF APPROVAL AS FOLLOWS:

ASBESTOS

Examination For:

- Bulk - Identification (PLM, TEM)
- Air - Fiber Counting (PCM, TEM)
- Water - TEM


Environmental Health & Housing

Examination For:

- Lead in Paint
- Lead Paint in Soil
- Lead in Dust Wipes

SEE COMPUTER PRINT-OUT FOR SPECIFIC TESTS APPROVED

THIS CERTIFICATE EXPIRES September 30, 2014 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH DATED AT HARTFORD, CONNECTICUT, THIS 4th DAY OF October, 2012



Registration No.

PH-0170

SUZANNE BLANCAFLOR, MS
CHIEF, ENVIRONMENTAL HEALTH SECTION