



Facility Support Services, LLC

Environmental & Safety Consulting Engineers

**Connecticut Department of Housing
Community Development Block Grant – Disaster Recovery
Owner Occupied Recovery and Rehabilitation Program**

**Hazardous Materials
Inspection Report**

**896-898 Howard Avenue
Bridgeport, Connecticut**

PREPARED FOR:

Martinez Couch & Associates, LLC
1084 Cromwell Ave. Suite A-2
Rocky Hill, CT 06067

PREPARED BY:

Facility Support Services, LLC
2685 State Street
Hamden, CT 06517
Phone (203) 288-1281

October 13, 2014

FSS #22214-2149

SIGNATURES OF REPORT AUTHORS

The employees of Facility Support Services, LLC whose names appear below prepared this report. Requests for information on the content of this document should be directed to these individuals.



Kevin S. Bogue, LEP, CHMM
Project Manager
CTDPH Asbestos Inspector #000157

TABLE OF CONTENTS

Section	Page
I. Introduction.....	1
II. Mold.....	1
III. Asbestos	3
IV. Radon	4
V. PCBs	5
VI. Lead.....	6
VII. Conclusions & Recommendations.....	7

TABLES

Table 1	Summary of Laboratory Analysis of Spore Types
Table 2	Summary of Laboratory Analysis of Radon

ATTACHMENTS

Attachment A	Mold Analytical Data
Attachment B	FSS Licensure
Attachment C	Asbestos Laboratory Analytical Data
Attachment D	Radon Analytical Data
Attachment E	PCB Analytical Data
Attachment F	Lead Report

I. Introduction

Facility Support Services, LLC (FSS) was contracted by Martinez, Couch & Associates, LLC (MCA) to perform a limited scope hazardous materials survey of 896/898 Howard Avenue in Bridgeport, Connecticut (the “Site”). The purpose of this inspection was to identify the presence of asbestos, PCBs, and lead paint and mold in certain building materials proposed for removal/demolition that qualify for the repair/replacement of items damaged by the October 2012 Tropical Storm Sandy under the Connecticut Department of Housing (DOH), Community Development Block Grant – Disaster Recovery Owner Occupied Recovery and Rehabilitation Program. In addition, FSS performed radon testing as required for DOH funded projects.

FSS utilized best industry practices to identify all suspect materials associated with the structures. Any material that has not been identified during this inspection or discovered during renovation/demolition activities must be presumed to be hazardous until such time that samples of the material can be collected and analyzed.

II. Mold

FSS conducted sampling for mold on September 22, 2014. Testing for total spores in air was conducted for the following areas of 896/898 Howard Avenue in Bridgeport, Connecticut to identify concerns with indoor air quality related to mold and fungi:

- Basement (near entrance staircase)
- Basement (near room divider)
- Outside of House

The outside ambient air sample provided a background reference sample (collected from a location in the front yard). Mr. Kevin Bogue of FSS conducted the spore sampling utilizing an air sampling pump and sample media. Air was collected at a rate of 15.0 liters of air per minute. The samples were collected on Air-O-Cell type sampling cartridges located in line with the sampling pump, which ran for 10 minutes at each sampling location.

The spore samples were analyzed by EMSL Analytical of Wallingford, Connecticut for the identification and enumeration of spores (EMSL Method M001). EMSL is a State of Connecticut, Department of Public Health certified laboratory (Accreditation Number 165118). Analytical reports for mold are included in Appendix A.

The analysis for total spore counts is a direct microscopic examination and does not include culturing or growing fungi. Therefore, the results include both viable and non-viable spores. Spore trap results are reported in spores per cubic meter of air.

Table 1
Summary of Laboratory Analysis of Spore Types
896/898 Howard Avenue, Bridgeport, Connecticut

Sample Number & Location	Raw Count	Total Fungi (Count/m ³)	Spore Types Present
20140922_2149_MS1 Basement (near staircase)	585	12,310	Alternaria, Ascospores, Aspergillus/Penicillium, Basidiospores, Chaetomium, Cladosporium, Curvularia, Epicoccum, Ganoderma, Myxomycetes, Pithomyces, Rust, Stachybotrys, Arthrimum
20140922_2149_MS2 Basement (room divider)	1,069	22,470	Alternaria, Ascospores, Aspergillus/Penicillium, Basidiospores, Chaetomium, Cladosporium, Curvularia, Epicoccum, Ganoderma, Myxomycetes, Pithomyces, Stachybotrys
20140922_2149_MS3 Outside	725	15,240	Alternaria, Ascospores, Aspergillus/Penicillium, Basidiospores, Cladosporium, Fusarium, Ganoderma, Myxomycetes, Pithomyces, Rust, Zygomycetes, Cercospora, Polythrincium

The suite of mold spores in the outside sample versus the interior samples are similar. The primary mold species were Aspergillus/Pencillium for the basement samples; Cladosporium for the outside sample.

Basidiospores are associated with forest floors, lawns and plants, and can grow on wood containing products. Basidiospores belong to members of the Phylum Basidiomycota, which includes mushrooms and fungi.

Cladosporium – Cladosporium's natural habitat is dead plant matter, soil and woody plants. In indoor environments, this spore type is found on fiberglass duct liners, paints, and textiles, especially in water damaged buildings. This spore type is associated with hay fever and asthma.

In Connecticut, there are currently no regulatory standards directly governing mold/fungal spore concentrations. Although no standards for mold exist, some information regarding levels have been published, including the following:

Baxter, et al considers mold contamination present in a building when the total mold spore concentration per cubic meter is above 10,000. However in special cases, even low quantitative levels of certain particles or particle types (such as *Penicillium/Aspergillus* spore chains in an un-treated building) may be diagnostic and may indicate a hidden mold reservoir that merits further investigation.

FSS's investigation found total spore concentrations inside the 896/898 Howard Avenue residence of up to 22,470/m³, which is above the 10,000/m³ level noted above.

The American Conference of Government Industrial Hygienists (ACGIH) stated that indoor mold levels are generally less than 1/3 the outdoor level and that when indoor mold is at more than this level remedial action should be taken to find the source of the elevated counts and to clean it up. However, this is a general rule and may be inaccurate and unreliable method for screening buildings for mold. FSS's investigation found a total spore concentration in the interior samples at levels slightly below (by basement entrance) and above the outside sample (middle of basement, near room divider).

III. Asbestos

FSS conducted a limited scope asbestos inspection and bulk sampling on September 22, 2014 of suspect building materials that are proposed for renovations. The inspection was conducted by Kevin Bogue, a State of Connecticut licensed Asbestos Inspector. Mr. Bogue's Connecticut Asbestos Inspectors/Management Planner license is provided in Appendix B.

The following suspect materials were identified during the inspection:

- Yellow mastic beneath grey carpet (basement)
- Yellow/tan linoleum (basement)
- Black mastic associated with yellow/tan linoleum
- Sheetrock
- Sheetrock joint compound
- Roof Shingle (lower)
- Roof Shingle (top)

This asbestos inspection was performed in accordance with the EPA, NESHAP regulations for building renovations and demolition, 40 CFR Part 61, Amended 11/20/1990. The bulk asbestos samples collected during this inspection were delivered under full chain of custody and analyzed by EMSL Analytical, Inc., via EPA/600/R-93/116. This is currently the approved EPA test method, which uses Polarized Light Microscopy (PLM). EMSL Analytical, Inc. is an accredited asbestos laboratory (NVLAP # 200700-0) and is a State of Connecticut approved public health laboratory for asbestos analysis. Copies of the laboratory analytical results can be found in Attachment C of this report.

Laboratory results have revealed that the asbestos content of the tested materials are below the 1% required to confirm a material as asbestos containing.

IV. Radon

Initial radon testing was conducted by Mr. Kevin Bogue. Test results were obtained by using a passive activated charcoal device manufactured and analyzed by Radon Testing Corporation of America of Elmsford, New York. The test devices are individually numbered and marked with a bar code for identification (RTCA 4 Pass Charcoal Canister, NRSB Device Code 10331).

Devices were placed in the basement level of the residence on September 22, 2014. The sampling devices was placed on tables with a yellow “Do Not Disturb Test in Progress” warning sign placed beneath the test device. The homeowner was reminded to

not open windows or to allow anyone to tamper with the test device. Testing time was approximately 7 days.

The Radon canister was submitted to Radon Testing Corporation of America for analysis. The analytical result for the samples as shown on Table 1 below. The EPA action level established for Radon is 4.0 pCi/L. Analytical result reports are included in Appendix D.

Table 2
Summary of Laboratory Analysis of Radon
110 East Rocks Road, Norwalk, Connecticut

Canister ID#	Location	Radon Concentration (pCi/L)
June 22-29, 2014		
2333070	Basement (room divider)	1.0
2343052	Basement (refrigerator)	1.4

V. PCBs

Following an inspection of building materials proposed for renovations, two suspected PCB-containing materials were identified.

- Yellow mastic beneath grey carpet (basement)
- Black mastic associated with yellow/tan linoleum

FSS collected a sample of these materials for laboratory analysis for PCBs by EPA Method 8082A with Soxhlet Extraction. Complete Environmental Testing of Stratford, Connecticut was utilized to conduct the analysis.

Laboratory data indicates that the PCB content of the sampled materials was below detectable levels (<0.80 ppm and <0.20 ppm) and below the 1 ppm action level for PCBs. No further investigations or special disposal requirements (for PCBs) are required for these materials. Laboratory analytical data for PCBs are provided in Appendix E.

VI. Lead

The subject residential structure was built prior to 1978 (in 1922) and therefore the likelihood that lead painted surfaces are present is increased. As a residential structure built prior to 1978 the removal of lead painted materials where a child under 6 is housed, or may visit, would trigger the EPA Renovation, Repair and Painting (RRP) rule. Furthermore, adherence to the requirements of The Lead-Safe Housing Rule (US Department of Housing and Urban development, HUD) are stipulated by the Connecticut Department of Housing (DOH) as part of the Community Development Block Grant – Disaster Recovery Owner Occupied Recovery and Rehabilitation Program.

A building wide XRF inspection was conducted by Maureen Monaco of Gilberto Lead Inspections, LLC (Gilbertco) utilizing a Scitec Map4 Portable X-Ray Fluoroscope Spectrum Analyzer with a Cobalt 57 source. Appendix F contains the Lead Inspection Report. The findings of the investigation determined several areas tested positive for lead based paint ($>1.0 \text{ mg/cm}^2$):

- Front Porch
 - Window Sill
 - Wall
 - Window Trim
 - Clapboard
 - Door Jamb
 - Door Casing
 - Threshold
- Laundry
 - Wall
- Kitchen
 - Wall – Upper
 - Wall
- Bathroom
 - Window Trim
 - Window Stop
- Rear Bedroom
 - Door Jamb
 - Door Casing
 - Window Sill
 - Window Trim
 - Window Stop
 - Closet Door Casing

Non-Intact Materials

A copy of the Gilbertco Lead Inspection Report is provided in Appendix E. Following the HUD Lead-Safe Housing Guidelines, non-intact materials should undergo interim measures to abate the hazard. Non-intact lead containing materials have been identified as the following:

- Front Porch
 - Window Sill
 - Wall
 - Window Trim

Demolition Materials

When toxic wastes are land disposed, contaminated liquid may leach from the waste and pollute ground water. Toxicity is defined through a laboratory procedure called the Toxicity Characteristic Leaching Procedure (TCLP) (Method 1311). The TCLP helps identify wastes likely to leach concentrations of contaminants that may be harmful to human health or the environment. There are no areas that tested positive for lead (regardless of intactness) that are proposed for demolition.

Soils

The lead inspection also included a composite sample of soil from a bare soil area located on the right side of the property. Soil sampling found soils have a lead concentration of 298 ppm, below the 400 ppm action level for lead in soil, and therefore no soil excavation is required.

VII. Conclusions & Recommendations

When the structure is renovated, all removed debris should be sent to an appropriate landfill for final disposal following all appropriate regulations. Any work involving lead-containing paints should be conducted under the EPA's RRP Renovation, Repair and Painting Rule. Any material discovered during renovation activities which have not been included in this survey must be presumed to contain asbestos, lead and PCBs until such time that the material can be evaluated and sampled.

Mold - FSS's investigation found total spore concentrations inside the 896 Howard Avenue residence of up to 22,470/m³. The preponderance of spores in the basement of the residence indicates that mold remediation should be conducted.

Asbestos – No asbestos containing materials (>1% asbestos) were identified in materials proposed for renovation or demolition.

PCBs - Two suspected PCB-containing materials were identified in proposed renovation materials and sampled. Laboratory data indicates that the PCB content of the sampled materials was below detectable levels and below the 1 ppm action level for PCBs. No further investigations or special disposal requirements (for PCBs) are required for these materials.

Radon – Levels of radon were identified in the basement of the residence at levels of 1.0 and 1.4 pCi/L, below the EPA action level of 4.0 pCi/L. No further work related to radon will be required.

Lead - Following the HUD Lead-Safe Housing Guidelines, the non-intact areas should undergo interim measures to abate the hazard. The following areas were non-intact as well as testing positive:

- Front Porch
 - Window Sill
 - Wall
 - Window Trim

There are no areas that tested positive for lead (regardless of intactness) that are proposed for demolition. No further consideration for lead containing demolition debris is required for this project.

The lead inspection also included a composite sample of soil from a bare soil area located on the right side of the property. Soil sampling found soils have a lead concentration of 298 ppm, below the 400 ppm action level for lead in soil, requiring remediation of soils. However, ground cover is recommended to be planted near the perimeter of the house or in water runoff areas. Asphalt, bushes, mulch, or good quality grass covering are acceptable.

ATTACHMENTS

ATTACHMENT A
MOLD ANALYTICAL DATA



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492

Phone/Fax: 203-284-5948 / (203) 284-5978

<http://www.EMSL.com> / wallingfordlab@emsl.com

Order ID: 241403795

Customer ID: FSS93

Customer PO:

Project ID:

Attn: Kevin Bogue
Facility Support Services, LLC
2685 State Street
Hamden, CT 06517

Phone: (203) 288-1281
Fax: (203) 248-4409
Collected: 09/22/2014
Received: 09/24/2014
Analyzed: 09/25/2014

Proj: 22214-2149

Test Report: Air-O-Cell™ Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods EMSL 05-TP-003, ASTM D7391)

Lab Sample Number:	241403795-0001			241403795-0002			241403795-0003		
Client Sample ID:	20140922_2149_MS1			20140922_2149_MS2			20140922_2149_MS3		
Volume (L):	150			150			150		
Sample Location:	Basement #1			Basement #2			Outside		
Spore Types	Raw Count	Count/m ³	% of Total	Raw Count	Count/m ³	% of Total	Raw Count	Count/m ³	% of Total
Alternaria	12	250	2	2	40	0.2	15	320	2.1
Ascospores	74	1600	13	42	890	4	186	3930	25.8
Aspergillus/Penicillium	307	6480	52.6	858	18100	80.6	1	20	0.1
Basidiospores	59	1200	9.8	37	780	3.5	92	1900	12.5
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium	9	200	1.6	9	200	0.9	-	-	-
Cladosporium	39	820	6.7	73	1500	6.7	335	7070	46.4
Curvularia	5	100	0.8	2	40	0.2	-	-	-
Epicoccum	3	60	0.5	2	40	0.2	-	-	-
Fusarium	-	-	-	-	-	-	5	100	0.7
Ganoderma	20	420	3.4	12	250	1.1	21	440	2.9
Myxomycetes++	40	840	6.8	23	490	2.2	40	840	5.5
Pithomyces	5	100	0.8	2	40	0.2	15	320	2.1
Rust	4	80	0.7	-	-	-	4	80	0.5
Scopulariopsis	-	-	-	-	-	-	-	-	-
Stachybotrys	4	80	0.7	7	100	0.4	-	-	-
Torula	-	-	-	-	-	-	-	-	-
Ulocladium	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	4	80	0.5
Arthrinium	4	80	0.7	-	-	-	-	-	-
Cercospora	-	-	-	-	-	-	2	40	0.3
Polythrincium	-	-	-	-	-	-	5	100	0.7
Total Fungi	585	12310	100	1069	22470	100	725	15240	100
Hyphal Fragment	40	840	6.8	17	360	1.6	33	700	4.6
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	6	100	0.8	-	-	-	25	530	3.5
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	2	-	-	2	-	-	-	-
Fibrous Particulate (1-4)	-	2	-	-	2	-	-	-	-
Background (1-5)	-	3	-	-	4	-	-	2	-

Bipolaris++ = Bipolaris/Drechslera/Exserohilum
Myxomycetes++ = Myxomycetes/Periconia/Smut

Gloria V. Oriol, Laboratory Manager
or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

High levels of background particulate can obscure spores and other particulates leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT AIHA-LAP, LLC--EMLAP Lab 165118

Initial report from: 09/25/2014 16:29:41

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Chain of Custody

EMSL Order Number (Lab Use Only):

241403795

Wallingford, CT 06492
PHONE: (203) 284-5948
FAX: (203) 284-5978

Company : Facility Support Services, LLC		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 2685 State Street		Third Party Billing requires written authorization from third party	
City: Hamden	State/Province: CT	Zip/Postal Code: 06517	Country: United States
Report To (Name): Kevin Bogue		Telephone #: 203-288-1281	
Email Address: kbogue.fss@snet.net		Fax #:	Purchase Order:
Project Name/Number: 22214-2149		Please Provide Results: <input type="checkbox"/> FAX <input checked="" type="checkbox"/> E-mail <input type="checkbox"/> Mail	
U.S. State Samples Taken: CT		Connecticut Samples: Commercial <input type="checkbox"/> Residential <input checked="" type="checkbox"/>	

Turnaround Time (TAT) Options* - Please Check

3 Hour
 6 Hour
 24 Hour
 48 Hour
 72 Hour
 96 Hour
 1 Week
 2 Week

*For RUSH TAT's Please Call Ahead to Confirm Lab Hours and Availability. Not all TAT options are valid for every test. Materials Science and IAQ TATs are in Business Days rather than Hours (i.e. 24 Hour = End of Next Business Day)

Asbestos

PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ 8hr. TWA TEM - Air <input type="checkbox"/> 4-4.5hr TAT(AHERA ONLY) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Water Fibers $\geq 10\mu m$ <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	PLM - Bulk <input type="checkbox"/> PLM EPA 600/R-93/116 <input type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> NYS 198.1 (friable-NY) <input type="checkbox"/> NYS 198.6 (non-friable-NY) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/ Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)	TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> EPA Reg. 1 Screening Protocol (Qualitative)
TEM - Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe-ASTM D6480		Other:

Lead (Pb)

Flame Atomic Absorption <input type="checkbox"/> Chips SW846-7000B or AOAC 974.02 <input type="checkbox"/> Soil SW846-7000B/7420 <input type="checkbox"/> Air NIOSH 7082 <input type="checkbox"/> Wastewater SM3111B or SW846-7000B/7420 <input type="checkbox"/> ASTM Wipe SW846-7000B/7420 <input type="checkbox"/> non ASTM Wipe SW846-7000B/7420 <input type="checkbox"/> TCLP SW846-1311/7420/SM 3111B	ICP <input type="checkbox"/> Air NIOSH 7300 Modified <input type="checkbox"/> non ASTM Wipe SW846-6010B or C <input type="checkbox"/> ASTM Wipe SW846-6010B or C <input type="checkbox"/> Soil SW846-6010 B or C <input type="checkbox"/> Waste Water SW846-6010B or C <input type="checkbox"/> TCLP SW846-6010B or C
Graphite Furnace Atomic Absorption <input type="checkbox"/> Soil SW846-7421 <input type="checkbox"/> Wastewater EPA 200.9 <input type="checkbox"/> Air NIOSH 7105 <input type="checkbox"/> Drinking Water EPA 200.9	Other: <input type="checkbox"/>

Materials Science

<input type="checkbox"/> Common Particle ID (large particles) <input type="checkbox"/> Full Particle ID (environmental dust) <input type="checkbox"/> Basic Material ID (solids) <input type="checkbox"/> Advanced Material ID <input type="checkbox"/> Physical Testing (Tensile, Compression) <input type="checkbox"/> Combustion-by-products (soot, char, etc.) <input type="checkbox"/> X-Ray Fluorescence (elem. analysis) <input type="checkbox"/> X-Ray Diffraction (Crystalline Part.) <input type="checkbox"/> MMVF's (Fibrous glass, RCF's) <input type="checkbox"/> Particle Size (sieve/microscopy/laser) <input type="checkbox"/> Combustible Dust <input type="checkbox"/> Petrographic Examination
Other: <input type="checkbox"/>

Microbiology

Wipe and Bulk Samples <input type="checkbox"/> Mold & Fungi - Direct Examination <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi Culture (Genus & Species) <input type="checkbox"/> Bacterial Count & ID (Up to Three Types) <input type="checkbox"/> Bacterial Count & ID (Up to Five Types) <input type="checkbox"/> MRSA <input type="checkbox"/> <i>Pseudomonas aeruginosa</i>	Air Samples <input checked="" type="checkbox"/> Mold & Fungi (Spore Trap) <input type="checkbox"/> Mold & Fungi Culture (Genus Only) <input type="checkbox"/> Mold & Fungi (Genus & Species) <input type="checkbox"/> Bacterial Culture & ID (Up to Three Types) <input type="checkbox"/> Bacterial Culture & ID (Up to Five Types) <input type="checkbox"/> Endotoxin Testing
Water Samples <input type="checkbox"/> Total Coliform & E.coli (P/A) <input type="checkbox"/> Fecal Coliform (SM 9222D) <input type="checkbox"/> Sewage Screen <input type="checkbox"/> Heterotrophic Plate Count (SM 9215)	Real Time Q-PCR (See Analytical Guide for Code) Code: Legionella <input type="checkbox"/> Level 1 <input type="checkbox"/> Level 2 <input type="checkbox"/> Level 3 <input type="checkbox"/> Level 4 Other: <input type="checkbox"/>


IAQ

Nuisance Dust NIOSH <input type="checkbox"/> 0500 <input type="checkbox"/> 0600 Airborne Dust <input type="checkbox"/> PM10 <input type="checkbox"/> TSP Silica Analysis: <input type="checkbox"/> All Species Silica Analysis - Single Species <input type="checkbox"/> Alpha Quartz <input type="checkbox"/> Cristobalite <input type="checkbox"/> Tridymite <input type="checkbox"/> HVAC Efficiency <input type="checkbox"/> Carbon Black <input type="checkbox"/> Airborne Oil Mist Radon Testing: Call for Kit and COC Other: <input type="checkbox"/>
--

**Comments/Special Instructions: *mool; Air-O-Cell*

Client Sample #'s	<i>M1 - M3</i>	Total # of Samples:	
Relinquished (Client):	<i>Kevin Bogue</i>	Date:	<i>9/24/14</i>
Received (Lab):		Date:	

Analysis Completed in Accordance with EMSL's Terms and Conditions located in the Analytical Price Guide



ATTACHMENT B

FSS LIENSURE

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A

ASBESTOS CONSULTANT-INSP/MGMT PLANNER

KEVIN S. BOGUE

CERTIFICATE NO.

000157


CURRENT THROUGH

08/31/15

VALIDATION NO.

03-928515


SIGNATURE


COMMISSIONER

ATTACHMENT C

ASBESTOS LABORATORY ANALYTICAL DATA



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241403790
CustomerID: FSS93
CustomerPO:
ProjectID:

Attn: **Kevin Bogue**
Facility Support Services, LLC
2685 State Street

Hamden, CT 06517

Project: **22214-2149**

Phone: (203) 288-1281
Fax: (203) 248-4409
Received: 09/24/14 9:00 AM
Analysis Date: 9/25/2014
Collected: 9/22/2014

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
20140922_2149_S1 A 241403790-0001	Basement - grey carpet- yellow mastic	Tan Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
20140922_2149_S1 B 241403790-0002	Basement - grey carpet- yellow mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
20140922_2149_S1 C 241403790-0003	Basement - grey carpet- yellow mastic	Yellow Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
20140922_2149_S2 A 241403790-0004	Basement - yellow/tan linoleum	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
This is a composite result of both vinyl and backing layers.					
20140922_2149_S2 B 241403790-0005	Basement - yellow/tan linoleum	Tan Non-Fibrous Homogeneous	<1% Glass	100% Non-fibrous (other)	None Detected
This is a composite result of both vinyl and backing layers.					
20140922_2149_S2 C 241403790-0006	Basement - yellow/tan linoleum	Tan Non-Fibrous Homogeneous	3% Glass	97% Non-fibrous (other)	None Detected
This is a composite result of both vinyl and backing layers.					

Analyst(s)

Kristin Lopez (7)
Lauren Brennan (12)



Gloria V. Oriol, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0.

Initial report from 09/26/2014 08:21:26



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
 Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241403790
 CustomerID: FSS93
 CustomerPO:
 ProjectID:

Attn: **Kevin Bogue**
Facility Support Services, LLC
2685 State Street

Hamden, CT 06517

Phone: (203) 288-1281
 Fax: (203) 248-4409
 Received: 09/24/14 9:00 AM
 Analysis Date: 9/25/2014
 Collected: 9/22/2014

Project: 22214-2149

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
20140922_2149_S3 A 241403790-0007	Basement - yellow/tan linoleum black mastic	Black Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
20140922_2149_S3 B 241403790-0008	Basement - yellow/tan linoleum black mastic	Black Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
20140922_2149_S4 A 241403790-0009	Basement - sheetrock	White Non-Fibrous Homogeneous	5% Cellulose	30% Gypsum 65% Non-fibrous (other)	None Detected
20140922_2149_S4 B 241403790-0010	Basement - sheetrock	White Non-Fibrous Homogeneous	2% Cellulose	30% Gypsum 68% Non-fibrous (other)	None Detected
20140922_2149_S4 C 241403790-0011	Basement - sheetrock	White Fibrous Homogeneous	4% Cellulose	35% Gypsum 61% Non-fibrous (other)	None Detected
20140922_2149_S5 A 241403790-0012	Sheetrock joint compound	White Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
20140922_2149_S5 B 241403790-0013	Sheetrock joint compound	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Analyst(s)
 Kristin Lopez (7)
 Lauren Brennan (12)


 Gloria V. Oriol, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0.

Initial report from 09/26/2014 08:21:26



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4, Wallingford, CT 06492
Phone/Fax: 203-284-5948 / (203) 284-5978
<http://www.EMSL.com> wallingfordlab@emsl.com

EMSL Order: 241403790
CustomerID: FSS93
CustomerPO:
ProjectID:

Attn: **Kevin Bogue**
Facility Support Services, LLC
2685 State Street

Hamden, CT 06517

Project: **22214-2149**

Phone: (203) 288-1281
Fax: (203) 248-4409
Received: 09/24/14 9:00 AM
Analysis Date: 9/25/2014
Collected: 9/22/2014

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
20140922_2149_S6 A 241403790-0014	Black (lower) shingle	Black Fibrous Homogeneous	2% Synthetic 10% Cellulose	88% Non-fibrous (other)	None Detected
20140922_2149_S6 B 241403790-0015	Black (lower) shingle	Black Fibrous Homogeneous	15% Cellulose 2% Synthetic	83% Non-fibrous (other)	None Detected
20140922_2149_S6 C 241403790-0016	Black (lower) shingle	Black Fibrous Homogeneous	20% Cellulose 5% Synthetic	75% Non-fibrous (other)	None Detected
20140922_2149_S7 A 241403790-0017	Brown (top) shingle	Black Fibrous Homogeneous	5% Glass	95% Non-fibrous (other)	None Detected
20140922_2149_S7 B 241403790-0018	Brown (top) shingle	Black Fibrous Homogeneous	4% Glass <1% Synthetic	96% Non-fibrous (other)	None Detected
20140922_2149_S7 C 241403790-0019	Brown (top) shingle	Black Fibrous Homogeneous	10% Glass	90% Non-fibrous (other)	None Detected

Analyst(s)

Kristin Lopez (7)
Lauren Brennan (12)



Gloria V. Oriol, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0.

Initial report from 09/26/2014 08:21:26

ATTACHMENT D
RADON ANALYTICAL DATA

Site Radon Inspection Report

Date : 09/30/2014

Kevin Bogue
FACILITY SUPPORT SVCS., LLC
2685 State Street
Hamden, CT 06517-Client: Anderson
Test Location: 896/898 Howard Ave
Bridgeport, CT 06605-

Individual Canister Results

Canister ID# :	2333070	Test Start :	09/22/2014 @ 13:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	09/29/2014 @ 12:10
Location :	Basement	Received:	09/30/2014 @ 16:36
Radon Level :	1.0 pCi/L	Analyzed:	09/30/2014 @ 14:58
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2343052	Test Start :	09/22/2014 @ 13:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	09/29/2014 @ 12:10
Location :	Basement-Refrige/tor	Received:	09/30/2014 @ 16:36
Radon Level :	1.4 pCi/L	Analyzed:	09/30/2014 @ 14:58
Error for Measurement is: ±	0.2 pCi/L		

The reported results indicate that radon levels in the building tested are below the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends retesting if your living patterns change and you begin occupying a lower level of the building, such as a basement or if major remodeling is done.

General radon information may be obtained by consulting the EPA booklet: A Citizen's Guide to Radon (www.epa.gov/radon/pubs/citguide.html). To request a copy or for further information, please contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.

Andreas C. George
Radon Measurement Specialist
NJ MES 11089Dante Galan
Laboratory DirectorNRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

ATTACHMENT E
PCB ANALYTICAL DATA

80 Lupes Drive
Stratford, CT 06615



Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet1@cetlabs.com

Client: Mr. Kevin Bogue
Facility Support Services
2685 State Street
Hamden, CT 06517

Analytical Report

CET# 4090649

Report Date: October 01, 2014
Project: 22214-2149
Project Number: Bridgeport

Connecticut Laboratory Certificate: PH 0116
Massachusetts laboratory Certificate.: M-CT903



New York Certification: 11982
Rhode Island Certification: 199

CET #:4090649

Project: 22214-2149

Project Number: Bridgeport

SAMPLE SUMMARY

The sample(s) were received at 3.9°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
20140922_2149_P1	4090649-01	Solid	9/22/2014	09/23/2014
20140922_2149_P2	4090649-02	Solid	9/22/2014	09/23/2014

Client Sample ID 20140922_2149_P1

Lab ID: 4090649-01

PCBs by Soxhlet

Method: EPA 8082A

Analyst: CA

Matrix: Solid

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
PCB-1016	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1221	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1232	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1242	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1248	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1254	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1260	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1268	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	
PCB-1262	ND	0.80	4	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:11	

Surrogate: TCMX

72.9 %

50 - 150

B4I2411

09/24/2014

09/26/2014 13:11

Surrogate: DCB

78.4 %

50 - 150

B4I2411

09/24/2014

09/26/2014 13:11

CET #:4090649
 Project: 22214-2149
 Project Number: Bridgeport

Client Sample ID 20140922_2149_P2
Lab ID: 4090649-02

PCBs by Soxhlet
Method: EPA 8082A

Analyst: CA
Matrix: Solid

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
PCB-1016	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1221	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1232	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1242	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1248	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1254	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1260	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1268	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
PCB-1262	ND	0.20	1	EPA 3540C	B4I2411	09/24/2014	09/26/2014 13:30	
<i>Surrogate: TCMX</i>	<i>48.6 %</i>	<i>50 - 150</i>			B4I2411	09/24/2014	<i>09/26/2014 13:30</i>	L
<i>Surrogate: DCB</i>	<i>56.2 %</i>	<i>50 - 150</i>			B4I2411	09/24/2014	<i>09/26/2014 13:30</i>	

CET #:4090649
 Project: 22214-2149
 Project Number: Bridgeport

QUALITY CONTROL SECTION

Batch B4I2411 - EPA 8082A

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B4I2411-BLK1)					Prepared: 9/24/2014 Analyzed: 9/26/2014				
PCB-1016	ND	0.20							
PCB-1221	ND	0.20							
PCB-1232	ND	0.20							
PCB-1242	ND	0.20							
PCB-1248	ND	0.20							
PCB-1254	ND	0.20							
PCB-1260	ND	0.20							
PCB-1268	ND	0.20							
PCB-1262	ND	0.20							
<i>Surrogate: TCMX</i>					70.7	50 - 150			
<i>Surrogate: DCB</i>					80.4	50 - 150			
LCS (B4I2411-BS1)					Prepared: 9/24/2014 Analyzed: 9/26/2014				
PCB-1016	0.842	0.20	1.000		84.2	50 - 150			
PCB-1260	0.901	0.20	1.000		90.1	50 - 150			
<i>Surrogate: TCMX</i>					91.4	50 - 150			
<i>Surrogate: DCB</i>					103	50 - 150			
Duplicate (B4I2411-DUP1)		Source: 4090649-01			Prepared: 9/24/2014 Analyzed: 9/26/2014				
PCB-1016	ND	0.20		ND				50	
PCB-1221	ND	0.20		ND				50	
PCB-1232	ND	0.20		ND				50	
PCB-1242	ND	0.20		ND				50	
PCB-1248	ND	0.20		ND				50	
PCB-1254	ND	0.20		ND				50	
PCB-1260	ND	0.20		ND				50	
PCB-1268	ND	0.20		ND				50	
PCB-1262	ND	0.20		ND				50	
<i>Surrogate: TCMX</i>					42.6	50 - 150			L
<i>Surrogate: DCB</i>					46.0	50 - 150			L

CET #:4090649

Project: 22214-2149

Project Number: Bridgeport

Batch S4I2601 - EPA 8082A

Analyte	Result (ug/L)	RL (ug/L)	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Calibration Check (S4I2601-CCV1)					Prepared: 9/26/2014 Analyzed: 9/26/2014				
PCB-1016	1010		1,000.000		101	80 - 120			
PCB-1260	925		1,000.000		92.5	80 - 120			
<i>Surrogate: TCMX</i>					<i>103</i>	<i>50 - 150</i>			
<i>Surrogate: DCB</i>					<i>92.0</i>	<i>50 - 150</i>			



80 Lupes Drive
Stratford, CT 06615

Tel: (203) 377-9984
Fax: (203) 377-9952
email: cet1@cetlabs.com

Quality Control Definitions and Abbreviations

Internal Standard (IS)	An Analyte added to each sample or sample extract. An internal standard is used to monitor retention time, calculate relative response, and quantify analytes of interest.
Surrogate Recovery	The % recovery for non-tarer organic compounds that are spiked into all samples. Used to determine method performance.
Continuing Calibration Batch	An analytical standard analyzed with each set of samples to verify initial calibration of the system. Samples that are analyzed together with the same method, sequence and lot of reagents within the same time period.
ND	Not detected
RL	Reporting Limit
Dilution	Multiplier added to detection levels (MDL) and/or sample results due to interferences and/or high concentration of target compounds.
Duplicate Result	Result from the duplicate analysis of a sample. Amount of analyte found in a sample.
Spike Level	Amount of analyte added to a sample
Matrix Spike Result	Amount of analyte found including amount that was spiked.
Matrix Spike Dup	Amount of analyte foun in duplicate spikes including amount that was spike.
Matrix Spike % Recovery	% Recovery of spiked amount in sample.
Matrix Spike Dup % Recovery	% Recovery of spiked duplicate amount in sample.
RPD	Relative percent difference between Matrix Spike and Matrix Spike Duplicate.
Blank	Method Blank that has been taken through all steps of the analysis.
LCS % Recovery	Laboratory Control Sample percent recovery. The amount of analyte recovered from a fortified sample.
Recovery Limits	A range within which specified measurements results must fall to be compliant.
CC	Calibration Verification

- Flags:
- H- Recovery is above the control limits
 - L- Recovery is below the control limits
 - B- Compound detected in the Blank
 - P- RPD of dual column results exceeds 40%
 - #- Sample result too high for accurate spike recovery.



Connecticut Laboratory Certification PH0116
Massachussets Laboratory Certification M-CT903

New York Certification 11982
Rhode Island Certification 199

Questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,



David Ditta
Laboratory Director

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at the specified detection limit
All analyses were performed in house unless a Reference Laboratory is listed.
Samples will be disposed of 30 days after the report date.



4090649

COMPLETE ENVIRONMENTAL TESTING, INC.

OF CUSTODY RECORD

Volatile Soils Only:

Date and Time in Freezer

Client:

CET

Additional Analysis

Metals (check all that apply)

Organics

80 Lupes Drive
Stratford, CT 06615
Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet@cetlabs.com

Sample ID	Date/Time	Matrix A=Air S=Soil W=Water DW=Drinking W. C=Cassette Solid Other (Specify)	Turnaround Time ** (check one)			
			Same Day	24 Hours	2-3 Days	Standard
20140922-2149-P1	9/22/14	S&M				X
20140922-2149-P2	9/22/14	S&M				X

8260 CT List	8260 Aromatics	8260 Halogens	SPLP 8260	TCLP 8260	TPH (418.1)	CT ETPH	8270 CT List	8270 PNAS	PCBs (soxhlet)	Pesticides	13 Priority Poll	8 RCRA	TOTAL	TCLP	SPLP	Field Filtered	Lab To Filter
									X								

RECEIVED BY: *KB*
DATE/TIME: 9/22/14
RECEIVED BY: *KB*
DATE/TIME: 9/23/14

Client / Reporting Information

Company Name: Facility Support Services, LLC
Address: 2685 State Street
City: Hamden CT State: CT Zip: 06517

Report To: Kevin Begue
Phone #: 203 206 1281
E-mail: KBegue.FSS@SWET.NET
Fax #: 203 206 1281

Project Information

Project Contact: K. Begue
Project #: 22214
Location: Bridgeport CT
Collector(s): KSB

Lab Use: Evidence of Cooling: 89 °C or N
Temp Upon Receipt: 89 °C
SHEET 1 OF 1

* Additional charge may apply. ** TAT begins when the samples are received at the Lab. TAT for samples received after 3 p.m. will start on the next business day. REV. 5/9/06

ATTACHMENT F

LEAD REPORT



STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

LEAD INSPECTION AND TESTING SUMMARY FORM

This lead inspection and testing summary form must be completed and sent to the property owner of the property in accordance with Section 19a-111-3 (d) of the regulations of Connecticut State Agencies concerning Lead Poisoning Prevention and Control. A Comprehensive Lead Inspection is one performed to satisfy CGS 19a-111 (epidemiological investigation) and CGS 19a-110(d) (on-site inspection). Bare soil areas, dust and water are required to be tested for the presence of lead as part of a comprehensive lead inspection.

PROPERTY INSPECTED/TESTED

(Check): Residence Child Day Care Center/Group Day Care Home Family Day Care Home
Name: _____ Name: _____

(Check One): Comprehensive Lead Inspection Limited Testing

Street Address: 896-898 Howard Ave. Apt.# 2 Floor: 2nd

City/Town: Bridgeport Zip Code: 06605 Telephone: _____

If Apartment, Number of Units: 3-4 Year Property Built: 1910

PROPERTY OWNER

Name: O'Neil and Shena Anderson

Street Address: 896-898 Howard Ave- Second Floor City: Bridgeport

State: CT Zip Code: 06605 Telephone: 203-338-0053

INSPECTING ENTITY

A. If Consultant Contractor:

Name: Gilbertco Lead Inspections LLC

Street Address: 287 Main Street

City: Ansonia State: CT Zip Code: 06401

Consultant License Number: CC 270

Inspector's Name: Maureen Monaco Telephone: 1-800-959-2985

Inspector's Certification Number: IR 1172

B. If Code Enforcement Agency:

Department Name: n/a

Street Address: _____

City: _____ State: _____ Zip Code: _____

Inspector's Name: _____ Telephone: _____

Date of Inspector's Initial Training: ____/____/____ Date of Latest Refresher Training: ____/____/____

INSPECTION INFORMATION

Beginning and End Date(s) of Inspection: 9 / 22 / 14

For each day that the inspection was conducted consent was given by an adult occupant of the dwelling unit to enter and inspect all areas of the dwelling that are under the control of that individual or to which that individual has legitimate access.

Yes No

Name of person 18 years of age or older who granted consent: Shena Anderson Age: 18+ Date: 9/22/14

Name of person 18 years of age or older who granted consent: _____ Age: _____ Date: _____

A. Were Lead-Based Surfaces Identified? (Check One) Yes No

If yes, complete the tables below. Data in tables may not indicate all identified lead-based surfaces.

EXTERIOR Lead-Based Surfaces	Foundation	Siding &/or Trim	Stairs &/or Stair Components	Porch &/or Porch Components	Doors &/or Trim	Windows &/or Trim	Garage &/or Garage Components
Deteriorated	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Intact	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

(X = positive location)

INTERIOR Lead-Based Surfaces	Floors	Baseboards	Walls	Ceilings	Stairs &/or Stair Components	Doors &/or Trim	Windows &/or Trim	Closet/ Cabinet Components
Deteriorated	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Intact	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

(X = positive location)

Were rooms, areas or components inaccessible during inspection? (Check One) Yes No
List any inaccessible locations: _____

B. Indicate Potential Lead Hazards Identified:

(Check All That Apply)

- Was drinking water tested for lead?
 Yes No
- Was dust tested for lead?
 Yes No
- Was bare soil tested for lead?
 Yes No N/A

Lead Hazard Locations	Floors (dust)	Window Sills (dust)	Window Wells (dust)	Soil	Water	Paint (XRF)	Paint Chip
(Enter highest result for each)				398		21.59	

If yes, complete the adjacent table.

Per section 19a-111-4(a) and 19a-111-2(e) of the Lead Poisoning Prevention and Control Regulations:

- A lead abatement plan is required for this property: Yes No
- A lead management plan is required for this property: Yes No
- A lead hazard remediation plan is required for this property: Yes No
- A lead management plan is required for this property: Yes No

Inspector's Signature: [Signature] Date: 10 / 1 / 2014


The federal Residential Lead-Based Paint Hazard Reduction Act, 42 U.S.C. 4852d, requires sellers and landlords of most residential housing built before 1978 to disclose all available records and reports concerning lead-based paint and/or lead-based paint hazards, including the test results contained or referenced in this notice, to purchasers and tenants at the time of sale or lease or upon lease renewal. This disclosure must occur even if hazard reduction or abatement has been completed. Failure to disclose these test results is a violation of the U.S. Department of Housing and Urban Development and the U.S. Environmental Protection Agency regulations at 24 CFR Part 35 and 40 CFR Part 745 and can result in a fine of up to \$11,000 per violation. To find out more information about your obligations under federal lead-based paint requirements, call 1-800-424-LEAD.

I have received a copy of this summary report from my landlord/property manager and have been informed that I can obtain further information about the testing results from the report by contacting the property owner listed above.

Resident's Signature: _____ Date: _____ / _____ / _____

**LEAD BASED PAINT INSPECTION
REPORT OF FINDINGS
OF:**

**896-898 HOWARD AVENUE
BRIDGEPORT, CONNECTICUT**



**DATE:
SEPTEMBER 22, 2014**

**PREPARED BY:
GILBERTCO LEAD INSPECTIONS LLC
287 MAIN STREET
ANSONIA, CONNECTICUT 06401**



GILBERTCO

LEAD INSPECTIONS, LLC

“LEAD BASED PAINT SPECIALIST”

October 1, 2014

Job 9928-16-896

Kevin Bogue, LEP, CHMM
Facility Support Services, LLC
2685 State Street
Hamden, Connecticut 06517

**Re: Lead Based Paint Inspection: 896-898 Howard Ave., Bridgeport, CT
Applicant 2149- O'Neil and Shena Anderson**

Gilbertco Lead Inspections LLC performed a limited XRF inspection for the presence of lead based paint at 896-898 Howard Ave., Bridgeport, Connecticut. The inspection was requested by Facility Support Services in response to distribution of HUD funds given to CT DOH for Storm Sandy repair work.

The site inspected consists of a large, four story, three family home built about 1910. The exterior is vinyl siding with vinyl replacements windows throughout. The home is in good repair and enjoys excellent housekeeping.

In accordance with HUD/EPA guidance issued June 26, 1996, the Scitec Map 4 Spectrum Analyzer was used in the “Unlimited” assaying mode. This enables the equipment to accurately determine whether the result is “Positive”, above the 1.0 mg/cm² action level or “Negative”, below the action level regardless of precision or operator bias. In accordance with the above guidance, values of 0.91 mg/cm² through 1.19 mg/cm² are considered “Inconclusive”, meaning the value level of lead in paint was so close to the 1.0 mg/cm² action level that further analysis by XRF would not result in a “Positive” or “Negative” answer. Only laboratory analysis of the paint film can determine actual values in this range. Chip sampling of inconclusive was not included in the scope of this report, therefore, any results above 0.9 mg/cm² are considered positive. Results are arranged floor plan style with the substrate and condition noted. Orientation of rooms places side ‘one’ as street side, with side ‘two’ to the left, side ‘three’ opposite, and wall ‘four’ to the right. Rooms were tested in a clockwise pattern.

In regards to the above mentioned property, *several lead based paint hazards were identified*. A lead based paint hazard is “any condition that causes lead exposure to lead from lead-contaminated dust, lead contaminated soil, or lead-contaminated paint that is deteriorated or present in accessible surfaces, friction surfaces, or impact surfaces that would result in adverse human health effects...”. ...”. (The Residential Lead Based Paint Hazard Reduction Act of 1992 – Title X). ...”. Several areas tested positive for lead based paint but are currently in an intact condition. These areas should be placed on a Management Plan and monitored annually for signs of deterioration or paint breakdown. *See attached* . In April 2010, a new EPA regulation requires that any contractor who disturbs more than six square feet of painted surface per room or does window replacement must be certified as a Renovate Right Contractor. Homeowners are allowed to do their own renovation but are not exempt from providing renovation notices or posting informational signs. Further information regarding Renovate Right may be obtained at www.epa.gov/lead/pubs/renovation or by calling the National Lead Information Center at 1-800-424-LEAD (5323).


Lead in dust was not included in the scope of this report. Only laboratory analysis can insure that no lead dust hazards remain after renovations or from everyday use of the home.

A composite soil sample was obtained from exposed bare soil on the right side of the property and found to have a lead concentration of 398 ppm. This is below the 400 ppm recommended lead in soil level and therefore no action needs to be taken. Nevertheless, vegetable plants should not be planted near the perimeter of the house or in water runoff areas. Children should not be allowed to play in bare soil areas adjacent to the house. Asphalt, bushes, mulch, or good quality grass covering are acceptable deterrents.

This lead inspection report should be disclosed to future tenants and /or buyers in accordance with Title X (copy enclosed). As with any lead-containing surface, children should not be allowed to chew or mouth painted surfaces as this is a common source of lead poisoning in children.

A copy of this report and has been sent to the owner in accordance with CGS 19a-111 and a proposed abatement plan has been submitted to the Bridgeport Health Department as required. Additionally, notification has been sent to the State Historic Preservation Office for approval.

Please feel free to call if any questions arise,


Maureen Monaco

Consultant Contractor #270

Lead Inspector Risk Assessor #1172

**CERTIFICATION
LEAD IN PAINT RESULTS**

AGENCY: GILBERTCO LEAD INSPECTIONS LLC
287 MAIN STREET
ANSONIA, CONNECTICUT 06401

PROJECT ADDRESS: 896-898 HOWARD AVENUE
BRIDGEPORT, CONNECTICUT

PROJECT NUMBER: 9928-16-896

TEST DATE: SEPTEMBER 22, 2014

REQUIREMENTS: CHAPTER 7 HUD GUIDELINES
LEAD INSPECTION- SURFACE BY SURFACE

INSTRUMENTATION: SCITEC MAP4 PORTABLE X-RAY (BRUKER HANDHELD)
FLUOROSCOPE SPECTRUM ANALYZER
(XRF) COBALT 57 SOURCE

REPORT MEDIUM: MG PB/CM2 (MILLIGRAMS OF LEAD
PER SQUARE CENTIMETER)

CALIBRATION: TO MEASURE LEAD K-SHELL EMISSIONS.
FACTORY CALIBRATED WITH HUD APPROVED
REFERENCE STANDARDS. CALIBRATION FIELD
CHECKED HOURLY AS RECOMMENDED BY
MANUFACTURER

OPERATORS CERTIFICATION: LEAD CONSULTANT CONTRACTOR-CC270
LEAD INSPECTOR RISK ASSESSOR- IR 1172
LEAD ABATEMENT SUPERVISOR- 2383

I hereby certify to the best of my knowledge and capabilities that this report reflects the true lead content of the surfaces tested in this report on this date.

Matthew D. Morris *10/2/14*

**896-898 Howard Ave., Lower Level, Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1.34	okay
Front Right BR	1	1	Wall	Sheetrk	Intact	-0.24	Negative
Front Right BR	1	1	Ceiling	Sheetrk	Intact	-0.6	Negative
Front Right BR	1	2	Wall	Sheetrk	Intact	-0.06	Negative
Front Right BR	1	2	Baseboard	Wood	Intact	-0.01	Negative
Front Right BR	1	2	Wall	Sheetrk	Intact	0.17	Negative
Front Right BR	1	3	Door	Wood	Intact	-0.14	Negative
Front Right BR	1	3	Door Casing	Wood	Intact	-0.09	Negative
Living Room	2	1	Wall	Sheetrk	Intact	0.24	Negative
Living Room	2	1	Door Casing	Wood	Intact	-0.14	Negative
Living Room	2	2	Baseboard	Wood	Intact	0.47	Negative
Living Room	2	2	Wall	Sheetrk	Intact	0.16	Negative
Living Room	2	3	Closet Door	Sheetrk	Intact	0.12	Negative
Living Room	2	3	Clo Dr Csng	Sheetrk	Intact	0.13	Negative
Living Room	2	4	Wall	Sheetrk	Intact	0.03	Negative
Living Room	2	4	Window Trim	Wood	Intact	-0.03	Negative
Kitchen	3	1	Wall	Sheetrk	Intact	-0.14	Negative
Kitchen	3	4	Wall	Sheetrk	Non-intact	0.21	Negative
Kitchen	3	4	Clo Dr Csng	Wood	Intact	0.19	Negative
Kitchen	3	4	Ceiling	Sheetrk	Intact	0.15	Negative
Kitchen	3	4	Wall	Sheetrk	Intact	0.37	Negative
Kitchen	3	4	Baseboard	Wood	Intact	-0.2	Negative
Kitchen	3	4	Cabinet	Wood	Intact	0.15	Negative
Kitchen	3	3	Wall	Sheetrk	Intact	0.35	Negative
Kitchen	3	3	Door	Wood	Intact	0.24	Negative
Kitchen	3	3	Door Casing	Wood	Intact	0.4	Negative
Kitchen	3	2	Closet Door	Wood	Intact	-0.13	Negative
Kitchen	3	2	Clo Dr Csng	Wood	Intact	-0.02	Negative
Front Left BR	4	1	Wall	Sheetrk	Intact	0.28	Negative
Front Left BR	4	2	Wall	Sheetrk	Intact	-0.05	Negative
Front Left BR	4	2	Window Trim	Wood	Intact	0.12	Negative
Front Left BR	4	1	Ceiling	Sheetrk	Intact	0.04	Negative
Front Left BR	4	4	Wall	Sheetrk	Intact	-0.06	Negative
Front Left BR	4	4	Door	Wood	Intact	-0.11	Negative
Front Left BR	4	3	Door Casing	Wood	Intact	-0.06	Negative
Front Left BR	4	3	Wall	Sheetrk	Intact	0.21	Negative
Bathroom	5	4	Door	Wood	Intact	-0.03	Negative
Bathroom	5	4	Door Jamb	Wood	Intact	0.1	Negative
Bathroom	5	4	Door Casing	Wood	Intact	0.05	Negative
Bathroom	5	4	Wall	Sheetrk	Intact	-0.07	Negative

**896-898 Howard Ave., Lower Level, Bridgeport, Connecticut
September 22, 2014**

Bathroom	5	1	Wall	Sheetrk	Intact	0	Negative
Bathroom	5	1	Cabinet	Wood	Intact	0.03	Negative
Bathroom	5	2	Wall	Sheetrk	Intact	-0.16	Negative
Bathroom	5	2	Baseboard	Sheetrk	Intact	0.11	Negative
Bathroom	5	1	Ceiling	Sheetrk	Intact	-0.44	Negative
Open Basement	6	1	Door	Wood	Intact	-0.35	Negative
Open Basement	6	1	Door Jamb	Wood	Intact	0.07	Negative
Open Basement	6	4	Wall	Sheetrk	Intact	0.7	Negative
Open Basement	6	2	Wall	Masonry	Intact	-0.27	Negative
Open Basement	6	3	Door	Wood	Intact	0.27	Negative
Open Basement	7	3	Door	Wood	unpainted	0.28	Negative
Open Basement	7	3	Door Casing	Wood	Intact	-0.57	Negative
Open Basement	7	3	Wall	Wood	Intact	-0.13	Negative
Open Basement	7	3	Floor	Masonry	Non-intact	0.23	Negative
Open Basement	7	3	Stair Tread	Wood	Intact	0.26	Negative
Open Basement	7	3	Stair Riser	Wood	Intact	0.49	Negative
Open Basement	7	3	Wall	Wood	Intact	0.23	Negative
Open Basement	7	3	Ceiling	Sheetrk	Intact	-0.43	Negative

**896-898 Howard Ave., First Floor, Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1.05	okay
Front Right BR	1	1	Wall	Sheetrk	Intact	0.11	Negative
Front Right BR	1	1	Window Trim	Wood	Intact	0.43	Negative
Front Right BR	1	1	Window Sill	Wood	Intact	0.23	Negative
Front Right BR	1	1	Window Apron	Wood	Intact	-0.08	Negative
Front Right BR	1	1	Baseboard	Wood	Intact	0.14	Negative
Front Right BR	1	1	Radiator	Metal	Intact	0.61	Negative
Front Right BR	1	4	Wall	Sheetrk	Intact	-0.12	Negative
Front Right BR	1	4	Baseboard	Wood	Intact	0.04	Negative
Front Right BR	1	4	Window Trim	Wood	Intact	0.02	Negative
Front Right BR	1	4	Window Sill	Wood	Intact	0.84	Negative
Front Right BR	1	4	Window Apron	Wood	Intact	-0.08	Negative
Front Right BR	1	4	Wall	Sheetrk	Intact	0.23	Negative
Front Right BR	1	2	Closet Door	Wood	Intact	-0.03	Negative
Front Right BR	1	2	Clo Dr Csng	Wood	Intact	0.11	Negative
Front Right BR	1	2	Door Casing	Wood	Intact	-0.31	Negative
Front Right BR	1	2	Wall	Sheetrk	Intact	0.24	Negative
Front Right BR	1	2	Baseboard	Wood	Intact	-0.03	Negative
Front Right BR	1	2	Door	Wood	Intact	-0.54	Negative
Front Right BR	1	3	Door Casing	Wood	Intact	0	Negative
Front Right BR	1	3	Wall	Sheetrk	Intact	0.27	Negative
Living Room	2	1	Door Casing	Wood	Intact	-0.34	Negative
Living Room	2	1	Wall	Sheetrk	Intact	0.37	Negative
Living Room	2	2	Door	Wood	Intact	10.06	Positive
Living Room	2	2	Door Casing	Wood	Intact	0.03	Negative
Living Room	2	2	Wall	Sheetrk	Intact	0.01	Negative
Living Room	2	2	Baseboard	Wood	Intact	-0.3	Negative
Living Room	2	2	Floor	Wood	Stain/varnish	0.16	Negative
Living Room	2	2	Cabinet	Wood	Intact	-0.02	Negative
Living Room	2	2	Cabinet	Wood	Intact	0.17	Negative
Living Room	2	3	Wall	Sheetrk	Intact	-0.04	Negative
Living Room	2	3	Door Casing	Wood	Intact	-0.28	Negative
Living Room	2	3	Baseboard	Wood	Intact	0.42	Negative
Living Room	2	4	Wall	Sheetrk	Intact	0.13	Negative
Living Room	2	4	Window Sill	Wood	Intact	0.37	Negative
Living Room	2	4	Window Trim	Wood	Intact	0.18	Negative
Living Room	2	5	Window Stop	Wood	Intact	-0.12	Negative
Living Room	2	4	Windwo Apron	Wood	Intact	0.24	Negative
Living Room	2	4	Baseboard	Wood	Intact	-0.08	Negative
Living Room	2	4	Radiator	Metal	Intact	0.76	Negative
Living Room	2	1	Floor	Wood	Stain/varnish	-0.33	Negative
Bathroom	3	2	Door Jamb	Wood	Intact	0.32	Negative
Bathroom	3	2	Door Casing	Wood	Intact	0.18	Negative

896-898 Howard Ave., First Floor, Bridgeport, Connecticut
September 22, 2014

Bathroom	3	2 Wall	Sheetrk	Intact	1.49 Positive
Bathroom	3	3 Wall	Sheetrk	Intact	2.62 Positive
Bathroom	3	3 Baseboard	Wood	Intact	0 Negative
Bathroom	3	4 Wall	Sheetrk	Intact	3.25 Positive
Bathroom	3	4 Window Trim	Wood	Intact	0.21 Negative
Bathroom	3	4 Window Sill	Wood	Intact	0.06 Negative
Bathroom	3	4 Window Apron	Wood	Intact	0 Negative
Bathroom	3	1 Wall	Sheetrk	Intact	-0.04 Negative
Bathroom	3	1 Baseboard	Wood	Intact	0.18 Negative
Kitchen	4	1 Door Jamb	Wood	Intact	0.18 Negative
Kitchen	4	1 Door Casing	Wood	Intact	0.38 Negative
Kitchen	4	1 Cabinet	Wood	Stain/varnish	0.27 Negative
Kitchen	4	2 Wall	Sheetrk	Intact	-0.14 Negative
Kitchen	4	2 Baseboard	Wood	Intact	0.27 Negative
Kitchen	4	4 Wall	Sheetrk	Intact	4.05 Positive
Kitchen	4	4 Window Trim	Wood	Intact	0.45 Negative
Kitchen	4	4 Window Sill	Wood	Intact	0.22 Negative
Kitchen	4	4 Window Stop	Wood	Intact	0.19 Negative
Kitchen	4	4 Wall-upper	Sheetrk	Intact	3.17 Positive
Kitchen	4	4 Wall-lower	Wood	Intact	0.02 Negative
Kitchen	4	4 Radiator	Metal	Intact	0.68 Negative
Kitchen	4	3 Wall	Sheetrk	Intact	3.23 Positive
Kitchen	4	3 Cabinet	Wood	Stain/varnish	0.43 Negative
Kitchen	4	3 Wall-upper	Sheetrk	Intact	3.93 Positive
Kitchen	4	3 Wall-lower	Sheetrk	Intact	0.17 Negative
Kitchen	4	3 Door	Sheetrk	Intact	0.63 Negative
Kitchen	4	3 Door Casing	Sheetrk	Intact	-0.01 Negative
Kitchen	4	1 Closet Door	Wood	Intact	-0.04 Negative
Kitchen	4	1 Clo Dr Csgng	Wood	Intact	0.38 Negative
Front Hall	5	1 Door	Wood	Intact	0.26 Negative
Front Hall	5	1 Door Casing	Wood	Intact	-0.17 Negative
Front Hall	5	1 Wall	Sheetrk	Intact	0.26 Negative
Front Hall	5	1 Baseboard	Wood	Intact	0.37 Negative
Front Hall	5	1 Floor	Wood	Stain/varnish	0.11 Negative
Front Hall	5	4 Wall	Sheetrk	Intact	0.17 Negative
Front Hall	5	4 Baseboard	Wood	Intact	-0.18 Negative
Front Hall	5	2 Wall	Sheetrk	Intact	0.16 Negative
Front Hall	5	2 Baseboard	Wood	Intact	0.25 Negative
Front Hall	5	3 Wall	Sheetrk	Intact	0.21 Negative
Front Hall	5	3 Radiator	Metal	Intact	0.28 Negative
Front Hall	5	3 Baseboard	Wood	Intact	-0.39 Negative
Front Hall	5	3 Door	Wood	Intact	8.27 Positive
Front Hall	5	3 Door Casing	Wood	Intact	0.48 Negative
Front Left Bedroom	6	1 Door	Wood	Intact	-0.06 Negative

896-898 Howard Ave., First Floor, Bridgeport, Connecticut

September 22, 2014

Front Left Bedroom	6	1	Door Casing	Wood	Intact	0.11	Negative
Front Left Bedroom	6	1	Wall	Sheetrk	Intact	0.13	Negative
Front Left Bedroom	6	1	Baseboard	Wood	Intact	0.29	Negative
Front Left Bedroom	6	1	Closet Door	Wood	Intact	0.09	Negative
Front Left Bedroom	6	1	Clo Dr Csng	Wood	Intact	0.34	Negative
Front Left Bedroom	6	1	Shelf Support	Wood	Intact	0.44	Negative
Front Left Bedroom	6	2	Window Trim	Wood	Intact	0.37	Negative
Front Left Bedroom	6	2	Window Sill	Wood	Intact	0.12	Negative
Front Left Bedroom	6	2	Window Stop	Wood	Intact	-0.11	Negative
Front Left Bedroom	6	2	WindowApron	Wood	Intact	0.75	Negative
Front Left Bedroom	6	2	Baseboard	Wood	Intact	0.53	Negative
Front Left Bedroom	6	2	Radiator	Wood	Intact	0.71	Negative
Front Left Bedroom	6	3	Wall	Sheetrk	Intact	0.04	Negative
Front Left Bedroom	6	3	Baseboard	Wood	Intact	0.43	Negative
Front Left Bedroom	6	3	Door	Wood	Intact	0.06	Negative
Front Left Bedroom	6	3	Door Casing	Wood	Intact	-0.02	Negative
Front Left Bedroom	6	3	Door Jamb	Wood	Intact	0.02	Negative
Bathroom	7	4	Door	Wood	Intact	-0.13	Negative
Bathroom	7	4	Door Jamb	Wood	Intact	0.06	Negative
Bathroom	7	4	Door Casing	Wood	Intact	2.37	Positive
Bathroom	7	4	Wall	Sheetrk	Intact	-0.02	Negative
Bathroom	7	1	Wall	Sheetrk	Intact	0.27	Negative
Bathroom	7	2	Wall	Sheetrk	Intact	0.89	Negative
Bathroom	7	2	Window trim	Wood	Intact	2.13	Positive
Bathroom	7	2	Window Sill	Wood	Intact	2.02	Positive
Bathroom	7	2	Window Stop	Wood	Intact	0.76	Negative
Bathroom	7	2	Window Apron	Wood	Intact	2.91	Positive
Bathroom	7	8	Radiator	Metal	Non-intact	0.48	Negative
Bathroom	7	8	Shelf	Metal	Non-intact	-0.2	Negative
Bathroom	7	3	Shelf Support	Wood	Intact	0.48	Negative
Rear Bedroom	8	1	Door	Wood	Intact	-0.04	Negative
Rear Bedroom	8	1	Door Jamb	Wood	Intact	-0.04	Negative
Rear Bedroom	8	1	Door Casing	Wood	Intact	0.31	Negative
Rear Bedroom	8	1	Wall	Sheetrk	Intact	0.09	Negative
Rear Bedroom	8	1	Baseboard	Wood	Intact	0.23	Negative
Rear Bedroom	8	2	Wall	Sheetrk	Intact	-0.19	Negative
Rear Bedroom	8	2	Window Sill	Wood	Intact	0.77	Negative
Rear Bedroom	8	2	Window Trim	Wood	Intact	0.57	Negative
Rear Bedroom	8	2	Window Apron	Wood	Intact	0.86	Negative
Rear Bedroom	8	3	Wall	Sheetrk	Intact	0.09	Negative
Rear Bedroom	8	3	Baseboard	Wood	Intact	-0.21	Negative
Rear Bedroom	8	4	Wall	Sheetrk	Intact	-0.35	Negative
Rear Bedroom	8	4	Baseboard	Wood	Intact	2.97	Positive
Rear Bedroom	8	4	Closet Door	Wood	Intact	-0.26	Negative
Rear Bedroom	8	4	Clo Dr CSng	Wood	Intact	0.53	Negative

**896-898 Howard Ave., Second Floor, Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1.04	okay
Front Porch	1	1	Wall	Sheetrk	Intact	-0.16	Negative
Front Porch	1	1	Window Sill	Wood	Non-intact	1	Inconclusive
Front Porch	1	1	Window Sill	Wood	Non-intact	1.76	Positive
Front Porch	1	1	Wall	Wood	Non-intact	15.2	Positive
Front Porch	1	4	Wall	Sheetrk	Intact	-0.36	Negative
Front Porch	1	4	Window Sill	Wood	Non-intact	2.51	Positive
Front Porch	1	4	Wall	Wood	Non-intact	8.81	Positive
Front Porch	1	3	Window Trim	Wood	Non-intact	19.47	Positive
Front Porch	1	3	Window Sill	Wood	Non-intact	8.85	Positive
Front Porch	1	3	Clapboard	Wood	Intact	1.04	Inconclusive
Front Porch	1	3	Door	Wood	Intact	0.33	Negative
Front Porch	1	3	Door Jamb	Wood	Intact	21.59	Positive
Front Porch	1	3	Door Casing	Wood	Intact	3.42	Positive
Front Porch	1	3	Threshold	Wood	Intact	3.57	Positive
Front Hall	2	1	Door	Wood	Intact	0.68	Negative
Front Hall	2	1	Door Casing	Wood	Intact	0.07	Negative
Front Hall	2	1	Wall	Sheetrk	Intact	0.35	Negative
Front Hall	2	1	Radiator	Metal	Intact	0.37	Negative
Front Hall	2	4	Wall	Sheetrk	Intact	0.1	Negative
Front Hall	2	4	Baseboard	Sheetrk	Stain/varnish	-0.06	Negative
Front Hall	2	1	Floor	Wood	Stain/varnish	-0.2	Negative
Front Hall	2	1	Stair Tread	Wood	Stain/varnish	0.21	Negative
Front Hall	2	1	Stair Riser	Wood	Intact	0.23	Negative
Front Hall	2	1	Stair Stringer	Wood	Intact	0.28	Negative
Front Hall	2	2	Wall	Sheetrk	Intact	-0.26	Negative
Front Hall	2	2	Newel Post	Wood	Intact	0.04	Negative
Front Hall	2	2	Newel Post	Wood	Intact	-0.06	Negative
Front Hall	2	2	Spindle	Wood	Intact	-0.21	Negative
Front Hall	2	2	Ceiling	Sheetrk	Intact	0.23	Negative
Front Hall	2	3	Wall	Sheetrk	Intact	-0.04	Negative
Front Hall	2	3	Baseboard	Wood	Intact	0.06	Negative
Front Bedroom	3	1	Wall	Sheetrk	Intact	0.77	Negative
Front Bedroom	3	4	Wall	Sheetrk	Intact	-0.52	Negative
Front Bedroom	3	1	Window Sill	Wood	Intact	-0.03	Negative
Front Bedroom	3	1	Window Trim	Wood	Intact	0.02	Negative
Front Bedroom	3	1	Radiator	Metal	Non-intact	0.83	Negative
Front Bedroom	3	1	Clo Dr Csng	Wood	Intact	-0.09	Negative
Front Bedroom	3	1	Wall	Sheetrk	Intact	0.31	Negative
Front Bedroom	3	3	Door Casing	Wood	Intact	0.27	Negative
Front Bedroom	3	3	Baseboard	Wood	Intact	0.26	Negative
Front Bedroom	3	3	Door	Wood	Intact	-0.63	Negative

**896-898 Howard Ave., Second Floor, Bridgeport, Connecticut
September 22, 2014**

Front Bedroom	3	3	Door Jamb	Wood	Intact	0.14	Negative
Front Bedroom	3	3	Door Casing	Wood	Intact	-0.13	Negative
Living Room	4	1	Door Casing	Wood	Intact	0.28	Negative
Living Room	4	1	Post/column	Wood	Intact	-0.29	Negative
Living Room	4	1	Window Sill	Wood	Intact	0.07	Negative
Living Room	4	4	Window Trim	Wood	Intact	-0.17	Negative
Living Room	4	4	Wall	Sheetrk	Intact	0.03	Negative
Living Room	4	4	Radiator	Metal	Non-intact	0.15	Negative
Living Room	4	2	Door	Wood	Intact	-0.26	Negative
Living Room	4	2	Door Casing	Wood	Intact	-0.22	Negative
Living Room	4	2	Wall	Sheetrk	Intact	0.45	Negative
Living Room	4	2	Baseboard	Wood	Intact	-0.13	Negative
Living Room	4	2	Floor	Wood	Stain/varnish	-0.36	Negative
Living Room	4	2	Door Casing	Wood	Intact	0.16	Negative
Living Room	4	3	Wall	Sheetrk	Intact	0.05	Negative
Living Room	4	3	Door Casing	Wood	Intact	0.37	Negative
Living Room	4	3	Door Jamb	Wood	Intact	0.13	Negative
Laundry	5	2	Door Casing	Wood	Intact	0.31	Negative
Laundry	5	2	Wall	Sheetrk	Intact	3.3	Positive
Laundry	5	2	Baseboard	Wood	Intact	-0.01	Negative
Laundry	5	4	Wall	Sheetrk	Intact	11.91	Positive
Laundry	5	4	Window Trim	Wood	Intact	-0.35	Negative
Laundry	5	4	Window Sill	Wood	Intact	0.26	Negative
Laundry	5	4	Window Stop	Wood	Intact	0.41	Negative
Laundry	5	1	Wall	Sheetrk	Intact	0.06	Negative
Laundry	5	2	Wall	Sheetrk	Intact	7.21	Positive
Bathroom	5	3	Baseboard	Wood	Intact	0.3	Negative
Kitchen	6	1	Door Jamb	Wood	Intact	0.31	Negative
Kitchen	6	1	Door Casing	Wood	Intact	-0.02	Negative
Kitchen	6	1	Cabinet	Wood	Stain/varnish	-0.39	Negative
Kitchen	6	4	Window Sill	Wood	Intact	0.26	Negative
Kitchen	6	4	Window Trim	Wood	Intact	-0.35	Negative
Kitchen	6	4	Window Stop	Wood	Intact	0.05	Negative
Kitchen	6	4	Window Apron	Wood	Intact	0.15	Negative
Kitchen	6	4	Wall-upper	Sheetrk	Intact	0.04	Negative
Kitchen	6	4	Chairrail	Wood	Intact	-0.01	Negative
Kitchen	6	4	Wall-lower	Wood	Intact	0.37	Negative
Kitchen	6	4	Radiator	Metal	Non-intact	-0.09	Negative
Kitchen	6	2	Wall-upper	Sheetrk	Intact	8.61	Positive
Kitchen	6	2	Chairrail	Wood	Intact	0.02	Negative
Kitchen	6	2	Wall-lower	Sheetrk	Intact	0.11	Negative
Kitchen	6	2	Baseboard	Sheetrk	Intact	0.1	Negative
Kitchen	6	3	Wall	Sheetrk	Intact	10.87	Positive
Kitchen	6	3	Door	Wood	Intact	-0.47	Negative

**896-898 Howard Ave., Second Floor, Bridgeport, Connecticut
September 22, 2014**

Kitchen	6	3	Door Casing	Wood	Intact	-0.03	Negative
Kitchen	6	3	Cabinet	Wood	Stain/varnish	-0.15	Negative
Dining Room	7	1	Wall	Sheetrk	Intact	-0.29	Negative
Dining Room	7	1	Door	Wood	Intact	-0.12	Negative
Dining Room	7	1	Door Casing	Wood	Intact	0.74	Negative
Dining Room	7	1	Closet Door	Wood	Intact	-0.04	Negative
Dining Room	7	1	Clo Dr Csng	Wood	Intact	0.88	Negative
Dining Room	7	1	Window Sill	Wood	Non-intact	0.19	Negative
Dining Room	7	1	Window Trim	Wood	Intact	0.88	Negative
Dining Room	7	1	Window Stop	Wood	Intact	0.5	Negative
Dining Room	7	2	Window Apron	Wood	Intact	0.72	Negative
Dining Room	7	2	Baseboard	Wood	Intact	0.43	Negative
Dining Room	7	2	Floor	Wood	Stain/varnish	0.14	Negative
Dining Room	7	4	Wall	Sheetrk	Intact	0.22	Negative
Dining Room	7	4	Door Casing	Wood	Intact	-0.18	Negative
Dining Room	7	2	Railing	Metal	Non-intact	0.8	Negative
Dining Room	7	2	Wall	Sheetrk	Intact	-0.24	Negative
Dining Room	7	2	Door Casing	Wood	Intact	0.4	Negative
Dining Room	7	3	Door Jamb	Wood	Intact	-0.14	Negative
Bathroom	8	4	Door	Wood	Intact	-0.14	Negative
Bathroom	8	4	Door Jamb	Wood	Intact	0.03	Negative
Bathroom	8	4	Door Casing	Wood	Intact	0.36	Negative
Bathroom	8	4	Wall	Sheetrk	Intact	0.57	Negative
Bathroom	8	1	Wall	Sheetrk	Intact	0.56	Negative
Bathroom	8	1	Cabinet	Wood	Intact	0.14	Negative
Bathroom	8	1	Window Sill	Wood	Intact	-0.2	Negative
Bathroom	8	2	Window Trim	Wood	Intact	1.81	Positive
Bathroom	8	2	Window Stop	Wood	Intact	1.46	Positive
Bathroom	8	2	Window Apron	Wood	Intact	0.19	Negative
Bathroom	8	2	Shelf	Wood	Intact	-0.06	Negative
Bathroom	8	3	Shelf Support	Wood	Intact	0.02	Negative
Bathroom	8	3	Wall	Sheetrk	Intact	0.12	Negative
Rear Bedroom	9	1	Door	Wood	Intact	0.01	Negative
Rear Bedroom	9	1	Door Jamb	Wood	Intact	4.59	Positive
Rear Bedroom	9	1	Door Casing	Wood	Intact	4.05	Positive
Rear Bedroom	9	1	Wall	Sheetrk	Intact	0.49	Negative
Rear Bedroom	9	2	Wall	Sheetrk	Intact	0.3	Negative
Rear Bedroom	9	2	Radiator	Metal	Non-intact	0.33	Negative
Rear Bedroom	9	3	Wall	Sheetrk	Intact	-0.31	Negative
Rear Bedroom	9	3	Window Sill	Wood	Intact	1.53	Positive
Rear Bedroom	9	3	Window Trim	Wood	Intact	4.76	Positive
Rear Bedroom	9	3	Window Stop	Wood	Intact	1.88	Positive
Rear Bedroom	9	3	Wall	Sheetrk	Intact	0.15	Negative
Rear Bedroom	9	4	Baseboard	Wood	Non-intact	0.06	Negative

896-898 Howard Ave., Second Floor, Bridgeport, Connecticut
September 22, 2014

Rear Bedroom	9	4	Closet Door	Wood	Intact	0.11	Negative
Rear Bedroom	9	4	Clo Dr Csg	Wood	Intact	4.63	Positive
Rear Bedroom	9	4	Clo Dr Csg	Wood	Intact	3.45	Positive

**896-898 Howard Ave., Rear Second Floor Porch and Rear Hall. Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1.24	Okay
2nd Fl Rear Porch	1	1	Ceiling	Wood	Non-intact	-0.05	Negative
2nd Fl Rear Porch	1	1	Transom	Wood	Non-intact	23.47	Positive
2nd Fl Rear Porch	1	1	Transom	Wood	Non-intact	18.87	Positive
2nd Fl Rear Porch	1	1	Transom	Wood	Non-intact	19.81	Positive
2nd Fl Rear Porch	1	1	Threshold	Wood	Non-intact	16.9	Positive
2nd Fl Rear Porch	1	1	Door Jamb	Wood	Non-intact	17.39	Positive
2nd Fl Rear Porch	1	1	Door	Wood	Intact	-0.01	Negative
Rear Hall	2	1	Door	Wood	Intact	-0.16	Negative
Rear Hall	2	1	Door Jamb	Wood	Intact	-0.04	Negative
Rear Hall	2	1	Door Casing	Wood	Intact	0.32	Negative
Rear Hall	2	1	Wall	Sheetrk	Intact	5.07	Positive
Rear Hall	2	3	Wall	Sheetrk	Intact	1.28	Positive
Rear Hall	2	4	Wall	Sheetrk	Intact	5.31	Positive
Rear Hall	2	1	Ceiling	Sheetrk	Intact	0.81	Negative
Rear Hall	2	1	Stair Tread	Wood	Intact	-0.03	Negative
Rear Hall	2	1	Stair Riser	Wood	Intact	0.06	Negative
Rear Hall	2	1	Stair Stringer	Wood	Intact	0.19	Negative
Rear Hall	2	1	Floor	Wood	Intact	-0.09	Negative
Rear Hall	2	4	Wall	Sheetrk	Intact	3.55	Positive
Rear Hall	2	4	Door Casing	Wood	Intact	0.31	Negative
Rear Hall	2	2	Closet Door	Wood	Intact	-0.1	Negative
Rear Hall	2	2	Clo Dr Csng	Wood	Intact	-0.15	Negative
Rear Hall	2	2	Floor	Wood	Intact	0	Negative

**896-898 Howard Ave., Third Floor, Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1.08	Okay
Front Bedroom	1	1	Wall	Sheetrk	Intact	-0.21	Negative
Front Bedroom	1	1	Window Sill	Wood	Intact	0.49	Negative
Front Bedroom	1	1	Window Trim	Wood	Intact	-0.03	Negative
Front Bedroom	1	1	Window Stop	Wood	Intact	-0.18	Negative
Front Bedroom	1	1	Window Apron	Wood	Intact	0.37	Negative
Front Bedroom	1	1	Baseboard	Wood	Intact	0.44	Negative
Front Bedroom	1	2	Wall	Sheetrk	Intact	-0.42	Negative
Front Bedroom	1	2	Closet Door	Wood	Intact	-0.04	Negative
Front Bedroom	1	2	Clo Dr Csng	Wood	Intact	-0.08	Negative
Front Bedroom	1	4	Wall	Sheetrk	Intact	0.17	Negative
Front Bedroom	1	4	Baseboard	Wood	Intact	-0.05	Negative
Front Bedroom	1	3	Wall	Sheetrk	Intact	-0.17	Negative
Front Bedroom	1	2	Door	Wood	Intact	0.03	Negative
Front Bedroom	1	2	Door Casing	Wood	Intact	0.1	Negative
Front Bedroom	1	2	Ceiling	Sheetrk	Intact	-0.05	Negative
Right Bedroom	2	2	Door	Wood	Intact	0.24	Negative
Right Bedroom	2	2	Door Casing	Wood	Intact	-0.02	Negative
Right Bedroom	2	2	Wall	Sheetrk	Intact	-0.09	Negative
Right Bedroom	2	2	Baseboard	Wood	Intact	-0.11	Negative
Right Bedroom	2	3	Wall	Sheetrk	Intact	0.06	Negative
Right Bedroom	2	3	Closet Door	Wood	Intact	-0.14	Negative
Right Bedroom	2	3	Clo Dr Csng	Wood	Intact	0.22	Negative
Right Bedroom	2	1	Ceiling	Sheetrk	Intact	-0.3	Negative
Right Bedroom	2	4	Wall	Sheetrk	Intact	0.04	Negative
Right Bedroom	2	4	Baseboard	Wood	Intact	0.22	Negative
Right Bedroom	2	4	Window Trim	Wood	Intact	0.28	Negative
Right Bedroom	2	4	Window Sill	Wood	Intact	0.08	Negative
Right Bedroom	2	4	Window Apron	Wood	Intact	0.14	Negative
Right Bedroom	2	1	Wall	Sheetrk	Intact	0.36	Negative
Right Bedroom	2	1	Wall	Sheetrk	Intact	0.31	Negative
Kitchen	3	1	Door Casing	Wood	Intact	0.35	Negative
Kitchen	3	1	Wall	Sheetrk	Intact	0.61	Negative
Kitchen	3	1	Cabinet	Other	Intact	0.14	Negative
Kitchen	3	2	Wall	Sheetrk	Intact	0.16	Negative
Kitchen	3	2	Window Trim	Wood	Intact	-0.05	Negative
Kitchen	3	2	Wall	Sheetrk	Intact	0.02	Negative
Kitchen	3	3	Wall	Sheetrk	Intact	-0.08	Negative
Kitchen	3	3	Cabinet	Wood	Intact	0.17	Negative
Kitchen	3	4	Wall	Sheetrk	Intact	-0.11	Negative
Kitchen	3	4	Baseboard	Wood	Intact	0.01	Negative

**896-898 Howard Ave., Third Floor, Bridgeport, Connecticut
September 22, 2014**

Bathroom	4	4	Door	Wood	Intact	-0.22	Negative
Bathroom	4	4	Door Jamb	Wood	Intact	-0.46	Negative
Bathroom	4	4	Door Casing	Wood	Intact	-0.4	Negative
Bathroom	4	4	Wall	Sheetrk	Intact	-0.15	Negative
Bathroom	4	1	Wall	Sheetrk	Intact	-0.05	Negative
Bathroom	4	2	Wall	Sheetrk	Intact	0.12	Negative
Bathroom	4	2	Cabinet	Wood	Intact	0.17	Negative
Bathroom	4	1	Ceiling	Sheetrk	Intact	-0.15	Negative
Living Room	5	1	Wall	Sheetrk	Intact	0.13	Negative
Living Room	5	1	Baseboard	Wood	Intact	0.23	Negative
Living Room	5	2	Wall	Sheetrk	Intact	-0.14	Negative
Living Room	5	2	Baseboard	Wood	Intact	0.27	Negative
Living Room	5	2	Door	Wood	Intact	0.19	Negative
Living Room	5	2	Door Casing	Wood	Intact	0.04	Negative
Living Room	5	2	Door Jamb	Wood	Intact	0.18	Negative
Living Room	5	3	Door	Wood	Intact	0.28	Negative
Living Room	5	3	Door Casing	Wood	Intact	0.34	Negative
Living Room	5	3	Wall	Sheetrk	Intact	0.04	Negative
Living Room	5	4	Wall	Sheetrk	Intact	0.02	Negative
Living Room	5	4	Baseboard	Wood	Intact	0.3	Negative
			* no windows				
Rear Left BR	6	4	Door	Wood	Intact	0.16	Negative
Rear Left BR	6	4	Door Casing	Wood	Intact	0.14	Negative
Rear Left BR	6	4	Wall	Sheetrk	Intact	0.25	Negative
Rear Left BR	6	4	Baseboard	Wood	Intact	-0.11	Negative
Rear Left BR	6	1	Wall	Sheetrk	Intact	-0.05	Negative
Rear Left BR	6	3	Window Trim	Wood	Intact	-0.15	Negative
Rear Left BR	6	3	Window Sill	Wood	Intact	-0.06	Negative
Rear Left BR	6	3	Window Apron	Wood	Intact	0.06	Negative
Rear Left BR	6	1	Baseboard	Wood	Intact	-0.71	Negative
Rear Left BR	6	2	Wall	Sheetrk	Intact	0.18	Negative
Rear Left BR	6	2	Baseboard	Wood	Intact	0.32	Negative
Rear Left BR	6	1	Ceiling	Sheetrk	Intact	0.05	Negative
Rear Left BR	6	1	Wall	Sheetrk	Intact	0.5	Negative
Rear Left BR	6	1	Closet Door	Wood	Intact	-0.09	Negative
Rear Left BR	6	1	Clo Dr Csng	Wood	Intact	0.09	Negative
Rear Left BR	6	1	Ceiling	Sheetrk	Intact	0.23	Negative
Rear Left BR	6	1	Wall	Sheetrk	Intact	0.2	Negative

**896-898 Howard Ave., Exterior, Bridgeport, Connecticut
September 22, 2014**

Room Type	Room #	Wall #	Component	Substrate	Condition	K Shell	Decision
Calibration						1	Okay
Exterior	1	3	Door	Metal	Intact	-0.05	Negative
Exterior	1	3	Door Casing	Wood	Non-intact	2.48	Positive
Exterior	1	3	Door Casing	Wood	Non-intact	19.42	Positive
Exterior	1	3	Threshold	Wood	Non-intact	7.37	Positive
Exterior	1	3	Kickplate	Wood	Intact	9.86	Positive
Exterior	1	3	Bilco Door	Metal	Non-intact	0.49	Negative
Exterior	1	4	Basement wnd trim	Wood	Non-intact	8.22	Positive
Exterior	1	4	Basement wnd trim	Wood	Non-intact	13.33	Positive
Exterior	1	4	Wall	Masonry	Intact	0.26	Negative
Exterior	1	7	Post/column	Wood	Non-intact	26.65	Positive
Exterior	1	7	Post/column	Wood	Non-intact	24.35	Positive
Exterior	1	1	Porch Wall	Wood	Intact	15.08	Positive
Exterior	1	1	Porch Floor	Wood	Intact	13.11	Positive
Exterior	1	1	Porch Floor	Wood	Stain/varnish	0.14	Negative
Exterior	1	1	Door	Wood	Intact	-0.13	Negative
Exterior	1	1	Door Jamb	Wood	Intact	15.04	Positive
Exterior	1	1	Threshold	Wood	Intact	0.56	Negative
Exterior	1	1	Stair Tread	Wood	Non-intact	-0.09	Negative
Exterior	1	1	Stair Riser	Wood	Non-intact	-0.6	Negative
Exterior	1	1	Railing	Wood	Non-intact	0.35	Negative
Exterior	1	1	Spindle	Wood	Non-intact	-0.02	Negative
Exterior	1	2	Wall	Masonry	Non-intact	0.15	Negative
Exterior	1	2	Basement wnd trim	Wood	Non-intact	4.95	Positive
Exterior	1	2	Trim under front porch	Wood	Non-intact	7.22	Positive
Exterior	1	2	Wall	Wood	Non-intact	0.69	Negative

SCHNEIDER LABORATORIES GLOBAL

INCORPORATED

2512 W. Cary Street • Richmond, Virginia • 23220-5117
804-353-6778 • 800-785-LABS (5227) • (FAX) 804-359-1475

Over 25 Years of Excellence in Service and Technology

LABORATORY ANALYSIS REPORT

Lead Analysis based on EPA 7000B Method

Using Preparation Method EPA 3050B

ACCOUNT #: 3813-14-639
CUSTOMER: Gilbertco Inc
ADDRESS: 287 Main Street
Ansonia, CT 06401

DATE RECEIVED: 9/27/2014

DATE ANALYZED: 9/29/2014

DATE REPORTED: 9/30/2014

PROJECT NAME: MCA

JOB LOCATION: Howard Ave

PROJECT NO.: 9928-16

PO NO.:

Sample Type: SOIL

SLI Sample No.	Customer Sample No.	Collection Date	Sample Description	Sample Wt (mg)	Total Lead (µg)	Lead Conc (% by wt)	Lead Conc PPM
32312514	9928-16	9/22/2014	Composite Right Side Of H	520	207.1	0.040	398


Analysis Run ID: 53876

Analyst: MARTI H. BAIRD

Total Number of Pages in Report: 1

Results relate only to samples as received by the laboratory.

Reviewed By


Thoria Nadiem, Analyst

Visit www.slabinc.com for current certifications.

Accrediting bodies: AIHA-LAP, LLC 100527, NVLAP 101150-0, VELAP/NELAC 460135 - Call laboratory for current national and state certifications.

*Minimum Reporting Limit: 10.0 µg. EPA Soil Std for bare residential soil: 400 ppm by wt in play areas; 1200 ppm by wt in bare soil in the remainder of the yard based on an avg of all other samples collected. EPA does not distinguish between lead-contaminated soil and soil-lead hazards. Soil samples are tested as received unless noted as "Dried before analysis." *Data precision justifies 2 sig. figures. All internal QC parameters were met. Unusual sample conditions, if any, are described.*

Abatement Plan for 896-898 Howard Ave, Bridgeport, Ct

A. Background Information

Date Plan Submitted: October 2, 2014

Address of Property: 896-898 Howard Ave., Bridgeport, CT

Plan Prepared by: Owner Planner Project Designer

Lead Planner / Project Designer

Name: Maureen Monaco Certificate: 2152

Telephone: 1-800-959-2985

Address: 287 Main Street, Ansonia, CT 06401

Inspection Report Used to Develop Abatement Plan

Date of Inspection: September 22, 2014

Consultant Contractor: Gilbertco Lead Inspections LLC, 287 Main Street, Ansonia, CT 06401 Consultant Contractor # 270

Telephone- 1-800-959-2985

Inspectors: Maureen Monaco- Lead Inspector Risk Assessor #1172

B. Owner Information

Name: O'Neal and Shena Anderson

Address: 896-898 Howard Ave., Second Floor, Bridgeport, CT

Telephone: 203-338-0053

C. Resident Information

Owner- Anderson family

Number of Children under six years old- one- O'Dayne Anderson dob 3-25-11

Will residents be relocated? Yes No

D. Abatement Contractor Information

Who will conduct abatement? Owner Abatement Contractor

Abatement contractor will submit all licenses and certifications of the company and individuals working on the property and give written notice to the Bridgeport Health Department at least five days prior to commencing the project.

This is a Department of Housing and Urban Development Project receiving Storm Sandy Disaster Recovery funds therefore must go out to bid. Abatement Contractor to be determined.

E. Repairs prior to Abatement

Please Note:

- Water leaks: Must be corrected prior to abatement regardless of the method of abatement. Uncorrected water leaks can cause encapsulating material to fail if the underlying lead painted surface deteriorates. Moisture can also cause paint on stripped surface (and unabated surface) to fail and expose lead residue that may remain on the substrate after stripping by heat, caustic chemicals, solvents or scraping.

- Heating Systems: Inadequate heat after abatement may lead to failure of encapsulants and paint. Therefore heating systems must be repaired. Prior to abatement, forced air systems must be shut down and sealed to prevent transport of lead contamination from the abatement area to other areas of the residence.

What Components or Mechanical Systems Need To Be Repaired Prior To Abatement?

- Water leaks, roof, plumbing, wall surfaces, etc.- Repairs to include interior ceiling and floor repair.
- Heating Systems-
- Electrical Systems
- Any other conditions that require repair so as not to impede abatement.
- No prior repairs required.

F. Abatement Techniques To Be Used

Identify which abatement techniques will be used on the attached forms. The three general strategies for lead paint abatement are removal, replacement, and encapsulation. See attached relevant forms.

A. Removal (REM): stripping of paint

B. Replacement (REP): Architectural replacement components shall conform with all contract requirements and specifications. Product submittal shall conform with requirements of Section 01 33 00-Submittal Procedures.

C. BARRIER: (BAR): enclosure using approved materials such as siding or sheetrock.

D. Liquid Encapsulation: (LENCAP) : Use of Connecticut approved encapsulant; technical information and MSDS attached.

E. Cementitious Encapsulation (CENCAP): provide technical information

* Note: If rigid, liquid or cementitious encapsulants are to be used, the associated surfaces must be periodically monitored in the future per a schedule that is established within a lead management plan. Additionally liquid and cementitious encapsulants must be authorized for use by the Connecticut Department of Public Health (DPH) and listed on the DPH registry of Authorized Encapsulant Products.

Paint Removal means the stripping of lead paint from the surfaces of components. The following are some of the paint removal processes that can be used; chemical stripping, mechanical stripping, and wet scraping/wet sanding.

- **Chemical stripping:** there are a variety of paint removal products that are available from various manufacturers. Commonly the stripper is applied to the building component and later removed by manual scraping. All paint layers must be removed. Follow manufacturer's direction on how to apply such products.
- **Mechanical stripping:** This technique requires the use of power tools. Examples of such equipment are: needle guns, vibrating, belt, and rotary sanders. Abrasive blasting equipment and other types of impact strippers that employ the use of steel studs of different sizes and shapes, that rotate in an enclosed head to impact the painted surface. See manufacturer instructions on how to use this equipment. (Note: Mechanically powered abatement equipment requires the use of HEPA-equipped vacuum attachments to remove dust generated during the use of the equipment).
- **Wet Scraping/wet sanding.** Wet scraping or wet sanding manually removes loose and peeling lead paint. Paint chips and dust that are generated during these procedures, must be controlled, to avoid further distribution of contaminants to adjacent areas. Wet Scraping and sanding involves misting

the peeling paint before scraping or sanding, and thus reducing the amount of lead dust that is generated during these processes. Surfactants (wetting agents) may be added to the water to facilitate cleanup.

- **Heat Gun:** This removal technique involves the softening of the paint with a heat gun and then scraping the paint off. To prevent vaporization of the lead contained in the paint, the temperature of the heat gun must not exceed 700 degrees Fahrenheit per DPH regulations.

Replacement means the removal of components such as windows, doors and trim that have lead painted surfaces and the installation of new components that are free of lead containing paint. Replacement may be feasible for many exterior and interior architectural components. Product submittal shall conform with requirements of Section 01 33 00- Submittal procedures.

Encapsulation refers to the processes that make lead paint inaccessible, by covering or sealing lead painted surfaces. If the lead paint is peeling or deteriorating then some wet scraping and/or wet sanding is necessary prior to encapsulation. The following are some types of rigid encapsulation materials: gypsum dry wall, fiberglass, wool and vinyl siding. Seams must be sealed to prevent the escape of lead dust. Liquid and cementitious encapsulants must be listed on the DPH registry of Authorized Encapsulant Products, to be considered for use.

The following cannot be used as encapsulants:

- A new coat of paint or primer
- Wall paper coverings
- Contact paper

Any area that is to be abated must be properly contained with materials such as 6 mil polyethylene sheeting to prevent further contamination of the dwelling or environment and to facilitate post abatement cleanup.

G. Dates of Abatement Project

Estimated start date: November 1, 2014

Estimated completion date: January 1, 2014

Note: Written notice shall be given to the local health department at least five days prior to actual starting date.

H. Notification To Connecticut Historical Commission- if property is over 50 years old

Year Built: 1920 +/- Notification required? Yes No

Address of Ct Historical Commission:

CT Commission of Culture and Tourism and Historic Preservation
1 Constitution Plaza, Second Floor
Hartford, CT 06103
1-860-256-2800

Date filed- 10/2/14

I. Notification procedure

Written notice will be given to the residents five working days prior to start date.
The notice shall:

- Inform the residents of their rights and responsibilities per the statutes and regulations

- Inform residents which surfaces or soil areas will be abated.

Additionally, warning signs shall be posted at all entrances to and exits from the abatement area, prior to abatement.

J. Containment of Work Area (Interior and Exterior)

Movable objects belonging to residents must be removed from the abatement area. The belongings should be stored in an easily accessible location.

Cover and seal all non-work surfaces with 6 mil polyethylene as follows;

- a) non-movable objects
- b) air systems heating, ventilation, and air conditioning
- c) entrance to abatement areas
- d) floors
- e) exterior grounds and surfaces (use 6 mil polyethylene sheeting to prevent release of lead into the environment)

Note: The contractor and/or owner is responsible for using the best available engineering controls to reduce the potential for emissions to the exterior of an abatement area. Engineering controls may include but not limited to, proper containment and control of the abatement area, provision of negative pressure within containment area, use of wet scraping/wet sanding methods and use of vacuum HEPA attached power tools.

Describe proposed engineering controls:

Polyethylene to cover ground when any exterior work is to be done.

K. Cleaning After Lead- Based Paint Abatement (Prior to Clearance Testing)

- Procedure: 1. Wet clean
2. Carefully remove the polyethylene covering.
3. Use a COMMERCIAL HEPA vacuum and wash with TSP or other effective non-TSP cleaner.
4. After 24 hours from the time active abatement has ceased, HEPA vac again, rewash with TSP or other effective non-TSP cleaner and HEPA vac again.

L. Waste Disposal (Hazardous)

A. Materials associated with the abatement shall be disposed of as hazardous waste with a TCLP reading ≥ 5 mg/l. The contractor shall obtain a small quantity hazardous waste generator ID number from the State of CT DEP for the site if hazardous waste exceeds 100 kilograms per month. Materials associated with this abatement include:

- Any lead containing or lead based paint debris
- Wood painted with lead based paint
- Stripped paint or paint chips
- Painted wall or ceiling plaster
- Painted concrete debris

B. Disposal of all hazardous waste shall comply with the requirements of Resource Conservation and Recovery Act (RCRA).

C. Contractor can wipe clean polyethylene sheeting and dispose of it as construction debris.

D. Dumpsters containing hazardous waste are to be kept covered and locked when not in active use for lading of materials.

E. All containers of hazardous lead bearing material shall carry the following label in accordance with 29 CFR 1926.62.

HAZARDOUS LEAD WASTE

Federal Law prohibits improper disposal.
If found, contact the nearest police or public safety authority,
or the U.S. Environmental Protection Agency

Generator Information:

Facility Name:

Facility Address:

Facility Phone Number:

EPA ID / Manifest Document # _____

Accumulation Start Date: _____

EAP Waste # _____

HAZARDOUS WASTE SOLID NUMBERS

ORM-E NA 9189 D008

HANDLE WITH CARE

Any questions regarding hazardous waste issues should be directed to:

State of CT- Dept of Environmental Protection, Waste Management Bureau, 79
Elm Street, Hartford, CT 06106-5127 ,1- 860-424-3023

M. Worker Protection

Note: Workers must use proper personal protective equipment per the OSHA Lead in Construction Standard (29CFR 1926.62) and state regulation. Full body covering (suits) with hood and shoe covering attached should be used to prevent lead dust contamination. Disposable coveralls that are used one time, provide effective protection. Indicate the level of protection that is to be provided:

Body Covering

Disposable

Head Covering hat

Disposable

Abatement Plan for 896-898 Howard Ave, Bridgeport, Ct

Hand covering

Disposable

Shoe Covering

Disposable

Respirator w/HEPA Filter

Type of respirator _____

Note: Neither smoking, eating, or drinking nor the application of cosmetic lip balm, is permitted within the work area. Use of personal clothing and foot wear is not permitted during abatement activities.

Indicate available washing facilities. Hand washing Showers

Bathroom sink water is available for handwashing; do not use kitchen sink for cleanup.

N. Clearance Testing

Prior to reoccupancy, a visual inspection of abatement areas is required and dust samples shall be collected and analyzed from floors and window sills in each area where abatement has occurred. This inspection and sampling must be performed by a certified lead inspector, certified lead inspector risk assessor or an authorized code enforcement official.

Visual inspection and sampling to be performed by a certified lead risk assessor.

Maureen Monaco , IR #1172
Gilbertco Lead Inspections LLC , CC # 270
287 Main Street, Ansonia, Ct 06401
1-800-959-2985 or

Facilities Support Services LLC
2685 State Street
Hamden, Connecticut 06517
1-203-288-1281

Sampling to include window sill, window well, and floor to be sampled in each room where abatement work has taken place.

Visual Inspection to be performed by an authorized code enforcement official of the Bridgeport Health Department once reoccupancy criteria has been met.

O. Soil Abatement-

1. For soil lead levels between 400 ppm and 5000 ppm

Plant grass or shrubbery to reduce exposure to bare soil.

Permanent barrier; examples asphalt or cement

Cover three to six inches with gravel or mulch-

Restrict access-

Excavate, remove and replace contaminated soil. Specify depth ____.

Relocate play equipment

2. For soil lead levels over 5000 ppm

Excavate and disposal top two inches


Rototill soil

Cover area with lead free soil, mulch, stone, asphalt or other acceptable covering

896-898 Howard Avenue, Bridgeport, Connecticut

Key: PS- Paint Stabilization
 BAR- Barriers
 RESACC- Restricted Access
 REM- Paint Removal
 REP- Replace with new
 LEN- Liquid Encapsulate
 REN- Rigid Encapsulate
 DCU- Dust Clean-up


Room Name	Component	Abatement Method	Comments
2 nd Floor Front Porch	Window Sills	LEN	
2 nd Floor Front Porch	Wood Walls	LEN	
2 nd Floor Front Porch	Clapboard –Wall 3	LEN	
2 nd Floor Rear Porch	Transom	LEN or REN	
2 nd Floor Rear Porch	Threshold	REM	
2 nd Floor Rear Porch	Door Jamb	REM	
Exterior	Rear Door Casing	LEN	
Exterior	Threshold	REM	
Exterior	Basement window trim x 6 or 7	LEN	
Exterior	Front Porch columns	LEN	4 square and 2 round
Exterior	Trim under front porch side 2	REN	
Exterior	Exposed fascia	REN	



Basement wnd trim



exposed drip edge



Exposed Fascia- left side



Front Porch Trim side 2



GILBERTCO LEAD INSPECTIONS, LLC


“LEAD BASED PAINT SPECIALIST”

October 1, 2014

State Historic Preservation Office
One Constitution Plaza
2nd Floor
Hartford, Connecticut 06103

Re: 896-898 Howard Ave., Bridgeport

An inspection of the above mentioned property in anticipation of Storm Sandy Disaster Recovery Block Grant monies revealed several lead hazards that require abatement because a child under the age of six resides on the property. Abatement will include drip edge and soffit repair and encapsulation of the basement window trim and front porch columns. Do you have any input?


Maureen Monaco
Gilbertco Lead Inspections LLC



287 Main Street
Ansonia, CT 06401
203-732-2615 - FAX 866-437-8191
Toll Free In CT Only 1-800-959-2985