

**CONNECTICUT LOCAL BRIDGE PROGRAM**

**Fiscal Year 2002**

**PRELIMINARY APPLICATION**

**VINEYARD ROAD over**

**BURLINGTON BROOK**

*Federal*

**Burlington, CT**

**ConnDOT Bridge No. 05916**

Prepared for the  
Connecticut Department of Transportation  
Local Bridge Program  
Newington, Connecticut

## Table of Contents

1. Application
2. Description / Existing Conditions
3. Proposed Condition
4. Cost Opinion
5. Appendix



CONNECTICUT DEPARTMENT OF TRANSPORTATION



James F Sullivan, Commissioner

PRELIMINARY APPLICATION FOR THE LOCAL BRIDGE PROGRAM

Preliminary application is hereby made by the Town/City/Borough of Burlington for possible inclusion in the Local Bridge Program (C.G.S. Sections 13a - 175p through 13a- 175w ) for Fiscal Year 2002 for the following structure:

Bridge Location: Vineyard Road over Burlington Brook

Bridge Number: 05916 Length of Span: 52 feet

Sufficiency Rating: 65.65% 52.84 Priority Rating: 65.43% 52.69

Evaluation & Rating Data Accomplished by State Forces: Yes x No

Evaluation & Rating Data Accomplished by Others: Yes No

(Professional Certification Required)

If Others, Name of Professional Engineer:

Connecticut Professional Engineers License Number:

Engineer's Address:

Description of Existing Condition of Structure: (attach description)

Description of Scope of Project: (attachment - Include 2 copies of preliminary plans and specifications).

Name of Municipal Official to Contact: Theodore C. Scheidel

Mailing Address: 200 Spielman Highway, Burlington, CT 06013

Telephone: (860) 673-6789 FAX:

E-mail:

Preliminary Cost Figure :

Preliminary Engineering Fees (Include Breakdown of Fees) \$ 176,284

(Not to Exceed 15% of Construction Costs)

Rights-of-Way Cost (If Applicable) \$ N/A

Municipally Owned Utility Relocation Cost \$ N/A

Estimated Construction Costs (Include Detailed Estimate) \$ 1,175,227

Construction Engineering (Inspection, Materials Testing) \$ 176,284

(Not to Exceed 15% of Construction Cost)

Contingencies (10% of Construction Costs Only) \$ 117,522

Total Estimated Project Cost \$ -1,539,547- 1,645,317.06

**Financial Aid Data:**

Federal Reimbursement: (Limited to qualifying bridges – See Appendix 1)

Total Estimated Project Cost multiplied by 80%:

Project Reimbursement Request \$ ~~1,231,637~~ 1,316,253.60

State Local Bridge Project Grant: (Cannot be Combined with federal reimbursement)

Allowable Grant Percentage 30.90% of Total Cost.

Project Grant Request \$ \_\_\_\_\_

State Local Bridge Project Loan: (maximum 50% of total project cost)


Project Loan Request \$ \_\_\_\_\_

**Schedule: (Anticipated Dates)**

Design Completion:	<u>Fall 2003</u>
Property Acquisition Completion:	<u>Spring 2004</u>
Utilities Coordination Completion,	<u>Fall 2003</u>
Construction Advertising:	<u>Fall 2003</u>
Supplemental Application Submission:	<u>Spring 2004</u>
Start of Construction:	<u>Spring 2004</u>
Completion of Construction:	<u>Fall 2004</u>

I hereby certify that the above is accurate and true, to the best of my knowledge and belief.

Signature: \_\_\_\_\_



(Chief Elected Official, Town Manager, or other Officer Duly Authorized)

Date: \_\_\_\_\_

5/15/01

Return completed applications to:

Mr. Stanley C. Juber  
Administrator of the Local Bridge Program  
Connecticut Department of Transportation  
2800 Berlin Turnpike, P.O. Box 317546  
Newington, Connecticut 06131-7546

## **2. Description / Existing Condition**

The bridge carrying Vineyard Road over the Burlington Brook is a simple span composed of a reinforced concrete deck on rolled steel beams located 300' west of Route 4. The original structure was built in 1954. The existing bridge travelway width is approximately 22' and is referenced as ConnDOT Bridge No. 05916. The structure has a clear span of 52' and is eligible for State and Federal funding under the Local Bridge Program for the fiscal year 2002.

### **Deck**

According to the ConnDOT bridge inspection report, dated 11/6/00, the deck is in good condition (rating = 7) with large areas of discoloration and map cracking. There are random small areas of minor cracking with rust and efflorescent staining. There are isolated signs of active leakage along the top flanges of the fascia beams with efflorescence and short stalactites.

### **Superstructure**

According to the ConnDOT bridge inspection report, dated 11/6/00, the overall superstructure is poor (rating = 4). All bearings show areas of paint pitting and light to medium rust. The stringers show areas of paint pitting and flaking with light to medium rust and isolated areas of heavy rust. The south fascia girder shows an area at mid span of laminar rust and pitting with section loss of up to 3/8 inch on the inside of the flange and web due to deck leakage. The north fascia beam shows laminar rust and section loss due to deck leakage about 16 feet from abutment #1.

### **Substructure**

According to the ConnDOT bridge inspection report, dated 11/6/000, the substructure is in fair condition (rating=5). The abutments have random full length vertical cracks extending across the bridge seat and numerous map hairline cracks. Abutment #2 has two isolated horizontal cracks of 36 and 50 inches open 1/8 to 1/4 inch. The wingwalls show vertical, horizontal and map cracks with discoloration and efflorescence.

### **Channel and Channel Protection**

The overall channel protection rating is 6, with embankment erosion both up and down stream exposing tree roots.

### **Approaches**

The approach guide rail is two wire rope on wood posts. Some posts are split and the cable, which is integral with the bridge rail, is loose.

### **3. Proposed Condition**

The substructure of the bridge is in generally good condition and requires only repairs to extend its service life. The poor (rating = 3) deck geometry warrants a deck replacement with a widening of the travelway to meet current standards. The deck replacement and widening would involve the following:

- 1) Remove the existing deck and bridge seats.
- 2) Widen and repair the existing abutments to accommodate a new deck with a 28' travelway.
- 3) Install a new prestressed concrete deck with a 26' travelway.
- 4) Install a new bridge rail system on new reinforced concrete parapets.
- 5) Place membrane waterproofing over the entire structure.
- 6) Install new guide railing and approaches.

Estimated construction cost for the work is \$1,175,227.00. A detailed estimate is provided on the following pages.

**Town of Burlington**  
**Vineyard Road over Burlington Brook**  
**Bridge No. 05916**  
**Federal Local Bridge Program**

**Preliminary Cost O**

Item No	Description	Unit	Est Qu		
<b>Structure Items</b>					
1A	Bituminous Concrete Class 1	Ton	17	\$51.71	\$888
1B	Bituminous Concrete Class 2	Ton	9	\$51.71	\$465
2	Membrane Waterproofing	S.Y.	203	\$43.48	\$8,837
3	Remove Existing Structure	L.S.	1	\$134,400.00	\$134,400
4	Class "A" Concrete	C.Y.	755	\$500.00	\$377,267
6	Deformed Steel Bars	LBS.	34713	\$0.96	\$33,325
7	Elastomeric Bearing Pads	Ea.	32	\$100.00	\$3,200
8	Prestressed Concrete Deck Units	L.F.	432	\$200.00	\$86,400
10	Metal Bridge Rail	L.F.	108	\$151.79	\$16,393
11	Structure Excavation	C.Y.	2202	\$18.35	\$40,400
12	Pervious Structural Backfill	C.Y.	1670	\$22.94	\$38,300
Structure Subtotal:					\$738,988
20% Contingency:					\$147,798
<b>Structure Total</b>					<b>\$886,785</b>
<b>Highway &amp; Stream Channel</b>					
1	Unsuitable Excavation	C.Y.	152	\$22.17	\$3,377
2	Borrow	C.Y.	441	\$12.23	\$5,392
3	Maintenance and Protection of Traffic	L.S.	1	\$10,000.00	\$10,000
6	Roadway Excavation	C.Y.	441	\$13.76	\$6,066
7	Subbase	C.Y.	1439	\$15.29	\$21,995
8	Formation of Subgrade	S.Y.	1883	\$1.67	\$3,145
9	Bituminous Concrete	TON	939	\$51.71	\$48,566
10	Mobilization	L.S.	1	\$63,500.00	\$63,500
12	Barricade Warning Lights	EA./DAY	1337	\$0.90	\$1,204
13	Temporary Precast Concrete Barrier C	L.F.	157	\$11.28	\$1,767
14	Signs	S.F.	120	\$15.79	\$1,895
15	Metal Beam Rail (Type R-B)	L.F.	320	\$11.89	\$3,810
16	Guide Rail Anchors	EA.	4	\$575.00	\$2,300
18	Water Pollution Control	Est	1	\$10,000.00	\$10,000
19	Erosion and Sedimentation Control	L.F.	1447	\$5.49	\$7,944
20	Construction Staking	L.S.	1	\$11,650.00	\$11,650
21	Riprap	C.Y.	4	\$74.16	\$273
22	Catch Basins	EA.	4	\$1,500.00	\$6,000
24	Granite Stone Transition Curbing	L.F.	100	\$30.00	\$3,000
25	Turf Establishment / Topsoil	S.Y.	2222	\$8.86	\$19,684
26	Construction Trailer	Mo.	8	\$1,100.00	\$8,800
Highway & Stream Channel Subtotal:					\$240,368
20% Contingency:					\$48,074
<b>Highway &amp; Stream Channel Subtotal</b>					<b>\$288,442</b>
<b>Estimated Total Construction Cost:</b>					<b>\$1,175,227</b>

# STRUCTURE NO. 05916

VINEYARD ROAD  
over  
BURLINGTON BROOK  
BURLINGTON

*Routine Inspection*  
on  
*1/3/2006*

*Inspected by Team 5*  
*for Area 5*

<b>TEAM:</b>	Forwarded to Senior	Sandra Dumas	Date	3/8/2007
<b>SENIOR:</b>	Reviewed by Senior	Sandra Dumas	Date	3/18/2007
	BMM Required		No	
	Town Bridge		Yes	
	Rating <= 5 (Items 58,59,60 or 62)		Yes	
	Forwarded to Supervisor	Sandra Dumas	Date	3/19/2007
	Forwarded to "To Be Copied Drawer"	<input type="checkbox"/>	Date	
	Date BRI-19 Entered		3/19/2007	
<b>SUPERVISOR:</b>	Reviewed by Supervisor		Date	
<b>SUPPORT:</b>	Date Copies Made	4-5-07	BMM No	four

**NBI: Yes**

Structure No. **05916** Town **BURLINGTON**  
Inspection Date **1/3/2007** Inspectors **Team 5**

# TABLE OF CONTENTS

## Loose Forms (not bound in report)

		Number of Sheets Enclosed
Maintenance Memo		<input type="text" value="0"/>
Flagging Memos		<input type="text" value="0"/>
PONTIS Element Data Collection Form		<input type="text" value="1"/>
Plan Sheets	Already on file <input type="checkbox"/>	<input type="text" value="0"/>

## Bound Report Pages

Title Cover Sheet		<input type="text" value="1"/>
Table of Contents		<input type="text" value="1"/>
Executive Summary		<input type="text" value="0"/>
Field Notes		<input type="text" value="0"/>
Calculations:	Load Rating Evaluation	<input type="text" value="0"/>
	Quantities & Cost Estimate	<input type="text" value="0"/>
Photo Sheets		<input type="text" value="8"/>
Photo Images		<input type="text" value="16"/>

## Forms

BRI-10, Concrete Deterioration Worksheet	<input type="text" value="1"/>
BRI-18, Bridge Inspection Form	<input type="text" value="5"/>
BRI-19, Highway Bridge Inventory Form	<input type="text" value="2"/>

## Comments:

**(1) Attached sheet.**

Bridge Number **05916**

Inspected By: *P. Talbot & K. Weir*

Sufficiency Rating **52.84**  
Previous Inspection Date **1/24/2005**

BS&E Received  Data Entry By: *Red*  
Copies Made  Data Entry Date: **3/19/07**

STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION  
BRIDGE SAFETY & EVALUATION  
**STRUCTURE EVALUATION**  
SHEET 1 OF 2 FORM BR-19 REV 10/00

SHEET **3** OF **11**  
(INSP. REPORT)

IDENTIFICATION

Bridge Name **BURLINGTON** Town Code **10100**

Inventory Route: **1**  
A) Record Type **1** B) Signing Prefix **5** C) Level of Service **0**  
D) Route Number **00000** E) Directional Suffix **0** NA

Feature Intersected **BURLINGTON BROOK**  
Facility Carried **VINEYARD ROAD**

Location **300 WEST OF RTE 4**

11) Milepoint **36.63** Miles  
16) Latitude **41 deg 46 min 30.00 sec**  
17) Longitude **72 deg 56 min 12.00 sec**

98) Border Bridge:  
A) State Code  B) Percent Responsibility  %  
C) Border Town Name

STRUCTURE TYPE AND MATERIAL

43) Structure Type, Main: **3** Steel  
A) Material **3** Steel  
B) Design Type **2** Stringer/Multi-beam

44) Structure Type, Approach:  
A) Material **0** Other B) Design Type **0** Other

45) Number of Spans, Main Unit **1**  
46) Number of Approach Spans **0**  
107) Deck Structure Type **1** Concrete Cast-in-Place  
108) Wearing Surface/Protective System:

A) Type of Wearing Surface **6** Bituminous  
B) Type of Membrane **0** None  
C) Type of Deck Protection **0** None

90) Inspection Date **01/03/07** Inspection Team **505** Frequency Class: **24** 01  
Indepth Insp **1/16/2006** Deck Survey **0** Access **0** Flagman **0**  
CRITICAL FEATURE INSPECTIONS  
Type Frequency Team Date  
Fracture:      
Uwater:      
Special:

RED FLAG

AGE AND SERVICE  
27) Year Built **1964** 106) Year Reconstructed **0000**  
42) Type of Service: **1** Highway  B) Under **5** WATERWAY

28) Number of Lanes: **2**  
A) On  B) Under   
29) Average Daily Traffic **1000**  
109) Percent Truck **7%** Half ADT?: **No**

30) Year of ADT **1992**  
19) Bypass, Detour Length **1** miles

GEOMETRIC DATA

48) Length of Max Span **52** ft  
49) Structure Length **58** ft

50) Curb or Sidewalk Widths:  
A) Left **0.7** ft B) Right **0.7** ft

51) Brg Rdwy width curb-curb **22.1** ft  
52) Deck Width, Out-Out **25.5** ft

32) Approach Roadway Width **22** ft  
33) Bridge Median **No Median**

34) Skew Angle **0** deg  
Deck Area **1480** sqft


35) Structure Flared **0**  
10) Inv. Rte. Min. Vert Clearance **99** ft

47) Log Inv. Rte. Total Horiz. Clr.: **22.1** ft  
53) Min Vert Clearance Over Bridge **99** ft

54) Min Vert Under Clearance **99** in  
55) Min Lat Under Clearance on Right **0** in  
56) Min Lat Under Clearance on Left **0.0** ft

BRIDGE COMMENTS:

*ADT's shown*



**CLASSIFICATION**

112) NBIS Bridge Length	Yes	
104) Highway System	0	Off System
26) Functional Class	9	Rural Local
100) Defense Highway	0	Not Defense Highway
101) Parallel Structure	N	No parallel structure exists
102) Direction of Traffic	2	2-way traffic
103) Temporary Structure	0	Not on national network
110) Designated National Network	0	On Free Road
20) Toll	3	Town or Township Highway Agency
21) Maintain	3	Town or Township Highway Agency
22) Owner	L	LOCAL
Report Class	5	Bridge is not eligible for National Register
37) Historical Significance		

**WATERWAY**

DrainageBasinCode	4311	
38) Navigation Control	0	No navigation control on waterway
39) Navigation Vert Cir.	0	40) Navigation Horiz Cir.
116) Vert-Lift Brig Nav Min		
111) Pier Abutment Protection		

**PROPOSED IMPROVEMENTS**

75A) Type of Work Proposed	Replacement - substandard	
75B) Work Done By	Work done by owner's forces	
76) Length of Struct. Improvement	ft	
94) Bridge Improvement Cost	\$	
95) Roadway Improvement Cost	\$	
96) Total Project Cost	\$	
97) Year of Improvement	Cost Est.	
114) Future ADT		115) Year Future ADT
List No.	Project No.	Advised

**POSTED SIGNS & UTILITIES**

Other Posted Signs 1	0	Other warning signs	
Other Posted Signs 2	0	One lane bridge	
Actual P.L. Single Unit Truck	tons	Actual P.L. 4Axle Truck	tons
Rec. P.L. Single Unit Truck	tons	Rec. P.L. 4Axle Truck	tons
Actual P.L. Semi-Trailer Truck	tons	Actual P.L. 3S2 Truck	tons
Rec. P.L. Semi-Trailer Truck	tons	Rec. P.L. 3S2 Truck	tons
Rec. P.L. All Vehicles	tons	Actual P.L. All Vehicles	tons
Posted Vert Clearance On Bridge	ft		ft
Posted Vert Under Clearance	ft		ft
Posted Speed Limit	25 mph		

**STRUCTURE EVALUATION**

SHEET 2 OF 2 FORM BRL-19 REV 10/00  
 SHEET 4 OF 11 (INSP. REPORT)  
 Inspected By: *P. Talbot* & *H. Weir*

Bridge Number	05916	NBIS Length	
Town Name	BURLINGTON	Yes	58
Facility Carried	VINEYARD ROAD		
Feature Crossed	BURLINGTON BROOK		

31) Design Load	5	LOAD RATING AND POSTING	
63) Operating Rating Type	1	Evaluation Code	L
64) Operating Rating	70.0	Year of Evaluation	1997
65) Inventory Rating Type	1	70) Bridge Posting	5
66) Inventory Rating	42.0	41) Structure Status	AL
		Open, no restriction	

**CONDITION**

58) Deck	7	Rating	By	APPRAISALS	Rating	By
59) Superstructure	4			67) Structure Evaluation	4	02
60) Substructure	5			68) Deck Geometry	4	01
61) Channel & Chan. Protection	6			69) Under Clear Vert & Horiz	N	01
62) Culverts	6			71) Waterway Adequacy	7	01
				72) Approach Rdwy Alignment	7	01
				113) Scour Critical	8	01

Items 58 Thru 72 Checked By: *J. Durso*

36) Traffic Safety Features:	0	
A) Bridge Railings	0	0
B) Transitions	0	0
C) Approach Guardrail	0	0
D) Approach Guardrail End	0	0

**OTHER FEATURES**

Fence Required	No	Barrel Ladder	No
Fence Present	No	Stand Pipes	No
Fence Height	0.0 ft	Cat Walks	No
Fence Type	Combination	Movable Inspection System	No
Fence Material	Other	Loose Concrete Checked?	No
Fence Top Type	Vertical		

**INSPECTION COMMENTS**

Proposed Next Indepth Insp Year	2010	
Senior Supervisor	<i>degrishnok</i>	
Supervisor	<i>lapierleid</i>	

REVIEWED BY: *J. Durso* Date: *3/19/07*

# Connecticut Department of Transportation

## Bridge Inspection Report BRI-18

**BRIDGE #:** 05916

**INSPECTION DATE:** 1/3/2020

**INSPECTION TYPE:** Routine    **PREVIOUS INSPECTION DATE:** 1/24/2005    **SNOOPER REQUIRED:** No  
**INSPECTION PERFORMED BY:** Team 5    **SNOOPER USED:** No

**TOWN:** BURLINGTON    **FEATURE CARRIED:** VINEYARD ROAD    **YEAR BUILT:** 1954  
**LOCATION:** 300' WEST OF RTE 4    **FEATURE INTERSECTED:** BURLINGTON BROOK    **YEAR REBUILT:** 0  
**MAIN MATERIAL:** Steel    **MAIN DESIGN:** Stringer/Multi-beam or Girde

**INSPECTION VISITS:**

**Inspection Date:** 1/3/2007    **Start Time:** 11:00 AM  
**Temperature:** 40 ° F    **End Time:** 12:15 PM

**INSPECTORS:**

**Inspector:** D. Talmont    **Task:** Routine Inspection  
**Inspector:** K. Weir    **Task:** Routine Inspection

**58. DECK**

**OVERALL RATING** 7

	RATING	
OVERLAY	<span style="border: 1px solid black; padding: 2px;">8</span>	BITUMINOUS CONCRETE WEARING SURFACE WITH ADDED CHIP SEAL & NO MEMBRANE WATERPROOFING. INSIDE VERTICAL FACE OF RAILBASES REVEALED UP TO 11 INCHES +/- SEE PHOTO 2.
DECK STR. CONDITION	<span style="border: 1px solid black; padding: 2px;">7</span>	UNDERSIDE SHOWS LOW % DETERIORATION. LARGE AREAS OF DISCOLORATION WITH CURING TYPE MAP CRACKING AND AREAS OF FROSTING. ALSO, RANDOM SMALL AREAS OF MINOR CRACKING WITH RUST AND EFFLORESCENCE STAINING WITH ISOLATED SHORT STALACTITES. ISOLATED SIGNS OF ACTIVE LEAKAGE ALONG TOP FLANGES OF BEAMS #1 AND #4 WITH EFFLORESCENCE AND SHORT STALACTITES. SEE PHOTO 5.
CURBS	<span style="border: 1px solid black; padding: 2px;">N</span>	
MEDIAN	<span style="border: 1px solid black; padding: 2px;">N</span>	
SIDEWALKS	<span style="border: 1px solid black; padding: 2px;">N</span>	
PARAPET	<span style="border: 1px solid black; padding: 2px;">7</span>	CONCRETE RAILBASE SHOWS RANDOM VERTICAL CRACKS, MINOR COLLISION SPALLS & SCRAPES AT ENDS. LIGHT ACCUMULATION ON SAND ON TOP.
RAILING	<span style="border: 1px solid black; padding: 2px;">6</span>	"H" POSTS WITH CHANNEL CAP AND (2) WIRE CABLES. PAINT SHOWS AREAS OF PITTING WITH LIGHT RUST AND BASE PLATES SHOW SAND BUILT-UP ALONG BASE WITH POCKETS OF HEAVY TO LAMINAR RUST PAINTED OVER, & SOME ANCHOR NUTS ROSEBUDDING.
PAINT	<span style="border: 1px solid black; padding: 2px;">N</span>	
FENCE	<span style="border: 1px solid black; padding: 2px;">N</span>	
DRAINS	<span style="border: 1px solid black; padding: 2px;">N</span>	
LIGHTING STANDARD	<span style="border: 1px solid black; padding: 2px;">N</span>	
UTILITIES TYPE/SIZE	<span style="border: 1px solid black; padding: 2px;">N</span>	
CONSTRUCTION JOINTS	<span style="border: 1px solid black; padding: 2px;">N</span>	
EXPANSION JOINTS	<span style="border: 1px solid black; padding: 2px;">N</span>	INDISCRIMINATE BITUMINOUS WEARING SURFACE OVER EXPANSION JOINTS SHOW FULL WIDTH TRANSVERSE CRACKS OPEN UP TO 1/4 INCH +/- SEE PHOTO 3.

**59. SUPERSTRUCTURE**

**OVERALL RATING** 4

	RATING	
BEARING DEVICES	<span style="border: 1px solid black; padding: 2px;">6</span>	ALL BEARINGS SHOW AREAS OF PAINT PITTING WITH AREAS OF LIGHT TO MEDIUM RUST, EXPOSED PRIMER.

6 OF 11

# Connecticut Department of Transportation

## Bridge Inspection Report BRI-18

**BRIDGE #:** 05916

**INSPECTION DATE:** 1/3/2020

**59. SUPERSTRUCTURE**

**OVERALL RATING** 4

ABUTMENT #1 (FIXED) BEARING #1 SHOWS HEAVY RUST. SEE PHOTOS 12 & 14.

STRINGERS N

GIRDERS 4

STRINGERS SHOW AREAS OF PAINT PITTING AND FLAKING WITH LIGHT TO MEDIUM RUST & SMALL AREAS OF EXPOSED PRIMER. ALSO, ISOLATED AREAS OF HEAVY RUST. SOUTH FASCIA SHOWS 13 LINEAR FEET +/- OF LAMINAR RUST AND HEAVY PITTING WITH SECTION LOSS RANGING FROM MINOR TO APPROXIMATELY 3/8 INCHES +/- LOCATED ON INSIDE OF FLANGES AND WEB AREA NEAR MID SPAN, CAUSED FROM DECK LEAKAGE ABOVE.

MOST OF THE RUST WAS REMOVED DURING FIELD INSPECTION & REMEASURED. BEAM #4 NORTH EDGE OF BOTTOM FLANGE APPROXIMATELY 2 FEET 8 INCHES FROM WEST INTERMEDIATE DIAPHRAGM SHOWED FLANGE WITH APPROXIMATELY 1/4 INCH REMAINING FOR 12 INCHES LONG UP TO 2 -1/2 INCHES WIDE.

NORTH FASCIA OUTSIDE FACE SHOWS AREA OF HEAVY TO LAMINAR RUST ON BOTTOM FLANGE AND LOWER WEB AREA WITH MINOR LOSS, EXTENDING FOR APPROXIMATELY 16 FEET +/- FROM ABUTMENT #1 WITH ADJACENT 3 FOOT AREA OF LAMINAR RUST ON BOTTOM OF TOP FLANGE WITH HEAVY PITTING. ALSO, INSIDE BOTTOM OF TOP FLANGE AT SAME LOCATION SHOWS AREAS OF LAMINAR RUST, CAUSED FROM DECK LEAKAGE ABOVE. SEE ATTACHED SKETCH & PHOTOS 6 THRU 9.

FLOOR BEAMS N

TRUSSES-GENERAL N

TRUSSES-PORTALS N

TRUSSES-BRACING N

PAINT 5

SEE PHOTO

RUST 4

SEE ABOVE.

MACHINERY MOV SPAN N

RIVETS & BOLTS 7

WELDS & CRACKS 8

COVER PLATES LOCATED ON INTERIOR BEAMS ONLY.

TIMBER DECAY N

CONCRETE CRACKING N

COLLISION DAMAGE 8

MEMBER ALIGNMENT 8

DEFLECT. UNDER LOAD N

VIBR. UNDER LOAD N

STAND PIPES N

BARREL LADDERS N

ARE BARREL LADDERS OSHA COMPLIANT? NA

**60. SUBSTRUCTURE**

**OVERALL RATING** 5

**RATING**

ABUTMENTS-STEM 5

ABUTMENTS SHOW AREAS OF LIGHT SCALE AND NUMEROUS MAP HAIRLINE CRACKS WITH DISCOLORATION & SOME LIGHT EFFLORESCENCE. ALSO, RANDOM FULL HEIGHT

7 OF 11

# Connecticut Department of Transportation

## Bridge Inspection Report BRI-18

**BRIDGE #:** 05916

**INSPECTION DATE:** 1/3/2020

**60. SUBSTRUCTURE**

**OVERALL RATING** 5

VERTICAL CRACKS, SOME OPEN UP TO 0.030 INCHES +/- EXTENDING ACROSS SEAT. ABUTMENT #2 SHOWS MODERATE TO HEAVY SCALE UNDER 4 INCH WEEP DRAINS. NORTH END FACE SHOWS (1) ISOLATED 50 INCH HORIZONTAL CRACK OPEN UP TO 1/4 INCHES +/-.  
SOUTH END FACE SHOWS (1) ISOLATED 36 INCH HORIZONTAL CRACK OPEN UP 1/8 INCHES +/- EXTENDING DIAGONALLY DOWNWARDS. ALSO, ABUTMENT SHOWS RANDOM HORIZONTAL & DIAGONAL CRACKS WITH MODERATE EFFLORESCENCE & RUST STAINS.  
SEE PHOTOS 11 & 13.

ABUTMENTS-BACKWALL	<span style="border: 1px solid black; padding: 2px;">7</span>	BACKWALL #2 BAY #2 SHOWS (1) ISOLATED FULL HEIGHT VERTICAL CRACK EXTENDING FROM ABUTMENT.
ABUTMENTS-FOOTINGS	<span style="border: 1px solid black; padding: 2px;">N</span>	NOT VISIBLE.
ABUT.-SETTLEMENT	<span style="border: 1px solid black; padding: 2px;">7</span>	NORTHWEST WINGWALL JOINT MISALIGNED AT TOP 7/8 INCH AND OPEN 1-1/4 INCH. (NO CHANGE)
ABUTMENTS-WINGWALLS	<span style="border: 1px solid black; padding: 2px;">6</span>	WINGWALLS SHOW VERTICAL, HORIZONTAL AND MAP CRACKS WITH DISCOLORATION & EFFLORESCENCE. ALSO, SOME STAINING FROM POUR LINES. NORTHWEST WINGWALL SHOWS (1) ISOLATED 43 INCH HORIZONTAL CRACK OPEN UP TO 1/16 INCH. NORTHEAST WINGWALL SHOWS AREAS OF ACTIVE LEAKAGE THIS INSPECTION. SEE PHOTO 10.
PIERS/BENTS-CAPS	<span style="border: 1px solid black; padding: 2px;">N</span>	
PIERS/BENTS-PILE BENT	<span style="border: 1px solid black; padding: 2px;">N</span>	
PIERS/BENTS-COLUMN	<span style="border: 1px solid black; padding: 2px;">N</span>	
PIERS/BENTS-FOOTINGS	<span style="border: 1px solid black; padding: 2px;">N</span>	
PIERS/BENTS-SETTLEMENT	<span style="border: 1px solid black; padding: 2px;">N</span>	
EROSION-SCOUR	<span style="border: 1px solid black; padding: 2px;">8</span>	
CONCRETE CRACK-SPALL	<span style="border: 1px solid black; padding: 2px;">6</span>	SEE ABOVE ITEMS.
STEEL CORROSION	<span style="border: 1px solid black; padding: 2px;">N</span>	
PAINT	<span style="border: 1px solid black; padding: 2px;">N</span>	
TIMBER DECAY	<span style="border: 1px solid black; padding: 2px;">N</span>	
COLLISION DAMAGE	<span style="border: 1px solid black; padding: 2px;">N</span>	
DEBRIS	<span style="border: 1px solid black; padding: 2px;">7</span>	LIGHT TO MODERATE ACCUMULATION OF PIGEON DROPPINGS AND SMALL STONES LOCATED ON SEATS.

**61. CHANNEL PROTECTION**

**OVERALL RATING** 6

	RATING	
CHANNEL SCOUR	<span style="border: 1px solid black; padding: 2px;">8</span>	LARGE ROCKS & BOULDERS LINE CHANNEL.
EMBANKMENT EROSION	<span style="border: 1px solid black; padding: 2px;">6</span>	EMBANKMENT EROSION LOCATED UP AND DOWNSTREAM EXPOSING TREE & BRUSH ROOTS.
DEBRIS	<span style="border: 1px solid black; padding: 2px;">6</span>	OBSTRUCTION - LARGE GRAVEL ENCROACHMENT AT WEST WITH MODERATE VEGETATION GROWTH RESTRICTS CHANNEL FLOW. SEE CHANNEL CHANGE BELOW. SEE PHOTO 4.
VEGETATION	<span style="border: 1px solid black; padding: 2px;">7</span>	TREES OVERHANGING CHANNEL.
CHANNEL CHANGE	<span style="border: 1px solid black; padding: 2px;">6</span>	FREEBOARD - 9 FEET 5 INCHES +/-. AVERAGE WATERDEPTH - 12 INCHES +/-. MEASUREMENT TAKEN AT MIDSPAN INLET END.

# Connecticut Department of Transportation Bridge Inspection Report BRI-18

BRIDGE #: **05916**

INSPECTION DATE: **1/3/2020**

61. CHANNEL PROTECTION  OVERALL RATING **6**

ALIGNMENT - STREAM ENTERS STRUCTURE AT MODERATE ANGLE WITH FLOW ALONG THE SOUTHEAST CHANNEL EMBANKMENT AND ABUTMENT #2.  
AVERAGE WATERDEPTH ALONG ABUTMENT #2 17 INCHES +/- THIS INSPECTION.

FENDER SYSTEM **N**

SPUR DIKES & JETTIES **N**

RIP RAP **7**

RIP RAP PARTIALLY BURIED UNDER ENCROACHMENT.

62. CULVERTS & RETAINING WALL  OVERALL RATING **N**

APPROACH CONDITION  OVERALL RATING **6**

RATING

APPROACH SLAB **N**

RELIEF JOINTS **N**

APPROACH GUIDE RAIL **6**

(2) WIRE CABLES WITH WOOD POSTS.  
SEVERAL POSTS SPLIT AND WEATHERED & SEVERAL HAVE BEEN REPLACED.  
NORTHWEST SHOWS (1) POST TIPPED.  
SLIGHTLY LOOSE CABLES ARE INTEGRAL WITH BRIDGE RAILING.

APPROACH PAVEMENT **7**

BITUMINOUS CONCRETE WITH ADDED CHIP SEAL.  
WEST APPROACH SHOWS RANDOM TRANSVERSE CRACKS, SOME FULL WIDTH AND ISOLATED LONGITUDINAL CRACKS. ALSO, SOME "D" CRACKING ALONG DECK END.  
EAST APPROACH SHOWS A TRANSVERSE CRACK & RANDOM LARGE "D" CRACKS AT DECK END WITH SETTLEMENT UP TO 3/4 INCHES +/-.  
SEE PHOTO 1.

APPROACH EMBANKMENT **8**

**TRAFFIC SAFETY FEATURES:**

BRIDGE RAILINGS **0**

TRANSITIONS **0**

APPROACH GUARDRAILS **0**

APPR. GUARDRAIL ENDS **0**

**LOAD POSTING**

SINGLE UNIT (TONS)

HS (TONS)

4 AXLE (TONS)

3S2 (TONS)

ADVANCE WARNING Y/N **N**

LEGIBILITY **N**

VISIBILITY/LOCATION **N**

**MISC.**

MIN VERT. UNDERCLR.  0'  0"

POSTED CLR. UNDER BRIDGE  '  "

# Connecticut Department of Transportation Bridge Inspection Report BRI-18

BRIDGE #: **05916**


INSPECTION DATE: **1/3/2020**

POSTED CLR. ON BRIDGE	<input type="checkbox"/> ' <input type="checkbox"/> "	
ADVANCE WARNING (Y/N)	<input type="checkbox"/> No	
SPEED LIMIT (IF ANY)	<input type="checkbox"/> 25 MPH	
CHARACTER OF TRAFFIC		

ADDITIONAL NOTES  
LIGHT - LOW% TRUCKS.

ADDITIONAL COMMENTS:

Inspectors' Signatures:

1)		Date: <u>01/28/2007</u>
2)		Date: <u>1.8.07</u>
3)	_____	Date: <u>__/__/__</u>
4)	_____	Date: <u>__/__/__</u>

P.E. Signature: \_\_\_\_\_ Date: \_\_/\_\_/\_\_  
 P.E.#: \_\_\_\_\_

Reviewed by: Sandra A Demas CDOT Date: 3,18,07