

Federal

CONNECTICUT DEPARTMENT OF TRANSPORTATION

The Honorable Emil H. Frankel, Acting Commissioner



PRELIMINARY APPLICATION FOR THE LOCAL BRIDGE PROGRAM

Preliminary application is hereby made by the Town/City/Borough of Plainfield for possible inclusion in the Local Bridge Program for Fiscal Year 2009 for the following structure:

Bridge Location: Sterling Hill Road over Ekonk Brook

Bridge Number: 04751 Length of Span: 23 feet

Sufficiency Rating: 49.98 Priority Rating: 48.92

Evaluation & Rating Performed by: xx State Forces Others

If Others, Name of Professional Engineer:

Connecticut Professional Engineers License Number:

Engineering Firm:

Engineer's Address:

Engineer's E-mail Address:

Description of Existing Condition of Structure: (attach description) see attached

Description of Project Scope: A (note repair code; attach narrative/preliminary plans & specifications).

Municipal Official to Contact (name & title): Paul E. Sweet, First Selectman

Mailing Address: 8 Community Avenue, Plainfield, CT 06374

Telephone: (860) 230-3001 FAX: (860) 230-3033

E-mail: selectman@plainfieldCT.com

Schedule: (Anticipated Dates)

Public Hearing Conducted: September, 2008

Design Completion: November, 2009

Property Acquisition Completion: N/A


Utilities Coordination Completion: September, 2009

Construction Advertising: January, 2010

Supplemental Application Submission: March, 2010

Start of Construction: April, 2010

Completion of Construction: November, 2010



PROJECT SITE
BR# 04751

9

8

7

JOINS

River

PROSPECT
WARD

GENDRON
ROAD

HILL
STREET

ROAD

ROAD

ROAD 200

200

MAIN ST
BARBER
MILL RD
VALLEY

STREET
MOSUP
RD

ST
MOSUP
ES

POTVIN AV
NORTH
SOUTH
LINNELL ST

AV
MAY
SUZIE
TOM AV

AV
MAY
SUZIE
TOM AV

AV
MAY
SUZIE
TOM AV

Plairfield
Catholic Sch

GRAHAM
JACQUES

BITGOOD
VILLAGE ST

MAPLE ST

VILLAGE
CENTER

ST
UNION

ST
MAY

GORMAN
ST

ST
MAY

Replacement of Sterling Hill Road Bridge over Ekonk Brook, Bridge No. 04751 Plainfield, CT

Existing Conditions:

Sterling Hill Road is a two-lane rural major access road in the town of Plainfield. The road carries local vehicular traffic, including school buses and commercial trucks, and runs east-west between Plainfield Road and Route 14A. Average Daily Traffic (ADT 1992) is 1,000 of which 7% is trucks. Estimated detour length is 3 miles.

The Sterling Hill Road Bridge (No. 04751) was constructed in 1950. The bridge is a single span structure with a clear span of 23' and total length of approximately 30'. The bridge has a roadway width of 20.2' between metal bridge railings. There are no curbs or parapets. The bridge is located on a straight tangent portion of the road and has a down grade from west to east.

The bridge superstructure consists of steel stringers and corrugated metal deck pan filled with bituminous concrete. The substructure consists of dry laid stone masonry abutments and flared wingwalls.

The structure opening appears to be hydraulically inadequate, as significant ponding occurs upstream of the bridge causing flooding to the adjacent property. The banks show significant erosion.

The roadway profile needs improvement to diminish sharp drop on the west approach. Minimum roadway width for the rural collector will be 26' (11' lanes and 2' shoulders).

There are overhead utilities on the downstream side.

The bridge is in poor condition and requires full replacement.

Proposed Construction:

1. Remove existing superstructure and the stone masonry superstructure to 2yr. flow elevation for critter passage use.
2. Construct 34' clearspan precast concrete rigid trane structure with reinforced concrete footing supported on steel H-piles. U-type concrete wingwall will be used.
3. Roadway width between curbs will be 26' and out to out bridge width will be 30'.
4. 3-bar aluminum bridge railing with concrete endposts will be used.
5. Roadway profile will be adjusted to meet the AASHTO/CDOT minimum criteria for 40 to 45 mph speed.
6. R-B 350 guiderailing will be used on the approaches. Approximately 500 L.F. of roadway will be reconstructed.

Bridge Number **04751**

STATE OF CONNECTICUT
DEPARTMENT OF TRANSPORTATION
BRIDGE SAFETY & EVALUATION
STRUCTURE EVALUATION

90) Inspection Date	Inspection Team	91) Frequency	Class:
4/8/2002	3	24	01
Indepth Insp	Deck Survey	Access	Flagman
4/8/2002		0	0
CRITICAL FEATURE INSPECTIONS			
Type	Frequency	Team	Date
Fracture:			
Uwater:			
Special:			

Inspected By: _____ & _____

Sufficiency Rating **49.7**
Previous Inspection Date **1/10/2006**

SHEET 1 OF 2 FORM BRI-19 REV 10/00

BS&E Received Data Entry By: _____
Copies Made Data Entry Date: _____

SHEET _____ OF _____ (INSP. REPORT)

RED FLAG

IDENTIFICATION

Bridge Name **PLAINFIELD** Town Code **59980**

5) Inventory Route:
 A) Record Type **1**
 B) Signing Prefix **5** City Street
 C) Level of Service **0** None of the bel
 D) Route Number **00000**
 E) Directional Suffix **0** NA

6) Feature Intersected **EKONK BROOK**

7) Facility Carried **STERLING HILL ROAD**

9) Location **575 FT EAST OF GENDRON RD**

11) Milepoint **1.41** Miles

16) Latitude **41 deg 42 min 42.00 sec**
 17) Longitude **71 deg 52 min 36.00 sec**

98) Border Bridge:
 A) State Code _____ B) Percent Responsibility _____ %
 C) Border Town Name _____

99) Border Bridge Structure No _____

STRUCTURE TYPE AND MATERIAL

43) Structure Type, Main:
 A) Material **3** Steel
 B) Design Type **2** Stringer/Multi-beam

44) Structure Type, Approach:
 A) Material **0** Other
 B) Design Type **0** Other

45) Number of Spans, Main Unit **1**
 46) Number of Approach Spans **0**

107) Deck Structure Type **6** Corrugated Steel

108) Wearing Surface/Protective System:
 A) Type of Wearing Surface **6** Bituminous
 B) Type of Membrane **0** None
 C) Type of Deck Protection **0** None

AGE AND SERVICE

27) Year Built **1950** 106) Year Reconstructed **0000**

42) Type of Service:
 A) On **1** Highway
 B) Under **5** WATERWAY

28) Number of Lanes:
 A) On **2**
 B) Under **0**

29) Average Daily Traffic **1000** Half ADT?: **No**

109) Percent Truck **7** %

30) Year of ADT **1992**

19) Bypass, Detour Length **3** miles

GEOMETRIC DATA

48) Length of Max Span **23** ft
 49) Structure Length **30** ft

50) Curb or Sidewalk Widths:
 A) Left **0.0** ft
 B) Right **0.0** ft

51) Brg Rdwy width, curb-curb **20.2** ft
 52) Deck Width, Out-Out **20.5** ft
 32) Approach Roadway Width **18** ft
 33) Bridge Median **0** No Median
 Deck Area **615** sqft
 34) Skew Angle **23** deg
 35) Structure Flared **0**

10) Inv. Rte. Min. Vert Clearance **99** ft **99** in
 47) Log Inv. Rte. Total Horiz Clr.: **20.2** ft
 47) RLog Inv. Rte. Total Horiz. Clr.: **ft**

53) Min Vert Clearance Over Bridge **99** ft **99** in
 54) Min Vert Under Clearance **N** Ref **0** ft **0** in
 55) Min Lat Under Clearance on Right **N** Ref **99.9** ft
 56) Min Lat Under Clearance on Left **0.0** ft

BRIDGE COMMENTS

CLASSIFICATION

112) NBIS Bridge Length	Yes	
104) Highway System	0 Off System	
26) Functional Class	9 Rural Local	
100) Defense Highway	0 Not Defense Highway	
101) Parallel Structure	N No parallel structure exists	
102) Direction of Traffic	2 2-way traffic	
103) Temporary Structure		
110) Designated National Network	0 Not on national network	
20) Toll	3 On Free Road	
21) Maintain	3 Town or Township Highway Agency	
22) Owner	3 Town or Township Highway Agency	
Report Class	L LOCAL	
37) Historical Significance	5 Bridge is not eligible for National Register	

WATERWAY

DrainageBasinCode	3503	
38) Navigation Control	0 No navigation control on waterway	
39) Navigation Vert Clr.	0	
116) Vert-Lift Brg Nav Min		
111) Pier Abutment Protection		
40) Navigation Horiz Clr.	0	

PROPOSED IMPROVEMENTS

75A) Type of Work Proposed		
75B) Work Done By		
76) Length of Struct. Improvement		ft
94) Bridge Improvement Cost	\$	
95) Roadway Improvement Cost	\$	
96) Total Project Cost	\$	
97) Year of Improvement Cost Est.		
114) Future ADT		115) Year Future ADT
List No.	Project No.	Advised

POSTED SIGNS & UTILITIES

Other Posted Signs 1		
Other Posted Signs 2		
Actual P.L. Single Unit Truck	tons	Actual P.L. 4Axle Truck
Rec. P.L. Single Unit Truck	tons	Rec. P.L. 4Axle Truck
Actual P.L. Semi-Trailer Truck	tons	Actual P.L. 3S2 Truck
Rec. P.L. Semi-Trailer Truck	tons	Rec. P.L. 3S2 Truck
Rec. P.L. All Vehicles	tons	Actual P.L. All Vehicles
Posted Vert Clearance On Bridge	ft in	
Posted Vert Under Clearance	ft in	
Posted Speed Limit	mph	
Utility		

STRUCTURE EVALUATION

SHEET 2 OF 2 FORM BRI-19 REV 10/00

SHEET ____ OF ____ (INSP. REPORT)

Bridge Number	04751	NBIS Length	
Town Name	PLAINFIELD	Yes	30
Facility Carried	STERLING HILL ROAD		
Feature Crossed	EKONK BROOK		

Inspected By: _____ & _____

LOAD RATING AND POSTING

31) Design Load	0		Evaluation Code	L	
63) Operating Rating Type	1		Year of Evaluation	2002	
64) Operating Rating	53.5		70) Bridge Posting	5	
65) Inventory Rating Type	2		41) Structure Status	A	
66) Inventory Rating	34.5		Open, no restriction		

CONDITION

	Rating	By
58) Deck	6	
59) Superstructure	5	
60) Substructure	4	
61) Channel & Chan. Protection	7	
62) Culverts	N	

APPRAISALS

	Rating	By
67) Structure Evaluation	4	
68) Deck Geometry	3	
69) Under Clear Vert & Horiz	N	
71) Waterway Adequacy	5	
72) Approach Rdwy Alignment	6	
113) Scour Critical	3	

Items 58 Thru 72 Checked By: _____

36) Traffic Safety Features:

A) Bridge Railings	1	
B) Transitions	0	
C) Approach Guardrail	0	
D) Approach Guardrail End	0	

OTHER FEATURES

Fence Required	No		Barrel Ladder	No	
Fence Present	No		Stand Pipes	No	
Fence Height	0.0 ft		Cat Walks	No	
Fence Type			Movable Inspection System	No	
Fence Material			Loose Concrete Checked?	Yes	
Fence Top Type					

INSPECTION COMMENTS

Proposed Next Indepth Insp Year	2012	
Senior Supervisor	carlsondm	
	kozlowskijc	

REVIEWED BY: _____ Date _____

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: 04751

INSPECTION DATE: 5/4/2004

INSPECTION TYPE: Routine **PREVIOUS INSPECTION DATE:** 4/8/2002 **SNOOPER REQUIRED:** No
INSPECTION PERFORMED BY: Team 3 **SNOOPER USED:** No

TOWN: PLAINFIELD **FEATURE CARRIED:** STERLING HILL ROAD **YEAR BUILT:** 1950
LOCATION: 575 FT EAST OF GENDRON **FEATURE INTERSECTED:** EKONK BROOK **YEAR REBUILT:** 0
MAIN MATERIAL: Steel **MAIN DESIGN:** Stringer/Multi-beam or Gird

INSPECTION VISITS: **INSPECTORS:**
Inspection Date: 5/4/2004 **Start Time:** 12:30 PM **Inspector:** D. Willis **Task:** INSPECTION
Temperature: °F **End Time:** 2:00 PM **Inspector:** T. Kahak **Task:** INSPECTION

58. DECK **OVERALL RATING** 7

	RATING	
OVERLAY	7	BITUMINOUS CONCRETE - HAIR/SAND BUILD-UP AT SHOULDERS. INE TRANSVERSE AND LONGITUDINAL CRACKS. OVERLAY DOESN'T EXTEND TO SHOULDERS. SAND BUILD-UP AT SHOULDERS.
DECK STR. CONDITION	7	GALVANIZED METAL BRIDGE PLANKING - SMALL AREAS OF SPOTTY RUST. SINGLE METAL BEAM RAIL WITH H-BEAM POSTS AND CHANNEL IRON CAP - MINOR PAINT PEELING WITH RUST BLEEDING THROUGH. METAL BEAM RAIL EXTENDS ACROSS STRUCTURE. STAND-OFF AT THE SOUTHEAST CORNER HAS 100% SECTION LOSS AREA AT THE BOTTOM OF THE WEB.
CURBS	N	
MEDIAN	N	
SIDEWALKS	N	
PARAPET	N	
RAILING	7	NO SAW CUTS AT DECK ENDS. HAIRLINE TRANSVERSE CRACKS AT DECK ENDS. OPEN 1/4" +/-.
PAINT	N	
FENCE	 	
DRAINS	N	
LIGHTING STANDARD	N	
UTILITIES TYPE/SIZE	N	
CONSTRUCTION JOINTS	N	
EXPANSION JOINTS	7	

59. SUPERSTRUCTURE **OVERALL RATING** 6

	RATING	
BEARING DEVICES	6	STEEL PLATES, ENCASED IN CONCRETE BLOCKS. MEDIUM TO HEAVY RUST TO SPOTTY HEAVY LAMINATING RUST ON EXPOSED AREAS.
STRINGERS	6	8 BEAMS BOTTOM FLANGES AND WEBS AT BOTH ABUTMENTS HAVE HEAVY LAMINATING RUST WITH SECTION LOSS. WORST AREA, BEAM # 8 ABUTMENT # 2 HAS 3/8" +/- SECTION LOSS AT BOTTOM FLANGE AND BEAM # 1 ABUTMENT # 1 BOTTOM FLANGE WITH UP TO 1/8" +/- SECTION LOSS. AREAS OF HEAVY LAMINATED RUST AND SECTION LOSS IN STIFFENERS IN TOP FLANGES THRU-OUT. WORST AREAS OVER ABUTMENTS. SEE SKETCH FOR SECTION LOSS AMOUNTS.
GIRDERS	N	
FLOOR BEAMS	N	

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: 04751

INSPECTION DATE: 5/4/2004

59. SUPERSTRUCTURE		OVERALL RATING 6
TRUSSES-GENERAL	N	
TRUSSES-PORTALS	N	
TRUSSES-BRACING	N	
PAINT	5	SEE ABOVE ITEMS. REMAINING STEEL HAS MEDIUM TO HEAVY RUST THROUGHOUT WITH PAINT PEELING. SPOTTY HEAVY LAMINATING RUST WITH 1/8"+/- PITTING TYPE SECTION LOSS ON TOP FLANGES ON BEAMS #3 #4 #5 AT MIDSPAN.
RUST	5	SEE ABOVE ITEMS.
MACHINERY MOV SPAN	N	
RIVETS & BOLTS	6	MEDIUM TO HEAVY RUST ON BOLTS AND NUTS FOR DIAPHRAGMS.
WELDS & CRACKS	8	
TIMBER DECAY	N	
CONCRETE CRACKING	N	
COLLISION DAMAGE	8	
MEMBER ALIGNMENT	8	
DEFLECT. UNDER LOAD	N	
VIBR. UNDER LOAD	N	
STAND PIPES		
BARREL LADDERS		

ARE BARREL LADDERS OSHA COMPLIANT?

60. SUBSTRUCTURE		OVERALL RATING 4
	<small>RATING</small>	
ABUTMENTS-STEM	4	MASONRY - FILLER STONE VOIDS ON BOTH ABUTMENTS AT WATERLINE. RULER CAN BE EXTENDED UP TO 26"+/-.
ABUTMENTS-BACKWALL	4	CONCRETE BLOCKS ON ABUTMENT CAPS, CRACKING WITH SOME HOLLOW AREAS UNDR BEAMS # 1 AND # 4 AND # 5 AT ABUTMENT # 1 AND BEAMS # 2 AND # 5 AND # 8 AT ABUTMENT # 2. (SEE ITEM 60-4).
ABUTMENTS-FOOTINGS	N	NOT VISIBLE.
ABUT.-SETTLEMENT	8	
ABUTMENTS-WINGWALLS	6	MASONRY - LARGE STONE VOIDS AND SOME STONE MOVEMENT AT ALL WINGS.
PIERS/BENTS-CAPS	N	
PIERS/BENTS-PILE BENT	N	
PIERS/BENTS-COLUMN	N	
PIERS/BENTS-FOOTINGS	N	
PIERS/BENTS-SETTLEMENT	N	
EROSION-SCOUR	8	
CONCRETE CRACK-SPALL	4	LARGE SURFACE SPALL IN CONCRETE BLOCK BACKWALL AT ABUTMENT # 1, BEAM # 5 - 7-1/2" HIGH X 6" WIDE X 8" DEEP WIT BOTTOM OF BEARING PLATE EXPOSED. POTENTIAL SPALL AT BEAM # 4 AT ABUTMENT # 1. ADJACENT BLOCKS HOLLOW. SPALL AREA UNDER BEAM # 1 AT ABUTMENT # 2, 8-1/2" LONG x 6" HIGH X 4" DEEP WITH

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

BRIDGE #: 04751

INSPECTION DATE: 5/4/2004

60. SUBSTRUCTURE		OVERALL RATING 4
	BEARING PLATE EXPOSED. SEE PHOTO.	
STEEL CORROSION	N	
PAIN	N	
TIMBER DECAY	N	
COLLISION DAMAGE	8	
DEBRIS	N	

61. CHANNEL PROTECTION		OVERALL RATING 7
	RATING	
CHANNEL SCOUR	7	MINOR AT ABUTMENTS.
EMBANKMENT EROSION	7	MINOR UNDERCUTTING UP AND DOWN STREAM.
DEBRIS	7	EARTH BUILD-UP SOUTH.
VEGETATION	7	GROWTH ALONG BROOK AND SURROUNDING STRUCTURE.
CHANNEL CHANGE	8	
FENDER SYSTEM	N	
SPUR DIKES & JETTIES	N	
RIP RAP	N	

62. CULVERTS & RETAINING WALL		OVERALL RATING N
------------------------------------------	--	-------------------------------------------------------------------------------------

APPROACH CONDITION		OVERALL RATING 6
	RATING	
APPROACH SLAB	N	
RELIEF JOINTS	N	
APPROACH GUIDE RAIL	7	METAL BEAM RAIL WITH TERMINAL ENDS - RAILS EXTEND ACROSS STRUCTURE.
APPROACH PAVEMENT	7	OVER-LAY. HAIRLINE TRANSVERSE AND LONGITUDINAL CRACKS. BITUMINOUS PATCHED AREA AND DEPRESSION AREA AT THE NORTHWEST CORNER.
APPROACH EMBANKMENT	6	EROSION NORTHWEST AND NORTHEAST.
TRAFFIC SAFETY FEATURES:		
BRIDGE RAILINGS	1	
TRANSITIONS	0	
APPROACH GUARDRAILS	0	
APPR. GUARDRAIL ENDS	0	

LOAD POSTING	
SINGLE UNIT (TONS)	
HS (TONS)	
4 AXLE (TONS)	
3S2 (TONS)	

Connecticut Department of Transportation
Bridge Inspection Report BRI-18

BRIDGE #: 04751

INSPECTION DATE: 5/4/2004

ADVANCE WARNING Y/N N _____
LEGIBILITY N _____
VISIBILITY/LOCATION N _____

MISC.

MIN VERT. UNDERCLR. 0' 0" _____
POSTED CLR. UNDER BRIDGE ' " _____
POSTED CLR. ON BRIDGE ' " _____
ADVANCE WARNING (Y/N) N _____
SPEED LIMIT (IF ANY) MPH _____
CHARACTER OF TRAFFIC LIGHT VOLUME/CARS AND HEAVY TRUCKS. TRUE DIRECTION WEST TO EAST.

ADDITIONAL NOTES

ADDITIONAL COMMENTS:

Inspectors' Signatures: 1) _____ Date: __/__/__
2) _____ Date: __/__/__
3) _____ Date: __/__/__
4) _____ Date: __/__/__
P.E. Signature: _____ Date: __/__/__
P.E.#: _____
Reviewed by: _____ CDOT Date: __/__/__

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	



Photo # 1: Bridge and west approach



Photo # 2: Typical top of deck

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	



Photo # 3: Typical condition of the overlay. Note up to 1/2" cracking of bituminous



Photo # 4: Bridge and east approach

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	




Photo # 5: Channel upstream



Photo # 6: Channel downstream

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	



Photo # 7: Typical railing configuration



Photo # 8: North elevation

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	



Photo # 9: Roadway erosion at southwest corner




Photo # 10: West abutment

Bridge No.:	04751	Inspected by:	Victor Luzhanskiy
Town:	Plainfield, Ct.	Inspected by:	Jagdeesh Gopal
Feature Carried:	Sterling Hill Rd	Date Inspected:	April 23, 2008
Feature Crossed:	Ekonk Brook	Project No.:	



Photo # 11: Typical underside of deck



Photo # 12: South elevation