

Michael W. Klemens, LLC  
POB 432  
Falls Village, CT 06031  
October 20, 2015

Melanie Bachman  
Acting Executive Director  
CT Siting Council  
[Via Email to Siting.Council@CT.gov](mailto:Siting.Council@CT.gov)

Dear Ms. Bachman:

Please find enclosed the one hundred and first bi weekly third party environmental monitoring reports prepared by Lenard Engineering for the Colebrook South Site Wind Turbine Site (Petition 983). The areas that have been cleared have been done in accordance with the plans and conform to the conservation plan for the protection of the cryptic vernal pools documented within Wetland One. We are continuing our bi-weekly monitoring of site conditions. If you require additional information, please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael W. Klemens". The signature is fluid and cursive, with the first name "Michael" and last name "Klemens" clearly distinguishable.

Michael W. Klemens, PhD  
860-824-8185 (land)  
203-448-8068 (mobile)



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** October 20, 2015  
**Re:** BNE Wind Colebrook South

---

Attached are CT Siting Council environmental erosion and sediment control monitoring reports numbers 231 and 232 for the period Oct 3, 2015 thru October 16, 2015.

No problems observed.

CC Greg Zupkus, BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	<b>231</b>
Date of Inspection:	October 8, 2015	Start / End Time:	8:30AM to 10:30AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly. Siltation on site but none off site  Towers 1 & 2 have been completed but are not on line yet Site grading, top soiling and hydroseeding of disturbed areas is being undertaken		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time                  Storm Duration                  Approximate Rainfall			
Weather at time of this inspection? 50°F    Sunny light cloudst			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983 CT GSN 002270	Report No.	<b>232</b>
Date of Inspection:	October 14, 2015	Start / End Time:	5:00PM to 5:30PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Sediment and Erosion controls in place and functioning properly. Siltation on site but none off site  Towers 1 & 2 have been completed but are not on line yet Site grading, top soiling and hydroseeding of most of the disturbed areas has been completed.		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time                  Storm Duration                  Approximate Rainfall			
Weather at time of this inspection? 57°F    Clear light clouds			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site: -.			