



APPROXIMATE EDGE OF PROPERTY

DRIVEWAY



3

4




1

ENCLOSED PORCH

FIRST & SECOND FLOOR

BEDROOM

2



FIRST FLOOR
SCALE 1" = 4'



PHOTO 1
(CHIMNEY PIT)
(N.T.S.)

INTERIOR WORK NOTES

- 1 INSPECT CHIMNEY AND CLEAN CHIMNEY PIT
- 2 WATER DAMAGED WOOD PANELING IN FIRST FLOOR BEDROOM. REPAIR ACCORDING TO CONTRACT DOCUMENTS.

EXTERIOR WORK NOTES

- 3 DAMAGED STORM WINDOWS TO BE REPAIRED. REPAIR ACCORDING TO CONTRACT DOCUMENTS
- 4 DAMAGED FASCIA BOARD AND MISSING GUTTERS. REPAIR AND REPLACE ACCORDING TO CONTRACT DOCUMENTS
- 5 DAMAGED WINDOW. REPAIR ACCORDING TO CONTRACT DOCUMENTS



PHOTO 2
(BEDROOM WATER STAINS ON CEILING)
(N.T.S.)



PHOTO 3
(DAMAGED STORM WINDOW TRIM AND ROOF LINE FASCIA)
(N.T.S.)



PHOTO 4
(DAMAGED FASCIA BOARD & MISSING GUTTER)
(N.T.S.)



PHOTO 5
(DAMAGED BASEMENT WINDOW)
(N.T.S.)



1084 Cromwell Avenue, Suite A-2
Rocky Hill, CT 06067
Telephone: (860) 436-4364
Fax: (860) 436-4626
www.martinezcouch.com

PROJECT 1811 - 17 KOSSUTH STREET,
NORWALK, CONNECTICUT 06854

REV5			
REV4			
REV3			
REV2			
REV1			
DRAWN BY: DCK		CHECKED BY: MR	SCALE: 1"=4'
		DATE:	06/26/2014

SCHEMATIC

FIRST FLOOR LAYOUT

JOB NO.	DRAWING NUMBER	SHEET
33-262-1811	BASEMAP 33-262--1811.dwg	A-1.0