

Photo 1 – Outdoor Air Shaft



Photo 2 – Disintegrating Liner Top
Outdoor Air Shaft

Photo 3 – Disintegrating Liner Top
Outdoor Air Shaft

Photo 4 – Disintegrating Liner Top
Outdoor Air Shaft

Photo 5 – Disintegrating Fiberglass
Liner – Rooftop

Photo 6 – Disintegrating Fiberglass
Liner – Rooftop

Photo 7 – Disintegrating Fiberglass Liner – Rooftop

Photo 8 – Sixth Floor North Top of Fan Box

Photo 9 – Sixth Floor South Top of Fan Box

Photo 10 – Room 601 VAV Return Plenum

Photo 11 – Room 601 Overall VAV Unit

Photo 12 – Room 601 Stain on Ceiling

Photo 13 – VAV-1 Ductboard

Photo 14 – Tenth Floor North Minimum Outside Air Duct

Photo 15 – Tenth Floor North Outside Air Chase

Photo 16 – Cochrane Ventilation

Photo 17 – Tenth Floor North Stain On CHW Pipe Insulation

Photo 18 – Tenth Floor South Top of Fan Box

Photo 19 – Tenth Floor South
Drain Pan



Photo 20 – Twelfth Floor VAV-38
Ductboard

Photo 21 – Seventeenth Floor North
Top of Fan Box

Photo 22 – Seventeenth Floor North
Top of Fan Box

Photo 23 – Seventeenth Floor North
Insulation @ Top of Coil Section

Photo 24 – Seventeenth Floor North
Insulation on Side of Fan Section

Photo 25 – Seventeenth Floor South
Top of Fan Box

Photo 26 – Seventeenth Floor South
Top of Fan Box

Photo 27 – Seventeenth Floor South
Side of Fan Box

Photo 28 – Seventeenth Floor Ionizers
on Desk

Photo 29 – Seventeenth Floor Ionizers
on Desk

Photo 30 – Bubbling Paint - Conference
Room 1713

Photo 31 – Office
Seventeenth Floor

Photo 32 – Active Leak in
Office – Eighteenth Floor

Photo 33 – Active Leak in
Office – Eighteenth Floor

Photo 34 – Eighteenth Floor North
Top of Fan Box



Photo 35 – Eighteenth Floor South
Top of Fan Box

Photo 36 – Eighteenth Floor North Internal
Duct Insulation

Photo 37 – Return Carbon Dioxide Sensor

Photo 38 – Stain on Wallboard in Mechanical Room