Route 2/2A/32
Environmental Impact Statement

Typical Busway Cross Section

Figure 2.2-22