Route 2/2A/32
Environmental Impact Statement

Typical Light Rail Cross Section

Figure 2.2-9