Route 2/2A/32
Environmental Impact Statement

1993-1995 Accident Trends

Figure 1.4-2

Legend

- ConnDOT's Suggested List of Surveillance Study Sites (SLOSSS)
- Actual Accident Rate is Greater than the Expected Accident Rate