



**Northeast
Utilities System**

107 Selden Street, Berlin CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(860) 665-5000

February 16, 2006

Ms. Pamela B. Katz
Chairman
Connecticut Siting Council
10 Franklin Square
New Britain, CT 06051

Re: Docket No. CSC 272 - D&M Plans - Segment 4a

Dear Ms. Katz:

This letter provides the response to requests for the information listed below.

Response to CSC-04 Interrogatories dated 02/02/2006
D&M - 009 *, 012

Very truly yours,

Anne Bartosewicz
Project Director
Transmission Business
NUSCO
As Agent for CL&P

AB/tms
cc: Service List

* Due to the bulk nature of this material, copies are being provided to the CSC only.

**The Connecticut Light and Power Company
Docket No. D&M Plans**

**Data Request CSC-04
Dated: 02/02/2006
Q- D&M-009
Page 1 of 1**

**Witness: NO WITNESS
Request from: Connecticut Siting Council**

Question:

Explain the over/under installation between station number 504 and 505.

Response:

In the Segment 4a D&M Plan, the duct bank is shown going under the sanitary sewer at Station 504+65 and over the sanitary sewer at Station 505+20 to maintain clearance. Due to the results of recently completed vacuum excavations of the utilities to verify their depths and dimensions, CL&P has determined that adequate clearance exists for the duct bank to traverse over the sanitary sewers at both station number 504+65 and 505+20. Attached as bulk* is the revised Plan and Profile drawing number 01224-10001, pg. 071, reflecting this change.

* Due to the bulk nature of this material, copies are being provided to the CSC only.

**The Connecticut Light and Power Company
Docket No. D&M Plans**

**Data Request CSC-04
Dated: 02/02/2006
Q- D&M-012
Page 1 of 1**

**Witness: NO WITNESS
Request from: Connecticut Siting Council**

Question:

Could vaults located at station numbers 806-8 07 in a church parking be lot moved to station number 803? If not, explain.

Response:

The vaults can not be relocated to Station 803 due to cable-length limitations of cable reels and limits on cable pulling tensions that would be exceeded.