

STATE BUILDING CODE INTERPRETATION NO. I-02-11

January 21, 2011

The following is being offered in response to your email request dated January 14, 2011 in which you seek an official code interpretation. Your question inquiry was *“whether or not a product identified as “BL1” is deemed hazardous”*. I am not authorized to make such a determination and, therefore, respectfully decline to do so.

Additionally, the associated information submitted was lacking sufficient detail to determine code compliance with Section 414.0 and Table 307.7(1), of the 2003 International Building Code portion of the 2005 State Building Code. Please have the manufacturer indicate compliance with these sections.