

Site ID	BCG02 (792N)
Sample ID	1235131106-BCG02
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	No Fill Observed
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BC02 (790N)
Sample ID	1235131107-BC02
Soil Characterization	Clean
Boring Depth (ft bg)	30
Fill Depth (ft bg)	No Fill Observed
Groundwater Treatment	No Treatment Required
Depth to Water (ft bg)	13.09
Qualitative Recharge	Medium-High

Site ID	BCG03 (793N)
Sample ID	1235131224-BCG03
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	9
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BCG01 (788N)
Sample ID	472131031-BCG01
Soil Characterization	Clean
Boring Depth (ft bg)	30
Fill Depth (ft bg)	13.75
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BCG28 (793S)
Sample ID	1235140109-BCG28
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	No Fill Observed
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BC01 (786N)
Sample ID	1235131108-BC01
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	13.5
Groundwater Treatment	Treatment Required
Depth to Water (ft bg)	12.55
Qualitative Recharge	Low

Site ID	BCG27 (791S)
Sample ID	1235131213-BCG27
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	9
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BC14 (792S)
Sample ID	1235131220-BC14
Soil Characterization	Contaminated
Boring Depth (ft bg)	30
Fill Depth (ft bg)	2
Groundwater Treatment	Treatment Required
Depth to Water (ft bg)	9.42
Qualitative Recharge	Medium-High

Site ID	BC13 (786S)
Sample ID	472131031-BC13
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	5
Groundwater Treatment	No Treatment Required
Depth to Water (ft bg)	11.41
Qualitative Recharge	Medium-High

Site ID	BCG25 (788S)
Sample ID	1195140109-BCG25
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	No Fill Observed
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

Site ID	BCG26 (789S)
Sample ID	1235140109-BCG26
Soil Characterization	Polluted
Boring Depth (ft bg)	30
Fill Depth (ft bg)	No Fill Observed
Groundwater Treatment	
Depth to Water (ft bg)	NA
Qualitative Recharge	

No.	DATE	DESCRIPTION	DESIGNER	REVIEWER
1.			XX/XX	XX

LEGEND

SOIL BORING LOCATION

NOTES:
BASEMAP – 2012 AERIAL PHOTOGRAPH FROM CTECO WEBSITE

SCALE:
HORZ.: 1" = 400'
VERT.:
DATUM:
HORZ.:
VERT.:
0 200 400
GRAPHIC SCALE

FUSS & O'NEILL
56 QUARRY ROAD
TRUMBULL, CONNECTICUT 06611
203.374.3748
www.fando.com

UNITED ILLUMINATING COMPANY

BAIRD-CONGRESS

BRIDGEPORT, CONNECTICUT

PROJ. No.: 20131010A10
DATE: AUGUST 2014

FIGURE 1
APPENDIX A

File Path: J:\DWG\P2013\10\10A10\Environmental\Plan\20131010A10_SAM03.dwg Layout: 11X17-L_DWG TO PDF Plotted: Wed, August 06, 2014 - 11:13 AM User: kferris
MS VIEW: LAYER STATE:
Plotter: DWG TO PDF.PC3 CTB File: FO HALF.STB