



STATE OF CONNECTICUT
CONNECTICUT SITING COUNCIL

Ten Franklin Square, New Britain, CT 06051

Phone: (860) 827-2935 Fax: (860) 827-2950

E-Mail: siting.council@ct.gov

www.ct.gov/csc

April 12, 2016

TO: James J. Murphy, Jr.

FROM: Melanie Bachman, Acting Executive Director *MAB*

RE: **PETITION NO. 1221** - Windham Solar LLC petition for a declaratory ruling that no Certificate of Environmental Compatibility and Public Need is required for the proposed construction, maintenance and operation of two 1.0 Megawatt and one 1.5 Megawatt Solar Photovoltaic Electric Generating facilities located at 91 Plainfield Pike Road, Plainfield, Connecticut.

The Connecticut Siting Council has scheduled a field inspection for Wednesday, April 20, 2016 at 1:30 p.m. to review this petition. Interested parties should meet at the existing access drive off of Plainfield Pike Road (Route 14A). See attached Google Earth Photo. Boots are suggested.

MB/MP

c: Secretary of the State (via e-mail service)
Honorable Paul E. Sweet, First Selectman, Town of Plainfield
Ryan Brais, Zoning Officer, Town of Plainfield
Lou Soja, Planning and Engineering, Town of Plainfield
Steve Broyer, Windham Solar LLC, c/o Ecos Energy LLC
Michael Melone, Windham Solar LLC, c/o Allco Renewable Energy Limited
Leo Properties LLC, 93 High Street, Moosup, CT 06354

Directions to Site from New Britain

1. Take Route 71 North to Route 9 South.
2. Take Route 9 South to Interstate 91 North.
3. Take I-91 North to Exit 25 (Route 3 North).
4. Take Route 3 North to Route 2 East.
5. Take Route 2 East to Norwich area.
6. Take Exit 28N (I-395 N) off of Route 2 East.
7. Proceed on I-395 N.
8. Take Exit 29 (Route 14A towards Plainfield/Oneco) off of I-395 N.
9. At the end of the exit ramp, turn right onto Route 14A (Plainfield Pike Road).
10. Proceed on Route 14A for about 0.45 miles.
11. Turn right onto the existing access drive as noted in the attached Google Earth photo.

Directions to (Plainfield) Site from Griswold Site (Petition No. 1220)

1. Proceed west on Route 138 (Voluntown Road) for about 3.8 miles towards I-395.
2. Turn right to merge onto I-395 N.
3. Proceed on I-395 N for about 5.6 miles.
4. Take Exit 29 (Route 14A towards Plainfield/Oneco) off of I-395 N.
5. At the end of the exit ramp, turn right onto Route 14A (Plainfield Pike Road).
6. Proceed on Route 14A for about 0.45 miles.
7. Turn right onto the existing access drive as noted in the attached Google Earth photo.

