

**PUBLIC WATER SYSTEMS VIOLATION REPORT
CONNECTICUT DEPARTMENT OF PUBLIC HEALTH
WATER SUPPLIES SECTION
TABLE C**

**TREATMENT TECHNIQUE VIOLATIONS
CALENDAR YEAR 2001**

SURFACE WATER TREATMENT RULE (SWTR)

FAILURE TO PROVIDE FILTRATION

PUBLIC WATER SYSTEM	PWS-ID	TOWN	PWS TYPE	POPULATION SERVED	STATUS
Portland Water Department	CT1130011	Portland	C	8,270	In Compliance (Source of supply has been replaced)
BHC - Ridgefield System	CT1180011	Ridgefield	C	6,804	In Compliance (Source of supply has been replaced)

LEAD AND COPPER RULE (LCR)

FAILURE TO COMPLETE LEAD EDUCATION

PUBLIC WATER SYSTEM	PWS-ID	TOWN	PWS TYPE	POPULATION SERVED	STATUS
East Hampton Mall (The Hamilton Company)	CT0420042	East Hampton	NTNC	100	Out of Compliance
North Madison Congregational Church	CT0769143	Madison	NTNC	29	Returned to Compliance
Brookside Professional Centre	CT1341172	Stafford	NTNC	25	Returned to Compliance
Voluntown Elementary School	CT1479013	Voluntown	NTNC	365	Returned to Compliance

FAILURE TO INSTALL OPTIMAL CORROSION CONTROL TREATMENT

PUBLIC WATER SYSTEM	PWS-ID	TOWN	PWS TYPE	POPULATION SERVED	STATUS
Fairfield Hills	CT0970021	Newtown	C	2,230	Returned to Compliance
Cook-Willow Realty	CT1110111	Plymouth	C	85	Returned to Compliance; No longer a public water system

C - COMMUNITY

NTNC - NONTRANSIENT NONCOMMUNITY