



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut  
**Date:** June 28, 2012  
**Re:** Wind Colebrook South

*Roger Hurlbut*

---

Attached are environmental erosion and sediment control monitoring reports numbers 33 and 34 for the period June 16 through June 29, 2012.

Report #33 was for a normal weekly inspection and # 34 was for an inspection after a short but relatively intense thunderstorm . No problems or discharges were observed.

CC C Jones Civil 1  
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>33</b>
Date of Inspection:	June 21, 2012	Start / End Time:	8:00AM to 9:00AM
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work has occurred since last inspection on 6/13/12 No precipitation since last inspection on 6/13/12 No problems observed		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time:      Storm Duration (hrs):      Approximate Rainfall (in):			
Weather at time of this inspection? sunny light breeze 76° F			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>34</b>
Date of Inspection:	June 26, 2012	Start / End Time:	7:00AM to 8:00AM
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work has occurred since last inspection on 6/21/12 No problems observed		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time: 6/25/12 – 7AM    Storm Duration (hrs): 1.5 hrs    Approximate Rainfall (in): 0.5			
Weather at time of this inspection? 55° F, Pt Cloudy, Breezy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			