



Memorandum

To: Dr. Michael Klemens
From: Todd Parsons 
Date: July 12, 2012
Re: Wind Colebrook South


Roger is on vacation until July 25. I will be conducting the inspections during his absence.

Attached are environmental erosion and sediment control monitoring reports numbers 35 and 36 for the period June 30 through July 14, 2012.

Report #35 was after a small rainstorm and Report #36 was for a normal weekly inspection. No problems or discharges were observed.

CC C Jones Civil 1
G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	35
Date of Inspection:	July 2, 2012	Start / End Time:	12.45 PM to 1:15 PM
Inspector's Name(s):	Roger Hurlbut <i>Roger Hurlbut</i>		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work has occurred since last inspection on 6/26/12 No problems observed		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time: 7/1/12 2:15 Storm Duration (hrs): 1.5 hrs Approximate Rainfall (in): 0.5			
Weather at time of this inspection? 77° F, Pt Cloudy, Breezy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	36
Date of Inspection:	July 12, 2012	Start / End Time:	1:30 PM to 2:30 PM
Inspector's Name(s):	Todd Parsons 		
Inspector's Title(s):	Principal Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work has occurred since last inspection on 7/2/12 No problems observed Silt fence should be installed in the area of Flags 445-450.		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall (in):			
Weather at time of this inspection? 90° F, Sunny			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			