



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: February 7, 2013
Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 73 and 74 for the period Jan 28 thru Feb 8.

The ground is frozen

CC G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	73
Date of Inspection:	January 31, 2013	Start / End Time:	7:30 AM to 8:00AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	Warm Temps & rain have melted most of the snow cover No work		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time: 1-31-13 12AM Storm Duration (hrs): 8 Approximate Rainfall: 0.7in			
Weather at time of this inspection? 45° F, overcast light drizzle			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	74
Date of Inspection:	February 7, 2013	Start / End Time:	1:30 PM to 2:00 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work Ground is frozen		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide: Storm Start Date & Time: Storm Duration (hrs): Approximate Rainfall:			
Weather at time of this inspection? 28° F, Sunny light clouds			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			