



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** April 5, 2013  
**Re:** BNE Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 81 and 82 for the period March 23 thru April 5, 2013.

No problems observed Most of the snow will probably be gone after this weekend

CC G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>81</b>
Date of Inspection:	March 29, 2013	Start / End Time:	7:30 AM to 8:15 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work Unvegetated portions of the site still have 50% snow cover -		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide: Storm Start Date & Time:                      Storm Duration (hrs):                      Approximate Rainfall:			
Weather at time of this inspection? 30° F, sunny, light breeze			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>82</b>
Date of Inspection:	April 1, 2013	Start / End Time:	4:30 PM to 5:00 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off		
Describe present phase of construction:	No work Unvegetated portions of the site still have some snow cover -		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time: 3/29 11PM    Storm Duration (hrs): 2.75    Approximate Rainfall: 0.14-in			
Weather at time of this inspection? 36° F, overcast, snow			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			