



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: May 30, 2014
Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 150 and 151 for the period May 17 thru May 30, 2014.

No runoff occurred as a result of the recent rain events.

CC G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	150
Date of Inspection:	May 23, 2014	Start / End Time:	7:30 AM to 8:00 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off ice		
Describe present phase of construction:	No work on site		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 5/22/14 10:45 AM Storm Duration (hrs):9Hrs Approximate Rainfall: 0.78			
Weather at time of this inspection? 56° Overcast			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	151
Date of Inspection:	May 29, 2014	Start / End Time:	12:30 PM to 1:00 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 off ice		
Describe present phase of construction:	No work on site		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 5/29/14 8:43AM Storm Duration (hrs):0.5Hrs Approximate Rainfall: 0.04			
Weather at time of this inspection? 63° Sunny clear			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			