



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: July 28, 2014
Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 158 and 159 for the period July 13 thru July 26, 2014

No work on site & areas are stable

CC G Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	158
Date of Inspection:	July 15, 2014	Start / End Time:	6:30PM to 7:00 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 7/13/14 8:00 PM Storm Duration (hrs): 11+/- Approximate Rainfall: 1.40-in			
Weather at time of this inspection? 76° Overcast			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	159
Date of Inspection:	July 26, 2014	Start / End Time:	12:00PM to 12:30 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If yes, provide: Storm Start Date & Time 7/23/14 8:00 PM Storm Duration (hrs): 1.5+/- Approximate Rainfall: >0.60-in			
Weather at time of this inspection? 74° Clear			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			