



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: Nov 26, 2014
Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 177 and 178 for the period Nov 15, 2014 thru Nov 28, 2014

No work on site & areas are stable

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	177
Date of Inspection:	Nov 17, 2014	Start / End Time:	7:30Am to 8:00AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 11-17-14 2:54 Storm Duration 17 Hrs Approximate Rainfall: >1.0-in			
Weather at time of this inspection? 32° Overcast/light rain			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	178
Date of Inspection:	Nov 24, 2014	Start / End Time:	7:30Am to 8:00AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input checked="" type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 11-24-14 3:12 AM Storm Duration 6 Hrs Approximate Rainfall: >0.79-in			
Weather at time of this inspection? 55°F Overcast/light rain			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			