



Memorandum

To: Dr. Michael Klemens
From: Roger Hurlbut *Roger Hurlbut*
Date: February 6, 2015
Re: BNE Wind Colebrook South

Attached are environmental erosion and sediment control monitoring reports numbers 188 and 189 for the period Jan 23, 2015 thru Feb 6, 2015

No work on site, ground is frozen & snow covered.

CC Greg Zupkus BNE Energy

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	188
Date of Inspection:	Jan 30, 2015	Start / End Time:	4:30 PM to 5:00PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site Ground is frozen & snow covered		
Type of Inspection: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, provide: Storm Start Date & Time Storm Duration Approximate Rainfall			
Weather at time of this inspection? 25°F cldy			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	189
Date of Inspection:	February 6, 2015	Start / End Time:	7:15 AM to 7:45AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	No work on site Ground is frozen & snow covered 		
Type of Inspection:	<input checked="" type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event		
Weather Information			
Has it rained since the last inspection?			
<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, provide:			
Storm Start Date & Time	Storm Duration	Approximate Rainfall	
Weather at time of this inspection? 6°F Sunny			
Discharge Information (A)			
Do you suspect that discharges may have occurred since the last inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection?			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			