



## Memorandum

**To:** Dr. Michael Klemens  
**From:** Roger Hurlbut *Roger Hurlbut*  
**Date:** April 20, 2015  
**Re:** BNE Wind Colebrook South

---

Attached are environmental erosion and sediment control monitoring reports numbers 199 and 200 for the period April 4, 2015 thru April 18, 2015

Ryan Company has had Denovo mobilize equipment, widen & regrade the access road.

CC Greg Zupkus BNE Energy  
Sam McGriff Ryan Company

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>199</b>
Date of Inspection:	April 9, 2015	Start / End Time:	7:15 AM to 7:45 AM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Ground is thawing Conditions at site are stable		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 4/8/2015 9:30 PM    Storm Duration 4Hrs    Approximate Rainfall 0.8			
Weather at time of this inspection? 29°F overcast			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			

General Information			
Project Name:	Wind Colebrook South		
Location:	Winsted- Norfolk Road Colebrook, Connecticut		
CT DEP Tracking No.	CSC Petition 983	Report No.	<b>200</b>
Date of Inspection:	April 18, 2015	Start / End Time:	1:30 PM to 2:30 PM
Inspector's Name(s):	Roger Hurlbut		
Inspector's Title(s):	Project Engineer		
Inspector's Contact Information:	LENARD ENGINEERING INC 860 379-6669 office		
Describe present phase of construction:	Site development equipment has been mobilized Entry access has been widened and regraded.		
Type of Inspection: <input type="checkbox"/> Regular <input type="checkbox"/> Pre-storm event <input type="checkbox"/> During storm event <input checked="" type="checkbox"/> Post-storm event			
Weather Information			
Has it rained since the last inspection? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
If yes, provide: Storm Start Date & Time 4/17/2015 4AM    Storm Duration 6Hrs    Approximate Rainfall 0..14			
Weather at time of this inspection? 70°F sunny			
Discharge Information			
Do you suspect that discharges may have occurred since the last inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Are there any discharges at the time of inspection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
Describe location of any discharges from the site:			