

## Community Living Arrangement Inspection Report Summary

Glenbrook Road B

321 Glenbrook Road Stamford, CT 06906

R-1040-B

Abilis

Inspection Date: Tuesday, January 26, 2016

DDS Region: West

Inspection Type: Standard

### Inspection Report Citations Were Reported In The Following Regulatory Areas:

#### Regulatory Category

##### **17a-227-11 Physical Requirements**

11d Hazard prevention

11g Fire extinguishers

##### **17a-227-12 Emergency Planning**

12b Emergency response training/monthly fire drills

##### **17a-227-14 Staff Development**

14a Specified training requirements

14b1 Signs and symptoms training timeliness