

DEPARTMENT OF PUBLIC SAFETY
DIVISION OF STATE POLICE

NO. & TYPE OF VEHICLES INVOLVED 2 Car
(passenger car, truck, bus, etc.)

OTHER(S) INVOLVED _____
(pedestrian, pole, bridge abutment, etc.)

CASE NUMBER DPS04- 040043 DATE 08-12-04 TIME 0101 hours

TOWN Killingly ROUTE Killingly Ave TROOPER Sgt. Caulfield # 263

UTILITY POLE NAME & # CL&P # 413

UTILITY POLE NAME & # _____

OP #1 Mattioli, David, M AGE 07-07-74

OP #2 Aguire, Cano, Ernesto AGE 03-31-76

ADDRESS 55 Westcott Road

ADDRESS 1160 11th Ave

TOWN Danielson STATE CT 06239

TOWN Salem STATE OR 97303

OP. LIC. 197846815 STATE CT

OP. LIC. 9053251 STATE Oregon

OWNER #1 CT Dept. of Public Safety

OWNER #2 Same

ADDRESS 47 Mill Hill RD , Colchester, CT

ADDRESS Same

REG. 650 PKY STATE CT

REG. ZFL 902 STATE Oregon

MAKE AND TYPE VEH. Ford, Crown Vic, Silver 4dr YEAR 2000

MAKE AND TYPE VEH. Niss, Frontier PU, Red YEAR 1998

TOWED TO Main Street Auto / Troop D

TOWED TO Townline Auto/ Troop D

VIN: 2FAPP71W7YX208526

VIN: 1N6DD26S3WC310559

OCCUPANTS _____ AGE _____

OCCUPANTS _____ AGE _____

Safeco Insurance Co of Oregon

POL# P5227120

R/F Grajales Lara, Cruz (DOB 09-12-82)

1960 21st NE, Salem, OR 97303

* L/R Jacobo, Anuncion (DOB 03-11-72)

17 St. James Row #4, Danielson, CT 06239

OP #4 _____ AGE _____

ADDRESS _____

TOWN _____ STATE _____

OP. LIC. _____ STATE _____

OWNER #4 _____

ADDRESS _____

REG. _____ STATE _____

MAKE AND TYPE VEH. _____ YEAR _____

TOWED TO _____

OCCUPANTS _____ AGE _____

R/R Gonzalez, Julio Delvalle (DOB 02-11-72)

17A St. James Row, Danielson, CT 06239

Vehicle #1 (State Police vehicle operated by Trooper Matioli) traveling S/Bound on Gauthier Ave., approaching the intersection of Killingly Avenue. Vehicle #2 traveling W/Bound on Killingly Ave., approaching the intersection of Gauthier Avenue. Vehicle #2 failed to stop at a stop sign, continued into the intersection where vehicle #2 side impacted Vehicle #1. Vehicle #1 then continued into a telephone pole, spun upon impact, and came to rest in the yard of a residence. This vehicle sustained serious damage. Vehicle #2 rolled over and came to rest on its roof. This vehicle was also seriously damaged

Operator #1 was able to crawl from his vehicle and was transported to Backus Hospital with non-life threatening injuries, including a laceration to his head.

Operator #2 and two passengers were also transported via Ambulance for medical treatment. The Operator is currently at UMASS in serious condition. The right front passenger (Grasales) is at Backus Hospital in serious condition. The remaining two passengers received minor injuries.

This investigation will remain open and active, an accident reconstructionist was called to the scene.